

19K

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

AK
Veh In
LKIC

08/12/2019

Owner: AL'EMMA CORNER

Not Withain
61 Day 85900h
Recovery After Repair
6 days

ESTIMATE TO REPAIR TOYOTA HIACE - GBF1515U

1pc front RH door
2pcs front RH door hinge @\$90.70
1pc front RH door inner rubber
1pc front RH door inner lock
1pc front RH wheel top panel
1pc front RH door rear pillar
1pc front RH door rear pillar inner panel
1pc rear RH door
1pc rear RH door lower hinge
1pc rear RH door lower lock
1pc rear RH door auto motor
1pc rear RH door inner rubber
1pc rear RH door inner sensor rubber

R \$ 1,248.50 ✓
R \$ 181.40 X
R \$ 268.70 X
R \$ 381.50 X
R \$ 681.50 X
R \$ 891.50 ✓
R \$ 781.50 ✓
R \$ 1,718.50 ✓
R \$ 281.50 ✓
DIT \$ 395.20 ✓
DIT \$ 1,258.50 ✓
R \$ 278.50 ~~5000~~ X
R \$ 781.50 ✓

less 25%

\$ 9,148.30
\$ 2,287.08
\$ 6,861.23

remove sticker
ROC sticker

m s.nett \$ 380.00 800h
m s.nett \$ 80.00 255m

remove & refit front RH door glass
tuffkote
wiring
spray painting
labour charges
Total

\$ 120.00 ✓
\$ 150.00 901
\$ 150.00 201
\$ 1,200.00 8001
\$ 1,400.00 8001
\$ 10,341.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts provided are for information
- Third party involvement on "No Prejudice" basis
- No illegal or improper handling of work
- Supplies and materials are to be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature
Date

