

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021723/KGA3Q2

**Date:** 25/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994292

**Claimant**  
**Vehicle No :** SGP86K **Insured Vehicle No :** GBJ6146Y

Date of Loss: 06/12/2019 Nature of Claim: TP Claim No: 4421041845SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGP86K</b>		
Make & Model:	TOYOTA ESTIMA AERAS, 2.4 PREMIUM (A)	Engine No:	2AZJ137164
Reg. Date:	27/05/2015 (Man. Year: 2015)	Chassis No:	ACR500188142
Colour:	Metallic White	Odometer:	123182 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,451.52	5,673.80	777.72	12.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	1,500.00	890.00	37.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,841.52</b>	<b>7,173.80</b>	<b>1,667.72</b>	<b>18.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
<b>(S\$)</b>	8,841.52	5,700.00	3,141.52	35.53
<b>+ GST 7.00/7.00% (S\$)</b>	618.91	399.00	219.91	35.53
<b>Nett Amount (S\$)</b>	<b>9,460.43</b>	<b>6,099.00</b>	<b>3,361.43</b>	<b>35.53</b>
<b>+ Loss of Use (7.0 x S\$120.00/day) (S\$)</b>		840.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>6,946.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,000.00</b>		

### INSPECTION

Date of Assignment: 09/12/2019

Date Inspected: 10/12/2019 Inspected At:

Alan's United Auto Pte Ltd (HQ)  
Blk 7 Sin Ming Industrial Estate, #01-76  
Singapore 575642

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,590.10 FL	*1,590.10 FL
2	1		*TAIL GATE GLASS MOULDING	Necessary	91.20 FL	*91.20 FL
3	2		*TAIL GATE LAMP	Cracked	766.80 FL	*766.80 FL
4	1		*TAIL GATE LAMP CTR REFLECTOR	Cracked	381.60 FL	*381.60 FL
5	1		*TAIL GATE LOGO	Necessary	66.80 FL	*66.80 FL
6	1		*TAIL GATE OUTER CHROME	Warped	287.70 FL	*287.70 FL
7	1		*TAIL GATE INNER TRIM COVER	Mtg Cracked	476.40 FL	*476.40 FL
8	2		*TAILLAMP	Serviceable	885.60 FL	*- FL
9	1		*REAR END PANEL	Bent	625.50 FL	*625.50 FL
10	1		*END PANEL TOP GARNISH	Buckled	260.50 FL	*260.50 FL
11	6		*END PANEL TOP GARNISH CLIPS	Necessary	44.40 FL	*44.40 FL
12	1		*END PANEL LOWER GARNISH	Dented	175.80 FL	*175.80 FL
13	2		*REAR FENDER INNER TRIM	Deformed	1,486.60 FL	*1,486.60 FL
14	1		*REAR BUMPER FASCIA	Buckled	541.70 FL	*541.70 FL
15	1		*REAR BUMPER SIDE RETAINER	O/s Distorted	103.80 FL	*51.90 FL
16	2		*REAR BUMPER SIDE SPONGE	Cracked	131.40 FL	*131.40 FL
17	2		*REAR BUMPER SIDE RETAINER (S)	Serviceable	72.80 FL	*- FL
18	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
19	1		*REAR BUMPER REVERSE SENSOR (4PC)	Dented	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,448.70</b>	<b>7,418.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,997.18	1,744.60
<b>Total Parts (\$)</b>	<b>6,451.52</b>	<b>5,673.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING,FRONT AND REAR SEATS,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO REMOVE AIR CON CONDENSER,PIPES AND DRIER,VACUUM AND TO RECHARGE GAS	New	120.00	0.00
4	TO APPLY UNDERSEALING	New	100.00	60.00
5	TO PUTTY AND SPRAY REPLACED PARTS	New	900.00	660.00
6	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,000.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,390.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >