

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021725/QBA3Q2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900163727

Claimant
Vehicle No : SLE2661K **Insured Vehicle No :** SGG7902G

Date of Loss: 06/12/2019 Nature of Claim: TP Claim No: 9505069870SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE2661K		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	L15B3536653
Reg. Date:	14/07/2016 (Man. Year: 2016)	Chassis No:	GK81005670
Colour:	White	Odometer:	227819 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,860.00	1,948.00	912.00	31.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,200.00	1,120.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	5,180.00	3,148.00	2,032.00	39.23
Approved Total (Overridden) (\$)		2,500.00		
(\$)	5,180.00	2,500.00	2,680.00	51.74
+ GST 7.00/7.00% (\$)	362.60	175.00	187.60	51.74
Nett Amount (\$)	5,542.60	2,675.00	2,867.60	51.74
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 10/12/2019

Date Inspected: 10/12/2019 Inspected At:

Lion City Rentals Pte Ltd
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/L DOOR	Dented	1,575.00 FL	*1,050.00 FL
2	1		*R/L FENDER	Dented	2,000.00 FL	*1,385.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,575.00	2,435.00
- List Item Discount on L Items 20.00/20.00% (S\$)	715.00	487.00
Total Parts (S\$)	2,860.00	1,948.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING R/L DOOR AND INCLUDE CUTTING OUT R/L FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	600.00
2	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS	New	120.00	100.00
3	TO RESPRAY R/L DOOR AND R/L FENDER	New	1,000.00	500.00
Gross Labour Cost (\$)			2,320.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >