

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021728/ARA3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100098490

Claimant
Vehicle No : SJD2628L **Insured Vehicle No :** SJJ9907D

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 2581695556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2628L	Engine No:	06407590N52B25AF
Make & Model:	BMW 523i, 2.5 (A)	Chassis No:	WBAFP320X0C546742
Reg. Date:	26/01/2011 (Man. Year: 2010)	Odometer:	137619 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,623.55	3,828.90	1,794.65	31.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	660.00	1,000.00	60.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,283.55	4,488.90	2,794.65	38.37
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	7,283.55	3,500.00	3,783.55	51.95
+ GST 7.00/7.00% (S\$)	509.85	245.00	264.85	51.95
Nett Amount (S\$)	7,793.40	3,745.00	4,048.40	51.95
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,145.00		

INSPECTION

Date of Assignment: 10/12/2019

Date Inspected: 10/12/2019 Inspected At:

Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Deformed	1,200.00 FL	*1,200.00 FL
2	1		*FRONT BUMPER SPONGE	Cracked	160.00 FL	*160.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	708.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	45.00 FL	*45.00 FL
5	1		*FRONT BUMPER NOZZLE COVER	Cracked	50.00 FL	*50.00 FL
6	1		*FRONT BUMPER CLIPS	Necessary	72.00 FL	*30.00 FL
7	1		*FRONT BUMPER AIR GRILLE GARNISH RH	Not Necessary	38.00 FL	*- FL
8	1		*FRONT BUMPER AIR DUCT RH	Cracked	39.00 FL	*39.00 FL
9	1		*HEADLAMP RH	Cracked	2,302.00 FL	*2,302.00 FL
10	1		*FOG LAMP RH	Cracked	295.00 FL	*295.00 FL
11	1		*FRONT BUMPER PARKING SENSOR RH (OUTER)	Not Necessary	380.00 FS	*- FS
12	1		*FRONT GRILLE (ACC)RH	Not Necessary	250.00 FS	*- FS
13	1		*HEAD LAMP BLACK STICKER (ACC)	Necessary	150.00 FS	*40.00 FS
14	1		*HEAD LAMP EYE LIP (ACC)	Necessary	180.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,869.00	4,241.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	245.45	412.10
Total Parts (\$\$)	5,623.55	3,828.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	TO RESET ELECTRICAL SYSTEM	New	280.00	80.00
3	TO RESPRAY AFFECTED AREAS	New	600.00	250.00
4	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR FRONT RH FENDER ,FRONT SUPPORT PANEL & ALIGNED ALL PARTS	New	700.00	300.00
Gross Labour Cost (\$)			1,660.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >