

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6740P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR LH	DENTED	1,755.00	950.00
1	REAR DOOR LH	DENTED	1,850.00	950.00
1	REAR DOOR UPPER HINGE LH	SERVICEABLE	145.00	-
1	REAR DOOR LOWER HINGE LH	SERVICEABLE	145.00	-
1	FRONT MUDFLAP LH	SERVICEABLE	285.00	-
1	SIDE MIRROR LH	SERVICEABLE	730.00	-
1	REAR FENDER WHEEL ARC LH	SCRATCHED	330.00	200.00
1	REAR MUDFLAP LH	SCRATCHED	283.00	125.00
1	REAR RIM LH	SCRATCHED	650.00	450.00
1	REAR ABSORBER LH	SERVICEABLE	455.00	-
1	REAR WHEEL BEARING LH	SERVICEABLE	240.00	-
	LESS 20% DISCOUNT		-1,373.60	-535.00
			5,494.40	2,140.00
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS.		1,000.00	500.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIT FRONT & REAR DOOR LH MECHANISM TO NEW DOOR ASSY.		300.00	140.00
	LABOUR TO REPLACE RH REAR UNDERCARRIAGE PARTS.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIT LH REAR WHEEL RIM TYRE.		100.00	40.00
	TO CONDUCT WHEEL ALIGNMENT & BALANCING.		150.00	60.00
	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.		100.00	30.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		1,000.00	600.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		80.00	30.00
			3,230.00	1,400.00
	GRAND TOTAL		8,724.40	3,540.00

Report Ref No. CS/INC19021739/Qtd3e2





RECOMMENDED COST OF LUMP SUM REPAIRS	2,850.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC19021739/Qtd3e2

Ja

OI SUN PIN

**Asst. Automotive Assessor** 

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser