FONG MOTORS

1 Kaki Bukit Ave 6 Blk C #01-27/45, AutoBay@ Kaki Bukit Singapore 417883 Tel: 6747 6388, Email: fongmotors@gmail.com Company Reg No. 068972/00L

Terence Tan
Blk 119 Toa Payoh Lor 1
#09-449
Singapore 310119

TP AXA. Xiao Tony.
 Estimate

 Code:
 FMSMF7317E

 Date
 10/9/2019

 Vehicle No.
 SMF7317E

 Model
 HONDA JAZZ

 CHASSIS/ENG#
 JHMGK5850JX20955

PARTS

| S/N | N Particular | Quantity | Unit Price | Amount |
|-----|--|----------|------------|----------------------|
| | 5. 104 | | | |
| 1 | Rear Tail Gate Dewild | 1 | \$799.60 | \$799.60 |
| 2 | Rear Tail Gate Hinge L/R | 2 | \$35.50 | \$71.00 |
| 3 | Rear Tail Gate Damper L/R √ | 2 | \$146.20 | \$292.40 |
| 4 | Rear Tail Gate Rubber Weather Strip | 2 | \$105.30 | \$210.60 /0530 |
| 5 | Rear Tail Gate Guide Stopper | 2 | \$7.50 | \$15.00 + |
| 6 | Rear Tail Gate Chrome Garnish | 1 | \$351.30 | \$351.30 + |
| 7 | Rear Tail Gate Chrome Garnish Clips | 4 | \$6.50 | \$26.00 + |
| 8 | Rear Tail Gate Jazz Emblem | 1 | \$45.40 | \$45.40 |
| 9 | Rear Tail Gate Mechanism Lock Dand | 1 | \$209.20 | \$209.20 |
| 10 | Rear Tail Gate Inner Handle While Man | 1 | \$75.20 | \$75.20 X |
| 11 | Rear Tail Gate Inner trimboard | 1 | \$168.30 | \$168.30 |
| 12 | Rear Tail Gate Windscreen Glass Moulding | 1 | \$953.70 | \$953.70 + |
| 3 | Rear Tail Gate Windscreen Glass Moulding | 1 | \$45.00 | \$45.00 |
| 4 | Rear Tail Gate Wiper Motor HM Nec | 1 | \$238.20 | \$238.20 |
| 5 | Rear Tail Lamp L/R (Mulled | 2 | \$252.30 | \$504.60 |
| 6 | Rear Tail Lamp Panel L/R | 2 | \$603.60 | \$1,207.20 \times |
| 7 | Rear Tail Lamp Stay Clips New | 4 | \$6.50 | \$26.00 + |
| 18 | Rear End Panel Devila | 1 | \$393.50 | \$393.50 |
| 9 | Rear End Panel Inner Top Garnish | 1 | \$75.80 | \$75.80 |
| 0.0 | Rear End Panel Inner Top Garnish Clips | 4 | \$6.50 | \$26.00 |
| 1 | Rear End Panel Antenna Sensor Could | 1 | \$78.80 | \$78.80 |
| 2 | Rear Trunk Panel Regra | 1 | \$534.60 | \$534.60 |
| 3 | Rear Trunk Panel Insualtor Mat | 1 | \$189.70 | \$189.70 + |
| 4 | Rear Trunk Panel Compartement Sponge | 1 | \$193.20 | \$193.20 |
| 5 | Rear Trunk Panel Buzzer Sensor Cruhed | 1 | \$87.80 | \$87.80 |
| 6 | Rear Bumper Dela | 1 | \$615.50 | \$615:50 492 |
| 7 | Rear Bumper Side Retainer L/R | 2 | \$19.50 | \$39.00 |
| 8 | Rear Bumper Side Retainer L/R | 1 | \$312.50 | \$312.50 + |
| 9 | Rear Bumper Reverse Sensor Dard & Pille | 51 | \$1,021.99 | \$1,021.99 40() |
| 0 | Rear Bumper Lower Garnish Delomed | 1 | \$212.10 | \$212.10 |
| | | | | |

| Rear Number Plate Rear Number Plate Garnish Rear Number Plate Garnish | SUBTOTA 1 | Sub-total 1 | \$9,609.79 \$1,921.96 \$7,687.83 |
|--|---|---|--|
| Rear Number Plate Affice Rear Number Plate Garnish Affice | 1 | Sub-total 1 | |
| Rear Number Plate Garnish | 1 | Sub-total 1 | \$7,687.83 |
| Rear Number Plate Garnish | 1 | Sub-total 1 | \$7,687.83 |
| Rear Number Plate Garnish | 1 | | |
| | | \$25.00 | \$25.00 × |
| Poor Toil Cata Issue trial and all and Ida | 1 | \$50.00 | \$50.00 + |
| Rear Tail Gate Inner trimboard clips | 1 | \$30.00 | \$30.00 |
| Rear Tail Gate Windscreen Glass Sealant | 1 | \$80.00 | \$80.00-60 |
| Rear Bumper Clips WW 120 | 1 | \$30.00 | \$30.00 |
| Labour | | Sub-total 2 | \$215.00 |
| | 1 | \$50.00 | \$50.00 ~ |
| | 1 | | \$60.00-30 |
| To remove & refix/renew reverse sensor assy and rectify | 1 | \$80.00 | \$80.00 50 |
| | | | |
| To remove reinstall rear tailgate windscreen | 1 | \$100.00 | \$100.00 |
| To remove, reinstall roof top trim upholstery csuhion seat | 1 | \$140.00 | \$140.00 60 |
| trim garnish trim liner carpet | | | |
| To remove rear seat dismantle | 1 | \$80.00 | \$80.00 × |
| To respray painting on the change bodyparts repair portion and where consistent to the accident | 1 | \$1,200.00 | \$1,200.00 80 |
| To provide Labour,workmanship to change the above damage bodyparts,repair, re-align body structure, body | 1 | \$1,250.00 | \$1,250.00 80 |
| alignments damage consistent to the accident | | | |
| To dismantle repair and realign rear wiper linkage and | 1 | \$100.00 | \$100.00 × |
| | 1 | ¢120.00 | |
| | | | \$120.00 60 |
| alignment back into its orignal specifications | 1 | \$250.00 | \$250.00 × |
| | - | Labour Total | \$3,430.00 |
| | To provide towing charge To remove, reinstall electrical wiring harness, check lighting To remove & refix/renew reverse sensor assy and rectify for proper functioning To remove reinstall rear tailgate windscreen To remove, reinstall roof top trim upholstery csuhion seat trim garnish trim liner carpet To remove rear seat dismantle To respray painting on the change bodyparts repair portion and where consistent to the accident To provide Labour, workmanship to change the above damage bodyparts, repair, re-align body structure, body alignments damage consistent to the accident To dismantle repair and realign rear wiper linkage and motor assy to proper functioning To apply anti-rust chemical on repair and replaced panel To set the chasis bench, adjust and align front chasis | To provide towing charge To remove, reinstall electrical wiring harness, check lighting To remove & refix/renew reverse sensor assy and rectify for proper functioning To remove reinstall rear tailgate windscreen To remove, reinstall roof top trim upholstery csuhion seat trim garnish trim liner carpet To remove rear seat dismantle To respray painting on the change bodyparts repair portion and where consistent to the accident To provide Labour, workmanship to change the above damage bodyparts, repair, re-align body structure, body alignments damage consistent to the accident To dismantle repair and realign rear wiper linkage and motor assy to proper functioning To apply anti-rust chemical on repair and replaced panel To set the chasis bench, adjust and align front chasis | To provide towing charge To remove, reinstall electrical wiring harness, check lighting To remove & refix/renew reverse sensor assy and rectify for proper functioning To remove reinstall rear tailgate windscreen To remove, reinstall roof top trim upholstery csuhion seat To remove, reinstall roof top trim upholstery csuhion seat To remove rear seat dismantle To respray painting on the change bodyparts repair portion and where consistent to the accident To provide Labour, workmanship to change the above damage bodyparts, repair, re-align body structure, body alignments damage consistent to the accident To dismantle repair and realign rear wiper linkage and motor assy to proper functioning To apply anti-rust chemical on repair and replaced panel To set the chasis bench, adjust and align front chasis alignment back into its orignal specifications |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

total: 5120.48 4/87 H.AK 06 Days.

Parts & Labour Total \$11,332.83