

REPAIR ESTIMATE*

VEHICLE NO : SH 8298M

DATE 9/12/2019 14:29

MAKE :

MODEL : HYUNDAI i40

Lke

CHINI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>Org</i>			\$ 1,110.10	
	Front Bumper Cover <i>x(r)</i>			\$ 1,052.20	
	Front Bumper Bracket Top (LH/RH) <i>xnn</i>		\$ 22.40	\$ 44.80	
	Front Bumper Bracket (LH/RH) <i>xnn</i>		\$ 24.60	\$ 49.20	
	<i>S</i> Radiator Grille Emblem - \$39.50 <i>Part taken rec.</i>				
	SUB TOTAL			\$ 2,256.30	
	LESS 20%			\$ 451.26	
	DISCOUNTED TOTAL			\$ 1,805.04	
	Front Number Plate <i>Org</i>			\$ 25.00	Nett
	Front No Plate Trim Cover <i>Scr</i>			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 350.00	\$280
	Spray Painting Charge			\$ 250.00	\$200
	Towing Fees		<i>xnn</i>	\$ 60.00	?
	TOTAL LABOUR			\$ 660.00	
	ESTIMATE TOTAL			\$ 2,520.04	

Ram (Lke)
9/12/19 1630hrs

Parasuram@lkkauto.com
88622728 hp

(2) repairs days
AA repair photo

(P/S)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.