

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19021766/GYD3E2
Date: 12/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SMJ924C **Insured Vehicle No :** GBF5886Y
 Date of Loss: 07/12/2019 Nature of Claim: TP Claim No: 1471529760SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ924C**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: HIDDEN
 Reg. Date: 21/04/2009 (Man. Year: 2009) Chassis No: JTDER12W003003000
 Colour: Blue Odometer: 221248 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/12/2019
 Date Inspected: 10/12/2019 Inspected At: Mje Motor (sin Ming, #01-96) (HQ)
 Block 7 Sin Ming Industrial Estate Sector C, #01-96
 Singapore 575642
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Buckled	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
9	1		*TAILGATE	Buckled	0.00 F	*- F
10	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE MOULDING	Deformed	0.00 F	*- F
12	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
13	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
14	1		*TAILGATE LOCK	Bent	0.00 F	*- F
15	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
16	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F
17	1		*REAR RH FENDER	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >