



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004855
INV Date 09/07/2020
Reference CC4/FCI19021773/Ada3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. PA 8798J
Insured Veh. SHC 1909L
Claim No. D19007645MFSH/1
Policy No. D-19092580MFSH
Accident Date 01/12/2019
Inspection Date 10/12/2019

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI19021773/Ada3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-07-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1909L	Veh. Inspected	PA 8798J	
Policy No.	D-19092580MFSH	Coverage (\$)	0.00	
Claim No.	D19007645MFSH/1	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	09/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTFST22P800007047	Colour	WHITE	
Odometer	370114	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	HABILEAD	6 mm	
L/H Front Tyre	195 R15C	HABILEAD	6 mm	
R/H Rear Tyre	195 R15C	HABILEAD	6 mm	
L/H Rear Tyre	195 R15C	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2019	Inspection Date	10/12/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8798J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	580.30	580.30
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	62.40	62.40
1	TAIL LAMP RH	CRACKED	338.90	338.90
1	TAILLAMP LOWER GARNISH RH	TORN	155.20	155.20
1	TAILLAMP LOWER GARNISH RETAINER RH	NOT NECESSARY	65.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	2,388.50	-
1	REAR FENDER INNER COWLING	TORN	180.00	180.00
1	REAR FENDER AIR VENT	CRACKED	80.00	80.00
1	REAR FENDER GLASS MOULDING	NOT NECESSARY	190.00	-
	LESS 25% DISCOUNT		-1,010.08	-349.20
			3,030.22	1,047.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NECESSARY	20.00	20.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	WHEEL RIM COVER (SN)	CUT	280.00	60.00
			540.00	120.00
	<u>LABOUR</u>			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER .		2,200.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		2,000.00	600.00
	TUFF COAT.		250.00	60.00
	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.		150.00	80.00
	TO REMOVE AND REFIX REVERSE SENSOR SETTING.		80.00	50.00
	REMOVE AND REFIX FENDER WINDSCREEN.	NOT NECESSARY	120.00	-
			4,800.00	1,390.00
	GRAND TOTAL		8,370.22	2,557.60

Report Ref No. CC4/FCI19021773/Ada3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CC4/FCI19021773/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 8798J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 8798J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

