

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9045U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
10	REAR BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	REAR BUMPER SPONGE	NOT NECESSARY	103.50	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDERCOVER	NOT NECESSARY	228.00	-
	LESS 25% DISCOUNT		-333.73	-
			1,001.17	-
	<u>SPECIAL NETT ITEMS</u>			
1	ADVERTISEMENT -REAR BUMPER (SN)	NECESSARY	50.00	50.00
2	ADVERTISEMENT -REAR FENDER RH/LH @\$100.00 (SN)	NECESSARY	200.00	200.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		300.00	280.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	80.00	-
			680.00	480.00
GRAND TOTAL			1,931.17	730.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				600.00

Report Ref No. CC3/QBE19021775/Fea3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.