

ASS. REC. BY:

ASS. REC. BY:

REF: CS/CT1 K10 21785/ GV f3 12

Special Instruction:

Survivor: GA ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTI Date/Time: 10.12.19 16.31pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLP 8169L Insured: SJN 7137B

at Workshop m/s Ah Lim Motor Tel: 64831241

of 10 AME Industrial Park 2A #01-09

Policy No: DMPCSN 30117719000 Claim No: SNM1AD205866102

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.12.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS imp 11.12.2019 H.O.D. Endorsement: _____

Date/Time: 11.12.19 5.46pm Person Contacted: Zila Vehicle IN/OUT OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLP 8169L →</u>
	<u>SJN 7137B - X</u>
10/1/2020	@ 4:37pm Zila said vehicle has not send in for repair, pending liability
7/2/20	@ 12:00pm Mui Hong said vehicle has not send in for repair, pending liability

31/3/20 final fig \$ 720 confirmed by email (Recd 880.30, 55M)

31/3/20 To Submit final report in merimen

66d.

net: C11

ASSIGNMENT

From:

Date: 11-12-2019

Estimated Cost:

UD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 8769L

at Workshop no: Ah km motor

of 10 MK Industrial park 2A 101-09

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh: 2.30pm omw mady

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLP 8769L

Regn:

21 Jun 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota wish 1.8 c.c 1798

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp Reading:

26359

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

ITD 6620W00J007079

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F: 195/65 R15

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal:

6 mm

R/Bal:

6 mm

L/Bal:

6 mm

L/Bal:

6 mm

D.O.A:

D.O.I:

11-12-19

Survey held at

w/s

2.30pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 7 DEC 2019

Date/Time, File Path to?



Prel. Report

1)



Final Report

Date/Time, File Path to?

2) 7/2 - typist

Report Form:

Lump Sum / IE / etc

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Meet and (\$)

Survey Fee:

Transportation:

7 + RS BA

Phone

Notes

TOTAL

250

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ALISON NG LI YING
932A HOUGANG AVE 9
#15-90
SINGAPORE 531932
TEL: 93671892

Estimate No: MC1900881
Date: 10 Dec 2019
Policy No: PNPV2019-00005768
Veh Reg No: SLP8769L
Make/Model: TOYOTA WISH 1.8 CVT

ATTN:
Your Ref No: SLP8769L
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SJN7137B

Estimate Repair Cost to Vehicle No :SLP8769L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT FENDER RH <i>X Repair</i>	1 PC	720.40	
2 FRONT DOOR PROTECTOR RH - CHECK PRICE <i>/ REC. 160</i>	1 PC	0.00	
		720.40	
	Less 25%	180.10	540.30
LABOUR			
3 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS. TEST AND RECTIFY FOR PROPER FUNCTIONING	1 PC	40.00	<i>X NN</i>
4 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	<i>200</i>
5 TO SPRAY FRONT DOOR RH. FRONT FENDER RH. SIDE MIRROR RH.	1 PC	500.00	<i>400</i>
		940.00	940.00
	1600.30	Total	S\$ 1,480.30
		Add GST @ 7%	103.62
		Total Amount Payable	S\$ 1,583.92

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS NINETY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

12/12/19 3 Days
part by nt
After repair photos
Gino Riap - 82880282
11/12/19

LIM MOTOR COMPANY hereby notify the Receiver of the following:
• Surveyor's report is for insurance company's use only.
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AUTHORISED SIGNATURE

Acknowledged by Repairer
Signature:
Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S: ALISON NG LI YING
932A HOUGANG AVE 9
#15-90
SINGAPORE 531932

TEL: 93671892

ATTN:

Your Ref No: SLP8769L

Claim Type: Third Party

Accident Date: 06/12/2019

TP Veh Reg No: SJN7137B

Claim No: MC1900881
No: MF1900968
Date: 30 Mar 2020
Policy No: PNPV2019-00005768
Veh Reg No: SLP8769L
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W00J007079
TP Ins Co: CHINA

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLP8769L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT DOOR PROTECTOR RH	1 PC	160.00	
		160.00	
	Less 25%	40.00	120.00
LABOUR			
2 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
3 TO SPRAY FRONT DOOR RH,FRONT FENDER RH, SIDE MIRROR RH.	1 PC	400.00	
		600.00	600.00
Total			S\$ 720.00
Add GST @ 7%			50.40
Total Amount Payable			S\$ 770.40

TOTAL: SINGAPORE DOLLAR SEVEN HUNDRED SEVENTY AND CENTS FORTY ONLY

The above vehicle was surveyed by GUO QIANG - LKK on 11/12/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ALISON NG LI YING
932A HOUGANG AVE 9
#15-90
SINGAPORE 531932

TEL: 93671892

ATTN:

Your Ref No: SLP8769L
Claim Type: Third Party
Accident Date: 06/12/2019
TP Veh Reg No: SJN7137B

Estimate No: MC1900881
Date: 10 Dec 2019
Policy No: PNPV2019-00005768
Veh Reg No: SLP8769L
Make/Model: TOYOTA WISH 1.8 CVT

Estimate Repair Cost to Vehicle No :SLP8769L

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 FRONT FENDER RH <i>X Repair</i>	1 PC	720.40	
2 FRONT DOOR PROTECTOR RH - CHECK PRICE <i>REC. 160.00</i>	1 PC	0.00	
		720.40	
	Less 25%	180.10	540.30
LABOUR			
3 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>X</i>
4 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	<i>200</i>
5 TO SPRAY FRONT DOOR RH, FRONT FENDER RH, SIDE MIRROR RH.	1 PC	500.00	<i>400</i>
		940.00	940.00
Total			SS 1,480.30
Add GST @ 7%			103.62
Total Amount Payable			SS 1,583.92

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS NINETY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

*3 Days .
part by rt .
After repair photos .
Gmo Riap - 82880282
11/12/19 .*

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

17-02-2020

KOK

*Man Photo
18-02-2020*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119021785/GVF3N2
 Date: 31/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30117719000
 Claimant Vehicle No: SLP8769L Insured Vehicle No: SJN7137B
 Date of Loss: 06/12/2019 Nature of Claim: TP Claim No: SNM19D205866C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP8769L
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1960690
 Reg. Date: 21/06/2017 (Man. Year: 2017) Chassis No: JTDGG20W00J007079
 Colour: Grey Odometer: 26359 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	660.30	120.00	540.30	81.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	600.00	340.00	36.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,600.30	720.00	880.30	55.01
+ GST 7.00/7.00% (S\$)	112.02	50.40	61.62	55.01
Nett Amount (S\$)	1,712.32	770.40	941.92	55.01

INSPECTION

Date of Assignment: 10/12/2019
 Date Inspected: 11/12/2019 Inspected At: Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8769L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	720.40 FL	*- FL
2	1		*FRONT DOOR PROTECTOR RH	Necessary	160.00 FL	*160.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					880.40	160.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					220.10	40.00
Total Parts (\$\$)					660.30	120.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	0.00
2	TO DISMANTLE ALL DAMAGED PARTS,TO CUT & WELD.TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	400.00	200.00
3	TO SPRAY FRONT DOOR RH,FRONT FENDER RH,SIDE MIRROR RH	New	500.00	400.00
Gross Labour Cost (\$\$)			940.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >