

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19021790/ASF3E2

Date: 29/05/2020

REFERENCE

Insured/Claimant:	CHAN MEI LING ALISON	Policy No:	1700094795-01
Date of Loss:	05/12/2019	Nature of Claim:	OD
		Claim No:	1494153971SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH3033A		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ601132
Reg. Date:	05/01/2018 (Man. Year: 2017)	Chassis No:	WAUZZZGA6JA043704
Colour:	Orange	Odometer:	38487 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,527.00	1,708.80	7,818.20	82.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,112.00	3,432.00	3,680.00	51.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,639.00	5,140.80	11,498.20	69.10
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	16,239.00	4,740.80	11,498.20	70.81
+ GST 7.00/7.00% (\$\$)	1,136.73	331.86	804.87	70.81
Nett Amount (\$\$)	17,375.73	5,072.66	12,303.07	70.81

INSPECTION

Date of Assignment:	11/12/2019	
Date Inspected:	10/12/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,706.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Not Necessary	273.00 FS	*- FS
4	1		*FRONT WHEEL SPOILER - RH	Not Necessary	31.00 FS	*- FS
5	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	38.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	32.00 FS	*- FS
7	1		*FRONT FENDER - RH	Repair	1,047.00 FS	*- FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
9	1		*FRONT FENDER BRACKET - RH	Not Necessary	43.00 FS	*- FS
10	1		*FRONT FENDER BRACKET - RH	Not Necessary	14.00 FS	*- FS
11	1		*FRONT FENDER BRACKET - RH	Not Necessary	14.00 FS	*- FS
12	1		*FRONT FENDER BRACE - RH	Not Necessary	29.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	52.00 FS	*- FS
15	2		*FRONT WHEEL COVER - LH / RH	Necessary	588.00 FS	*469.60 FS
16	1		*FRONT DOOR - RH	Repair	2,285.00 FS	*- FS
17	1		*FRONT DOOR CATCH	Not Necessary	109.00 FS	*- FS
18	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	85.00 FS	*- FS
19	1		*TYRE PRESSURE DATA PLATE	Not Necessary	26.00 FS	*- FS
20	1		*EXTERIOR MIRROR MOUNTING	Damaged	471.00 FS	*376.40 FS
21	1		*MIRROR GLASS - RH	Not Necessary	282.00 FS	*- FS
22	1		*CORNER TRIM - RH	Cut	41.00 FS	*32.80 FS
23	1		*WINDOW GUIDE	Not Necessary	377.00 FS	*- FS
24	1		*WINDOW APERTURE SEAL - RH OUTER	Deformed	119.00 FS	*95.20 FS
25	1		*FRONT DOOR COVER - RH	Cut	235.00 FS	*187.60 FS
26	1		*FRONT ALUMINIUM RIM - RH	Cut	548.00 FS	*438.40 FS
27	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
28	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
29	1		*MIRROR CAP - RH	Missing	136.00 FS	*108.80 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					9,527.00	1,708.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	0.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY	New	300.00	300.00
4	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	500.00
5	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR AND RHS WING MIRROR COVER	New	2,500.00	1,800.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,112.00	3,432.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >