

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT


AXA INSURANCE PTE LTD Ref: CS3/ASM19021791/Hcf3s2

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 07-01-2020

068811

| ATTN: RUIHONG LI | | | Code: ASM | | | |
|--|----------------|-------------------|----------------|------------|--|--|
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | | |
| | Insured Veh. | SLF 2913D | Veh. Inspected | SGJ 2467M | | |
| | Policy No. | | Coverage (\$) | 0.00 | | |
| | Claim No. | S9M029PQ | Excess (\$) | 0.00 | | |
| | Assign From | RUIHONG LI | Assign Date | 11/12/2019 | | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA ALTIS | c.c | 1598 | | |
| | Engine No. | HIDDEN | Year of Reg. | 2006 | | |
| | Chassis No. | MR053ZEC107125909 | Colour | SILVER | | |
| | Odometer | 82779 KM | Steering | IN ORDER | | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | Balance | | |
| | R/H Front Tyre | 185/70 R14 | KUMHO | 5 mm | | |
| | L/H Front Tyre | 185/70 R14 | KUMHO | 5 mm | | |
| | R/H Rear Tyre | 185/70 R14 | FALKEN | 5 mm | | |
| | L/H Rear Tyre | 185/70 R14 | FALKEN | 5 mm | | |
| 4. Description of Damages | | | | | | |

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.



Page No.:1 of 1

| 5. | General Information | | | | | |
|----|---------------------|--|---------------------|-------------------------|--|--|
| | Accident Date | 09/12/2019 | Inspect Date / Time | 11/12/2019 (02:10 PM) | | |
| | Survey held at | ALPHA CAR SERVICES PTE LTD | | | | |
| | | BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883 | | | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days

Report Ref No. CS3/ASM19021791/Hcf3s2

Inspected By

LEE HOCK ANN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.