



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO19021802/Esd3q2	
			Date: 13/01/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 3379L	Veh. Inspected	GBA 3685A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD1905749/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	11/12/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	JTFHT02P200003977	Colour	BLUE
	Odometer	42730 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MICHELIN	5 mm
	L/H Front Tyre	195 R15C	MICHELIN	5 mm
	R/H Rear Tyre	195 R15C	MICHELIN	5 mm
	L/H Rear Tyre	195 R15C	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S,NS AND REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/12/2019	Inspection Date	11/12/2019
	Survey held at	15 FAN YOONG ROAD		
	Repairer	MOVA AUTOMOTIVE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	