

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 5473U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR REVERSE CAMERA (CONSISTENT)	NOT NECESSARY	180.00	-
1	REAR R/H HEAD LIGHT (CONSISTENT)	NOT NECESSARY	880.00	-
1	REAR BUMPER (CONSISTENT)	CUT	1,500.00	895.00
1	REAR BUMPER SIDE RETAINERS (CONSISTENT)	NOT NECESSARY	170.00	-
1	BUMPER SENSOR (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR BUMPER REFLECTORS (CONSISTENT)	BROKEN	380.00	210.00
1	REAR BUMPER TOP STEP GARNISH (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	480.00	-
1	REAR END PANEL INNER GARNISH (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR BOOT GARNISH (CONSISTENT)	NOT NECESSARY	100.00	-
1	HYDRAULIC HINGE (CONSISTENT)	NOT NECESSARY	200.00	-
2	RUBBER MOULDING (CONSISTENT)	NOT NECESSARY	40.00	-
	LESS 20% DISCOUNT		-	-221.00
			4,320.00	884.00
	SPECIAL NETT ITEMS			
1	BACK BUMPER CLIP (CONSISTENT)(SN)	NECESSARY	150.00	30.00
1	SET REAR REVERSE SENSOR (CONSISTENT)(SN)	NOT NECESSARY	620.00	-
			770.00	30.00
	<u>LABOUR</u>			
	REMOVE AND REFIT REAR TAILGATE.	NOT NECESSARY	300.00	-
	REMOVE AND REFIT REAR BUMPER.		300.00	200.00
	REMOVE,REFIT AND REPLACED DAMAGE LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		150.00	30.00
	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR.	NOT NECESSARY	200.00	-
	REMOVE AND REFIT REAR REVERSE SENSOR.		240.00	20.00
	TO APPLY UNDERCOATING ON REPLACED PANEL.		120.00	30.00
	TO RESPRAY PAINTING.		1,000.00	400.00
			2,310.00	680.00
	GRAND TOTAL		7,400.00	1,594.00

Report Ref No. CC4/ASM19021811/Egs3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM19021811/Egs3q2



Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor