POLICE REPORT Pg. 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 3

Report No. T/20190909/2090

Date/Ti 09/09/2	me Report 019 14:57	Made:	Vide Report No.: D/20190909/0039	Station Diary No.:			
Informa	ant's Partic	ulars	Volume 15 Live State 1 1 1	712 A 12 E			
	f Informant 'ING MING		Address:				
ID Type / ID No.: FIN NO / G2482597W			Contact No.: Home/Office: Mobile: 85990556				
Nationality: CHINESE			Home/Office: Mobile: 85889556 Email:				
Sex: Male	Age: 35	Date of Birth: 16/03/1984	Type of Informant: Driver				
Race: Chinese Occupation: SERVICE SECTOR			Language: Institution / School Name				
			Driving Licence Information: Class: 3,4	Date of Expiry:			

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident:	Type of Location Straight Road	
Location: Along Road 1 PENJURU RO			09/09/2019 08:4		
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision Between Movin	on: ng Vehicles - Head To R	ear		Anyone conveyed by ambulance:	

Vehicle No.	Туре	Make	Model	Color	Condition	NOTE:
SKA5577J	Car	TOYOTA		-	Condition	No of Passenge
ASSERVATOR SECTION AND	Our	TOTOTA	COROLLA ALTIS 1.6 AUTO	Beige	Slightly Damaged	0
XD5732H	Lorry	D.A.F.	CF FT CF85.410 SMT 13L ABS TURBO	Blue	Slightly Damaged	0

POLICE REPORT Pg. 2



T/20190909/2090

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20190909/2090

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date, time and location

I was travelling straight on extreme tight of the 2 lanes road. I wanted to make a lane change to the extreme left. Before engaging, I made sure to check the mirror and the blind spot. It was at this moment where I collided onto another vehicle which was in-front of me.

POLICE REPORT Pg. 3





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20190909/2090

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.

Signature Of Officer Recording The Report: TP / NG JIN SHENG	Signature Of Informant: 2HAO YING MING
Signature Of Interpreter: Not applicable	Date/Time: 09/09/2019 14:57
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI Contact No.: 65476904	Classification Of Case:
Authentication Stamp	




Accident Photo














Accident Photo









GUAN AUTO SERVICE

Blk 7 Sin Ming Industrial Estate Sector C, ##01-82 Singapore 575642

TO: Chuah Taik Sim

57 Yuk Tong Avenue

Singapore 596358

Date: 09 October 2019

Tax Invoice: GAS/SKA5577J/198242

Vehicle No : SKA 5577 J

Make/Model: Toyota Altis 1.6 Auto

Date Of Accident: 09.09.2019

PARTICULAR

(

Amount S\$

Rear Right Side & front both side Portion damaged

Repair, Replace, Straighten, Alignment, Panel Beating,

cutting, welding, reset, Labour And spraypainting etc.

Lump Sum Repair as per surveyor

recommendation -----

\$17,300.00

Singapore Dollars: Seventeen Thousand Three Hundred Only

Total \$

\$17,300.00 Nett



GUAN AUTO SERVICE



TAX INVOICE

GST REG. NO.: 200106276D

	2001002/02
DATE	INVOICE NO.
30-Sept-2019	A 40676

INVOICE TO	
CHUAH TAIK SIM 57 YUK TONG AVENUE SINGAPORE 596358	

	VHA NO.	DUE DATE	VEH. NO.
	A 40676	30-Sept-2019	SJB 7876 P
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 10 SEPTEMBER 2019 TO 21 SEPTEMBER 2019 YOUR REF: SKA 5577 J	11	112.14953	1,233.64
NA GROUND AND AND AND AND AND AND AND AND AND A			
GST @ 7%			\$86.36
TOTAL			\$1,320.00

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.

BKW Rent-A-Car Pte Ltd

120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg, No: 20-0106276-D Website: www.bkw.sg A subsidiary of BKW Automobile Pte Ltd



BKW RENT A CAR PTE LTD 120 Lower Delta Road #02,15 Cendex Centre Singapore 169208 Tel: 6738 7777 Fax: 6738 6666 ACRA No: 20-0106276-D GST Reg. No: 20-0106276-D 24 HOURS HELPLINE: 6223 1122 VEHICLE HIRING AGREEMENT

VHA NO: A 40676

I many				HIRING AGREEMEN		vvorksno	p: I u	DE DE
		R'S PARTICUL	ARS	Hirer's Own Vehicl	e No: SKH 55	F Beplace Vet	h No:	
Name (as in I/C		H TIPIN		Loan Vehicle No:	5 112 72	7/ VF	R No:	
NRIC/Passport			Birth: 11 10 145	Make & Model:		Auto/I	Manual Gr	roup:
Address: >	- TU	c Touls		y .	CHARGES	:	\$	
			s(59635	Daily	day @\$ 1	20 Per da	ay \$12	2001
Name & Addres	ss of Employer			Weekly/Monthly	week @\$	Per week/Month	IV	21
Occupation		Debtes		Others				7
Driving Licence	No:	Driving	1 9 1 - 1	CDW/PAI	@\$	Per day/Month	ılv	1
D/L Type: Local/	anche De Nation Steel and	Passed	Date: / -/	Delivery/Collection	Svc		1	
***************************************						GST	11	
	DRIVE	R'S PARTICUL	ARS	OR No:		(A) SUB-TOTA	L \$13	701
Name (as in t/C)			-	Petrol Level OUT	E 1/4 1	1/2 3/4 F	FILE	V
NRIC/Passport I		Date of	Birth:	& Surcharge IN			+	_
ss:			Age:	1		7	+	-
and undertail			S(Firstkm F Excess mileage is ch	REE per day argeable	GST		
occupation	-	Driving	Exp	Yrs at cents r	er km	TOTAL CHARGE	S	
riving Licence I	No:	Passed / F	Expiry Date:	18 14 14 18 18 18 18 18 18 18 18 18 18 18 18 18		グルグル ルグ・グル ルット ルット メン	AW BAY	1 78 6 W 18 18
I/L Type: Local/I	Int'l/Others:		Contact No:	M. K. M. M. K. M. W. K. S.				
10	- П					アグルルカル ルス・		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	8			28-18 W 18 18 W 18-25 V		A WAYA WAYA WA WAYA WAYA WAYA		
	Col.			NON WAIVER EXC	CARL TENEDISTRA	the first francisco	01-	and the same
	1			ACCESSORIES CH		1 1	15	
		7		Data Cards	등통점 인근하였다면 현재 연극하다 .		Radio / CD	
	0	1	0	□ Jack □	Tyre Opener	Petrol Cap	Spare Tyre	
					at I			
INDICATE:			T AMP	17	B			
A - Accidents D - Dents	-			15.10				
('cratches rack				Hirer's Signature : SINGAPORE Use 0		Additional	Driver's S	ignature :
have read and	d name to the tek	me and condition o	ii bash aldan as shin am					
payable under	this agreement a	and for parking and	traffic infringements n	reement. If I have presented hay be billed to that accoun	t and my signatur	e above will be con-	sidered to	have been
IMPORTANT		ard voucher. All is	nformation I have be	en given BKW Rent A C				
1. The Hirer a	ind the authorized	driver must be over 2	23 years of age and unde e a minimum of 2 years re	r 65 suffered or incurred	by you in respect o	whatsoever and howso If the vehicle or the use	e or the ope	ration of the
and qualifie	a driving expenser	ce. Failure to observe the Hirer/the Author	e stipulation may return a	The owner reserve	the right not to repl	paid immediately in the ace an replacement ve	ehicle if an a	accident
2 All vehicles	are supplied with a	petrol and should retu	rned with petrol level like is payable by the hirer shi	wise 8 Smoke or permit sr	noking and transpor	e repair at BKW author t of pets in the vehicle	are not allo	wed Any
he fail to ret	turn the vehicle at t	he appropriate petrol	ievei.	the cost of removin	g the offensive smel	pet's smell, the hirer a l or pet's hair between	\$200 - \$40	00
for any late	return at the rate s	hown per hour per da	be liable for additional charge inclusive of CDW and/o	PAI Incked keys inside	at a punctured tyre, of vehicle, by itself.	empty petrol tank, loss does not constitute a t	s of vehicle	s key or
where appli day rental	icable. Any returns	after our operation is	ours will be charged as a	full in the event the ow	ner's 24-Hours Eme	rgency Service is calle	ed upon to n	espond to
4. Use of the v	rehicle for illegal po	urpose (For instance	in connection with theft.	drug 10. In case of accident	the hirer shall repo	ne cost of such respons int to rental office imme	ediately An	accident
Vehicle stric	ctly for Singapore (be driven out of Singapo	all liability from all p	rarties claim. Full ex	allure to comply, the hi cess amount have to b	rer will have be paid imm	e to borne ediately m
penalty fee	of \$200 in addition	al to the appropriate	e Ltd. The hirer is liable for insurance top up in the co	Mr.S. Hop award of on seco	ident.			
6. The hirer an	osure of Malaysia und/or driver shall be	usage. Fresponsible for all dr	amages or losses howeve	in the car is sufficie	nt and do not drive v	when the vehicle is stall time will be bear by the	Il and does	not have
caused, all 1	traffic violations, fin	es and penalties impr	osed on the vehicle for thit's use or operation	12. All customers' data	will be kept strictly of	confidential and is solel	ly used for t	he
/. The hirer an	id/or driver shall be	responsible for all cla	aims damages losses	13. Lunderstand and ag	ree to the personal	ctions and other relating data collection statement	ig matters. ent stated o	in the
Date Out	Time Out	Mileage	and cost expense (include Check By	ng Terms and Condition Remarks	ns Pagé		+	93
Note that		196900				Hirer's/Driver Sig	mature	B
Return Of Vehicle	e: The Hirer Driver	Is Required To Sign	In The Column "Signature	Of Hirer Driver Failing Which T e Shall Be Accepted As Conclu	he Day And Time In	serted Relow Shall Re	Deemed T	o Be The
Questioned On A	any Account Whats	oever. And I had clea	red my belonging items fr	om the rental vehicle (cashcare	, parking coupons,	etc)"	De Challen	gec Or
Date In	Time In	Mileage	Check By	Remarks		1.		7511
2111111		11 11517	4 18 11 .	1111	200	Hirer's/Driver Sig	nature	B



Efficient Towing Services

403 Sm Ming Avenue 24 to 07, Sm Shirp Garden, Singapore, 570-403

Ab Di Mobile: 8588 887

Email: efficientlowing sg., postst com Business Reg. No. 53549144K. CASH SALE / JOB ORDER

	0
283	8
362	0
Ö.	Date

Jump Start Changing of battery

M Accident/Brehkdown Tyre Replacement

With Load/Cargo Box

51. Penjaha Rb 200: 116-115

Time (day night): gen gun

Location:

Vehicle No. SEASS/ K

Messis

48-10 1 HOLEN JOI-82

Multi/Basement

King Dolly

Transport Charge

Door Opening Service Low Body Kit

Crane Up/Winch Out

Tow Truck VLLYOP & Driver Name:

Others:

00

ash S

10:

Authorised By:

Collect Doc/Key

Repo

Woodlands and Tuas Checkpoint

注意:本公司对所拖之丰耥,在进行中如有任何损失或破坏,

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed. 一概由车主自行负责。

Reg. No : 52941122M

470 Segar Road #09-232 Singapore 670470 Email: ktoaa@singnet.com.sg HP: 98505311

****INVOICE****

M/S: Chuah Taik Sim

C/O Guan Auto Service.

Blk 7 Sin Ming Industrial Estate Sector C,

#01-82 Singapore 575642.

Invoice No

19-08242

Invoice Ref

TP/GAS/SKA5577J/8242

Date

08 October 2019

DESCRIPTION	Al	MOUNT
For Services Rendered Inspection Report Fees Inclusive Of:	s	974:00
Transportation And Photographs Eighty-Four (84) Copies		
Vehicle No : SKA 5577 J		
Make/Model: Toyota Corolla Altis 1.6 Auto		*00
		41
Singapore Dollars: Nine Hundred Seventy Four Only	s	974.00

Cheques should be made payable to KTO AUTOMOBILE ASSESSORS. Please indicate our Invoice No. on the reverse of your cheque.

KTO AUTOMOBILE ASSESSORS

Ong Ah Keng (CAE, AMIMI, MSAAA)

Automotive Appraiser

Reg. No: 52941122M

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S: Chuah Taik Sim

C/O Guan Auto Service.

Blk 7 Sin Ming Industrial Estate Sector C,

#01-82 Singapore 575642.

Date

: 08 October 2019

Our Ref

: TP/GAS/SKA5577J/8242

REFERENCE PARTICULARS

Date of Accident

: 09 September 2019

Date of Inspection : 09 September 2019 Type of Inspection : Third Party Claim

Date of Re-Inspn

VEHICLE PARTICULARS

Registration No

Make

Model

Year

: SKA 5577 J

: Toyota

: 2010

: Corolla Altis 1.6 Auto

Engine No

: 3ZZB003272

Chassis No

: MR053ZEE106176703

Odometer Colour

: 78258 km : Beige metallic.

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition

Foot Brake

Hand Brake

Front Off Side

Rear Near Side

Rear off Side

: Good

: Serviceable : Serviceable

General Body Work: Good

Steering Lightings

: Serviceable : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

Front Near side

Make : Falken

: Falken

: Falken

: Falken

Size

195/65R15

195/65R15

195/65R15

195/65R15


Thread Balance

6 mm

6 mm 4 mm

4 mm

GENERAL DESCRIPTION OF DAMAGES



The vehicle sustained damage at the rear off side & front both side portion. For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was \$17,300.00 nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs: Eighteen (18) working days.

Enclosed Eighty-Four (84) photographs depicting damage to the vehicle.

Inspection conducted at: Blk 7 #01-82 Sin Ming Industrial Estate Sector C, Singapore 575642.

Name of Workshop: Guan Auto Service.

In accordance to your instruction, we have not authorise repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation


ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

		AND DESCRIPTION OF THE PROPERTY AND THE	QTY	ASSESSED		ORIGINAL		REVISED
	A)	SPARE PARTS	PC/SET	CONDITION		QUOTATION		QUOTATION
	1	Front bumper	1	Distorted	\$	645.80	\$	645.80\$SAO
	2	Front bumper reinforcement ×(SUC)	1	Serviceable	\$	318.00		~ /
	3	Front bumper fog lamp L/R @ \$184.20 MS	2	LH only (Ripped off)	S	368.40	\$	184.20
	4	Front bumper fog lamp cover L/R @ \$64.00°	15 2	LH only (Ripped off)	\$	128.00	\$	64.00
	5	Front bumper bracket L/R @ \$43.80 MS	2	LH only (Bent)	S	87.60	\$	43.80
	6	Front bumper side retainer L/R @ \$38.17	2	LH only (Damaged)	S	76.34	\$	38.17
	7	Front bumper grille \(\seta_{\mathcal{V}} \)	1	Serviceable	\$	159.00		
	8	Front radiator grille was	1	Serviceable	\$	230.70		7.1.2
	9	Front headlamp L/R @ \$794.00 LFD 8	2	LH only (Broken)	S	1,588.00	\$	794.00 \$580
	10	Front bonnet 🕦	1	Dented	S	894.09	\$	894.09 \$ 750
	11	Front bonnet hinge L/R @ \$68.00	2	Bent	S	136.00	\$	136.00
	12	Front radiator support	1	Bent	S	1,954.00	\$	1,954.00 \$873.8
•	13	Front wheel house panel RH XHO	1	Dislodged	\$	1,955.00	\$	1,955.00 ×
	14	Front folder side mirror LH SS	1	Malfunction	S	497.00	S	497.00 \$ 2 60
	15	Front fender LH DAS	1	Dislodged	\$	579.50	5	(579.50\$281.AS
	16	Front fender quarter garnish LH	1	Torn	\$	58.00	S	58.00
	17	Front fender inner liner LH	1	Torn	\$	98.20	\$	98.20
	18	Front fuse & relay box	1	Cracked	\$	498.00	\$	498.00 € ≥80
	19	Front intake air tube 9	1	Torn	\$	159.00	\$	159.00
	20	Front wiper washer tank assy	1	Cracked	\$	257.00	\$	257.00 \$150
	21	Auto transmission mounting	1	Damaged	\$	151.10	\$	151.10
	22	Engine mounting back	1	Damaged	\$	161.10	\$	161.10
	23	Front air cleaner top cover XSVC	1	Serviceable	S	195.20		~
	24	Front air cleaner lower housing	1	Cracked	\$	490.00	\$	490.00×
	25	Front lower arm L/R @ \$395.20	2	Bent	S	790.40	\$	790.40
	26	Front shock absorber L/R (h	1 set	Bent	s	590.20	S	590.20
	27	Front shock absorber mounting @ \$82.10 vec	_2	Necessary	S	164.20	\$	164.20
	28	Front drive shaft RH × (CyC)	1	Serviceable	S	1.395.00		-
	29	Front drive shaft LH 8+	1	Bent	S	957.00	S	957.009 740
	30	Front cross member sub assy X (Svc)	/1	Serviceable	\$	2,942.00		~
	31	Front wheel hub bearing L/R @ \$210.50 vol	2	Jammed	\$	421.00	5	421.00 \$ 34 0
	32	Front door LH 70	1	Dented	\$	928.00	5	928.00 —
	33	Front door trim board LH Xnn	A	Deformed/Cracked	\$	499.30	\$	499.30 X
	34	Front rocker trim panel L/R \$498.00 A	2	Sheared off	\$	996.00	\$	966.00
	35	Front door protector LH	1	Necessary	\$	85.50	\$	85.50
	36	Front driver seat belt	1	Activated-Necessary	\$	599.80	\$	599.80
	37	Front passenger seat belt	1	Activated-Necessary	\$	599.80	\$	599.80
	38	Front air bag control module XIVA	1	Activated-Necessary	S	1,266.70	\$	1,266.70 × nv
	39	Rear door protector LH X	1	Damaged	S	85.80	\$	85.80 ×
	40	Rear fender RH V	1	Grazed/Dented	S	795.10	\$	795.10
	41	Rear fender under shield RH	1	Torn	S	98.70	\$	98.70
	42	Rear bumper SES SES	1	Grazed/Deformed	S	573.70	\$	597.70
	43	Rear bumper side retainer JaR @ \$57.15 015	2	RH only (Damaged)	\$	114.30	\$	57.15
	44	Rear tail lamp RH ×(SVC)	1	Serviceable	\$	403.90		~
		3			\$	25,991.43	\$	19,160.31512275.8
				Less 25%	\$	6,497.86	\$	4,790.08
					\$	19,493.57	\$	14,370.23
					20			7.444.2011.00

Our Ref : TP/GAS/SKA5577J/8242

						28515.86		
			Total Pa	arts and Labour	s	28,497.81	s	21,634.47
				Labour Total:	S	6,980.00	\$	5,240.00
	71	To supply rear windscreen sealant. Ale			<u>s</u>	50.00	\$	50.00 \$ 40
	70	To provide towing service charge.			\$	100.00	\$	100.00 \$80
	69	To conduct wheel alignment balancing.			s	120.00	\$	120.00 \$70
		front suspension, control system to enable necessame.	essary re	pairs, check and refit	\$	450.00	\$	350.00 \$200
•	68	Remove & replace under carriages damaged p	oarts, disn	mantle & reassemble				
(67	To transfer front door mechanism & compone			\$	80.00	\$	40.00
7538	66	To drill holes & reinstall rear bumper reverse	sensor.		\$	80.00	\$	60.00 \$30
	2500	headlights, audio system & centre locking sys	tem for p		\$	100.00	\$	50.00
	65	Check wiring, lighting, electrical circuit, reco						100 cm
	64	To carry out diagnostic checks & reset.			\$	380.00	\$	250.00 \$ 100
		hose, pipe, wire, to enable necessary repairs,			\$	250.00	\$	180.00 \$150
	63	To remove, replace safety belt, & refit trims			100		====	
	62	To remove & reinstall rear windscreen to assi	st repair.		\$	120.00	\$	120.00 \$80
		body structure panel.	,	mary ungn	\$	450.00	S	350.00 \$200
	61	To mount vehicle onto chassis alignment ben	ch, straio	hten and re-alion	9.	100.00	Φ	150.00
	60	To cavity preservation on all affected areas.	and retini	un con gas.	\$	180.00	\$	150.00
	59	Remove & reinstall air-con system, vacuum a	and refill	air-con eas	\$ \$	2,500.00 120.00	\$ \$	1,800.00 \$ \$0
		panel, panel beating, cutting, welding, remov fittings to facilitate repairs, reshape, refit, ad all relevant parts.	e & reins	stall necessary		2 500 00		1,800.00 \$ 1400
	58	paint materials. Remove damaged parts, knock out dents, stra	ighten, ja	ack out damaged	\$	2,000.00	S	1,500.00 \$1200
•	57	Spray painting on above new & repaired part	s includir	ng supply of		المعادلة عامل الهال	144	
1	C)	LABOUR CHARGES & MISC					-	\$1915.50
		AND SANDARD POR SANDARD STATE OF SANDARD S		Parts Total :	\$	21,517.81	S	16.394.47
	56	Auto transmission oil res	4 litres	Necessary	\$	140.00	S	140.00 \$ 100
	55	Rear windscreen glass moulding	1 501	Necessary	\$	146.74	\$	24.00 146.74 \$ 120
	54	Rear fender under shield clips	l set	Necessary	\$	28.00 24.00	2	28.00
	53	Rear bumper clips	l set	Necessary	\$ \$	380.00	\$	380.00
	52	Rear sport rim RH S	1	Grazed/Cracked	\$	760.00	S	760.00
	51	Front sport rim L/R @ \$380.00 Str	2	Grazed/Cracked	5	360.00	S	360.00
	50	Pront tyre L/R (Falken 195/65R15)	1 2	Necessary Punctured	\$	34.00	\$	34.00
	49	Front fender 'VVT-I' emblem LH nel		-555	\$	28.00	\$	28.00
	48	Front fender inner liner clips LHNEL	l set	Necessary		53.50	\$	53.50
	47	Front bumper emblem	1	Necessary Necessary	\$ \$	42.00	S	42.00
	45 46	Front bumper clips Net	l set	Necessary	\$	28.00	\$	28.00

FINAL LUMP SUM ADJUSTMENT



\$ 17,300.00 LIST HEM \$9206.91 Smet : \$1915.50 Labour : \$3800

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation Total: \$149224\3

Our Ref : TP/GAS/SKA5577J/8242

POINT OF IMPACT

The impact was confined to the rear off side & front both side portion of the vehicle. The damages appeared to be consistent as per the accident report statement. Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$17,300.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully KTO Automobile Assessors

Ong Ah Keng (CAE, AMIMI, MSAAA)

Automotive Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internati	ionale Des Experts En Automo	obile
sol	MPO INSURANCE	SINGAPORE PL	Ref : CS3/SMO19016	112/Fyf3s2-1
#05	RAFFLES PLACE -01/06 GAPORE LAND TO	OWERSINGAPORE 048623	Date: 07-01-2020 Code: SMO	
1.		Policy Particulars	:- THIRD PARTY CLAIM	1
	Insured Veh.	XD 5732H	Veh. Inspected	SKA 5577J
	Policy No.	D18MTHCVE003051	Coverage (\$)	0.00
	Claim No.	CMTD1904277	Excess (\$)	0.00
	Assign From	GNOH PAU LOONG	Assign Date	11/12/2019
2.		Vehicle Part	iculars & Condition	State The College Co.
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053ZEE106176703	Colour	BEIGE
	Odometer	148256	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Condi	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FALKEN	4 mm
	L/H Front Tyre	195/65 R15	FALKEN	4 mm
	R/H Rear Tyre	195/65 R15	FALKEN	4 mm
	L/H Rear Tyre	195/65 R15	FALKEN	4 mm
4.		Descript	ion of Damages	

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND N/S PORTION, REAR O/S PORTION, N/S AND O/S BODY.

DAMAGES SEE DETAILS.

5.	General Information				
	Accident Date	09/09/2019	Inspection Date	11/09/2019	
	Survey held at	BLK 7 SIN MING IND	-80		
	Repairer	GUAN AUTO SERVIC	CE		

5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Estimate Days of Repair 5b. ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 5577J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
- 1	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	645.80	540.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	318.00	
2	FRONT BUMPER FOG LAMP L/R @ \$184.20	N/S MISSING	368.40	184.20
2	FRONT BUMPER FOG LAMP COVER L/R @ \$64.00	N/S MISSING	128.00	64.00
	FRONT BUMPER BRACKET L/R @ \$43.80	N/S MISSING	87.60	43.80
2	FRONT BUMPER SIDE RETAINER L/R @ \$38.17	N/S MISSING	76.34	38.17
1	FRONT BUMPER GRILLE	NOT NECESSARY	159.00	
1	FRONT RADIATOR GRILLE	NOT NECESSARY	230.70	
2	FRONT HEADLAMP L/R @ \$794.00	N/S BROKEN	1,588.00	580.00
1	FRONT BONNET	DENTED	894.09	750.00
2	FRONT BONNET HINGE L/R @ \$68.00	BENT	136.00	136.00
1	FRONT RADIATOR SUPPORT	BENT	1,954.00	873.81
1	FRONT WHEEL HOUSE PANEL RH	NOT NECESSARY	1,955.00	
1	FRONT FOLDER SIDE MIRROR LH	SHORT CIRCUIT	497.00	360.00
1	FRONT FENDER LH	DISTORTED	579.50	281.45
1	FRONT FENDER QUARTER GARNISH LH	CUT	58.00	58.00
1	FRONT FENDER INNER LINER LH	сит	98.20	98.20
1	FRONT FUSE & RELAY BOX	CRACKED	498.00	380.00
1	FRONT INTAKE AIR TUBE	BROKEN	159.00	159.00
1	FRONT WIPER WASHER TANK ASSY	CRACKED	257.00	150.00
1	AUTO TRANSMISSION MOUNTING	DAMAGED	151.10	151.10
1	ENGINE MOUNTING BACK	DAMAGED	161.10	161.10
1	FRONT AIR CLEANER TOP COVER	SERVICEABLE	195.20	
1	FRONT AIR CLEANER LOWER HOUSING	NOT NECESSARY	490.00	
2	FRONT LOWER ARM L/R @ \$395.20	BENT	790.40	790.40
1	SET FRONT SHOCK ABSORBER L/R	BENT	590.20	590.20
2	FRONT SHOCK ABSORBER MOUNTING @ \$82.10	NECESSARY	164.20	164.20
1	FRONT DIVE SHAFT RH	SERVICEABLE	1,395.00	
1	FRONT DRIVE SHAFT LH	BENT	957.00	740.00
1	FRONT CROSS MEMBER SUB ASSY	SERVICEABLE	2,942.00	
2	FRONT WHEEL HUB BEARING L/R @ \$210.50	NECESSARY	421.00	340.00

Report Ref No. CS3/SMO19016112/Fyf3s2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT DOOR LH	DENTED	928.00	928.00
1	FRONT DOOR TRIM BOARD LH	NOT NECESSARY	499.30	85
2	FRONT ROCKER TRIM PANEL L/R @ \$498.00	CUT / CRACKED	996.00	966.00
1	FRONT DOOR PROTECTOR LH	NECESSARY	85.50	85.50
1	FRONT DRIVER SEAT BELT	JAMMED	599.80	599.80
1	FRONT PASSENGER SEAT BELT	JAMMED	599.80	599.80
1	FRONT AIR BAG CONTROL MODULE	NOT NECESSARY	1,266.70	
1	REAR DOOR PROTECTOR LH	NOT NECESSARY	85.80	
1	REAR FENDER RH	DENTED	795.10	795.10
1	REAR FENDER UNDER SHIELD RH	TORN	98.70	98.70
1	REAR BUMPER	DEFORMED / SCRATCHED	597.70	597.70
2	REAR BUMPER SIDE RETAINER L/R @ \$57.15	O/S DISTORTED	114.30	57.15
1	REAR TAIL LAMP RH	SERVICEABLE	403.90	
	LESS 25% DISCOUNT		-6,503.86	-3,090.35
			19,511.57	9,271.03
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	28.00	28.00
1	FRONT BUMPER TOP SEAL (SN)	NOT NECESSARY	42.00	
1	FRONT BUMPER EMBLEM (\$N)	NECESSARY	53.50	53.50
1	SET FRONT FENDER INNER LINER CLIPS LH (SN)	NECESSARY	28.00	28.00
1	FRONT FENDER 'VV-I' EMBLEM LH (SN)	NECESSARY	34.00	34.00
2	FRONT TYRE L/R (FALKEN 195/65R15) (SN)	PUNCTURE	360.00	360.00
2	FRONT SPORT RIM L/R @ \$380.00 (SN)	SCRATCHED / CRACKED	760.00	760.00
1	REAR SPORT RIM RH (SN)	SCRATCHED	380.00	380.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	28.00	28.00
1	SET REAR FENDER UNDER SHIELD CLIPS (SN)	NECESSARY	24.00	24.00
1	REAR WINDSCREEN GLASS MOULDING (SN)	NECESSARY	146.74	120.00
4	LITRES AUTO TRANSMISSION OIL (SN)	NECESSARY	140.00	100.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
			2,074.24	1,955.50

Report Ref No. CS3/SMO19016112/Fyf3s2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR		1.0000	
	SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS.		2,000.00	1,200.00
	REMOVE DAMAGED PARTS, KNOCK OUT DENTS, STRAIGHTEN, JACK OUT DAMAGED PANEL, PANEL BEATING, CUTTING, WELDING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, RESHAPE, REFIT, ADJUST, REPLACE AND REALIGN ALL RELEVANT PARTS.		2,500.00	1,400.00
	REMOVE & REINSTALL AIR-CON SYSTEM, VACUUM AND REFILL AIR-CON GAS.		120.00	80.00
	TO CAVITY PRESERVATION ON ALL AFFECTED AREAS.		180.00	80.00
	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH, STRAIGHTEN AND RE-ALIGN BODY STRUCTURE PANEL.		450.00	200.00
	TO REMOVE & REINSTALL REAR WINDSCREEN TO ASSIST REPAIR.		120.00	80.00
	TO REMOVE, REPLACE SAFETY BELT, & REFIT TRIM GARNISH, INTERIOR UPHOLSTERY, HOSE, PIPE, WIRE, TO ENABLE NECESSARY REPAIRS, CHECK, REFIT AS SAME.		250.00	150.00
	TO CARRY OUT DIAGNOSTIC CHECKS & RESET.		380.00	100.00
	CHECK WIRING, LIGHTING, ELECTRICAL CIRCUIT, RECONNECTION WIRE SOCKET, FOCUS HEADLIGHTS, AUDIO SYSTEM & CENTRE LOCKING SYSTEM FOR PROPER FUNCTION.		100.00	50.00
	TO DRILL HOLES & REINSTALL REAR BUMPER REVERSE SENSOR.		80.00	30.00
	TO TRANSFER FRONT DOOR MECHANISM & COMPONENTS.		80.00	40.00
	REMOVE & REPLACE UNDER CARRIAGE DAMAGED PARTS, DISMANTLE & REASSEMBLE FRONT SUSPENSION, CONTROL SYSTEM TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		450.00	200.00
	TO CONDUCT WHEEL ALIGNMENT BALANCING.		120.00	70.00
	TO PROVIDE TOWING SERVICE CHARGE.		100.00	80.00
			6,930.00	3,760.00
- 55	GRAND TOTAL		28,515.81	14,986.53



Page No.:4 of 4

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	11,900.00
--	-----------

Report Ref No. CS3/SMO19016112/Fyf3s2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.