



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 9796G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR LH	BUCKLED	1,216.80	1,216.80
1	FRONT DOOR FRAME PROTECTIVE STICKER RH	NECESSARY	67.20	67.20
1	REAR DOOR LH	BUCKLED	1,196.40	1,196.40
1	REAR DOOR FRAME PROTECTIVE STICKER LH	NECESSARY	67.20	67.20
1	RUNNING BOARD PANEL LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-509.52	-509.52
			2,038.08	2,038.08
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE & REPLACE ,REPAIR ,READJUST FRONT DOOR LH,REAR DOOR LH ,RUNNING BOARD PANEL LH & ETC.INCLUSIVE OF THE REPAIR OF RUNNING BOARD PANEL LH.		500.00	400.00
	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR LH ,REAR DOOR LH,INNER MECHANISM & ETC .BACK TO ORIGINAL OPERATIONS.}		220.00	120.00
	LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC.BACK TO PROPER CONDITIONS.}		80.00	-
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH ,REAR DOOR LH ,RUNNING BOARD PANEL & ETC.		800.00	600.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.	NOT NECESSARY	200.00	-
			1,800.00	1,120.00
	GRAND TOTAL		3,838.08	3,158.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CC4/FC119021818/Gka3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.