

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19021823/KGA3Q2

Date: 29/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00017101

Claimant
Vehicle No : SLP402Y **Insured Vehicle No :** SKV2620B

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 1201900039134

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP402Y		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS049586
Reg. Date:	25/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU103559179
Colour:	Metallic Silver	Odometer:	213925 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 8 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,442.82	5,626.88	1,815.94	24.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	960.00	970.00	50.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,372.82	6,586.88	2,785.94	29.72
+ GST 7.00/7.00% (\$\$)	656.10	461.08	195.02	29.72
Nett Amount (\$\$)	10,028.92	7,047.96	2,980.96	29.72
+ Loss of Use (6.0 x S\$70.00/day) (\$\$)		420.00		
+ Doc/Search Fee (\$\$)		7.48		
Nett Liability (\$\$)		7,475.44		
Global Sum Settlement (\$\$)		7,470.00		

INSPECTION

Date of Assignment: 11/12/2019

Date Inspected: 11/12/2019 Inspected At:

Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP402Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cracked	2,531.60 FL	*2,531.60 FL
2	1		*FRONT BUMPER	Buckled	450.80 FL	*450.80 FL
3	10		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
4	1		*FRONT BUMPER REINFORCEMENT -UPPER	Repair	711.50 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	107.20 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	107.20 FL	*107.20 FL
7	1		*FRONT BUMPER UPPER GRILLE	Serviceable	321.90 FL	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Serviceable	148.60 FL	*- FL
9	1		*FRONT BUMPER EMBLEM	Necessary	87.10 FL	*87.10 FL
10	1		*FRONT BUMPER TOW COVER LH	Serviceable	25.70 FL	*- FL
11	1		*FRONT BUMPER SPONGE -UPPER	Cracked	89.81 FL	*89.81 FL
12	1		*FOG LAMP LH	Serviceable	910.70 FL	*- FL
13	1		*LH FRONT FENDER	Buckled	868.70 FL	*868.70 FL
14	1		*LH FRONT FENDER UNDERSHIELD	Cracked	195.60 FL	*195.60 FL
15	10		*LH FRONT FENDER UNDERSHIELD CLIP	Necessary	25.00 FL	*25.00 FL
16	1		*LHF FENDER WORDING HYBRID	Necessary	44.17 FL	*44.17 FL
17	1		*LH FRONT RIM	Dented	1,555.10 FL	*1,555.10 FL
18	1		*LH FRONT HUB CAB	Serviceable	195.65 FL	*- FL
19	1		*LH FRONT KNUCKLE ARM	Bent	471.55 FL	*471.55 FL
20	1		*LH FRONT BEARING HUB	Necessary	543.23 FL	*543.23 FL
21	1		*LH FRONT LOWER ARM	Distorted	492.65 FL	*492.65 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,923.76	7,502.51
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,480.94	1,875.63
Total Parts (\$\$)	7,442.82	5,626.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,SUPPORT PANEL ,LHF FENDER)	New	800.00	400.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,SUPPORT PANEL ,LHF FENDER)	New	800.00	400.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TUFF COAT	New	100.00	30.00
5	TO DO WHEEL ALIGNMENT	New	120.00	60.00
6	TOWING	New	60.00	50.00
Gross Labour Cost (S\$)			1,930.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >