

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2005408

INV Date 05/08/2020

Reference CC6/CTI19021829/Aba3n2

Code CT

PROFESSIONAL SERVICE FEE

Vehicle No. SKG 9209P

Insured Veh. SKZ 880J

Claim No. SNM19D2058/9

Policy No. DMPCSN30269819000

Accident Date 07/12/2019

Inspection Date 10/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
CHIN	CHINA TAIPING INSURANCE (S) PTE LTD Ref : CC6/CTI19021829/Aba3n2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 05-08-2020 Code: CTI			
1.		Policy Particulars :	- THIRD PARTY CLAIM		
	Insured Veh.	SKZ 880J	Veh. Inspected	SKG 9209P	
	Policy No.	DMPCSN30269819000	Coverage (\$)	0.00	
	Claim No.	SNM19D2058/9	Excess (\$)	0.00	
	Assign From		Assign Date	10/12/2019	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA FORTUNER	c.c	2694	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	MR0ZX69G200020760	Colour	BLACK	
	Odometer	126115	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	265/50 R20	YOKOHAMA	6 mm	
	L/H Front Tyre	265/50 R20	YOKOHAMA	6 mm	
	R/H Rear Tyre	265/50 R20	YOKOHAMA	6 mm	
	L/H Rear Tyre	265/50 R20	YOKOHAMA	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	07/12/2019	Inspection Date	10/12/2019	
	Survey held at	PRO-JEX V2D AUTO PTE LTD			
		25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB SINGAPORE 417800			
5a.			emarks		
		ON WAS CONDUCTED ON A"WIT		REPAIRS	
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	3 Working Days		
	•		1		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 9209P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	980.00	678.00
1	SET REAR BUMPER CLIPS	NECESSARY	100.00	30.00
1	REAR BUMPER SPONGE	NOT NECESSARY	25.00	-
1	REAR BUMPER REINFORCEMENT	BENT	350.00	350.00
2	REAR BUMPER SIDE RETAINERS @\$95.00	NECESSARY	190.00	190.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	850.00	-
1	REAR END PANEL GARNISH	DEFORMED	258.00	258.00
2	REAR BUMPER REFLECTOR @\$105.00	NOT NECESSARY	210.00	-
1	TAIL GATE	TO REPAIR SEE LABOUR	1,254.00	-
1	TAIL GATE LOCK	NOT NECESSARY	357.00	-
1	TAIL GATE LATCH	NOT NECESSARY	85.00	-
1	TAIL GATE WEATHERSTRIP	NOT NECESSARY	280.00	-
1	TAIL GATE LOGO	NECESSARY	89.00	89.00
1	TAIL GATE EMBLEM 'TOYOTA'	NECESSARY	83.00	83.00
1	TAIL GATE EMBLEM 'FORTUNER '	NECESSARY	86.00	86.00
1	TAIL GATE EMBLEM 'V '	NECESSARY	35.00	35.00
1	REAR EXHAUST PIPE	NOT NECESSARY	620.00	-
1	REAR EXHAUST PIPE CHROME	NOT NECESSARY	87.00	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	350.00	-
1	REAR FLOOR PANEL	NOT NECESSARY	1,200.00	-
1	REAR W/S GLASS MOULDING	NOT NECESSARY	230.00	-
	LESS 25% DISCOUNT		-	-449.75
			7,719.00	1,349.25
	SPECIAL NETT ITEMS			
1	PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSORS (SN)	DAMAGED	380.00	200.00
			480.00	200.00
	LABOUR			
	CHASSIS ALIGNMENT.	NOT NECESSARY	300.00	-

Report Ref No. CC6/CTI19021829/Aba3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	R&R REAR W/S GLASS .	NOT NECESSARY	200.00	-
	R&R REAR EXHAUST PIPE .	NOT NECESSARY	180.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND TAIL GATE.		1,000.00	300.00
	SPRAY PAINTING .		800.00	400.00
			2,480.00	700.00
	GRAND TOTAL		10,679.00	2,249.25

(TO ITS PRE-ACCIDENT CONDITION)	0.00
(10 110 TRE-ADDIDENT CONDITION)	

Report Ref No. CC6/CTI19021829/Aba3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKG 9209P

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKG 9209P

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315







