

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19021892/AVF3E2

Date: 21/05/2020

REFERENCE

Insured/Claimant:	PEH CHAI PENG	Policy No:	2100445230	
Date of Loss:	07/12/2019	Nature of Claim:	OD	Claim No: 2938658690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY1128U			
Make & Model:	AUDI A3, 1.4 TFSI (A)	Engine No:	CZC504868	
Reg. Date:	30/12/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8V5G1052582	
Colour:	Maroon	Odometer:	60201 km	
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$68,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,233.60	4,264.16	6,969.44	62.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,002.00	5,102.00	3,900.00	43.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,235.60	9,366.16	10,869.44	53.71
+ GST 7.00/7.00% (S\$)	1,416.49	655.63	760.86	53.71
Nett Amount (S\$)	21,652.09	10,021.79	11,630.30	53.71

INSPECTION

Date of Assignment:	12/12/2019		
Date Inspected:	12/12/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	148.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	148.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	187.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	35.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	99.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	637.00 FS	*509.20 FS
9	1		*RADIATOR GRILLE - COVER	Not Necessary	89.00 FS	*- FS
10	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	660.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	125.00 FS	*- FS
12	1		*FOAM FILLER PIECE COVER	Cracked	51.00 FS	*40.40 FS
13	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	182.00 FS	*- FS
14	1		*BONNET	Repair	2,898.00 FS	*- FS
15	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
16	1		*BONNET CATCH HOOK	Not Necessary	81.00 FS	*- FS
17	2		*BONNET STRIKER - LH / RH	Not Necessary	200.00 FS	*- FS
18	1		*BONNET EDGE PROTECTION - FRONT	Necessary	25.00 FS	*19.92 FS
19	2		*BONNET LID LOCK	Not Necessary	367.00 FS	*- FS
20	1		*BONNET BOWDEN CABLE	Not Necessary	53.00 FS	*- FS
21	1		*WATER BOX ADAPTER SEAL - LH	Not Necessary	12.00 FS	*- FS
22	1		*BONNET CATCH HOOK	Not Necessary	58.00 FS	*- FS
23	1		*CAUTION SIGN STICKER	Necessary	12.00 FS	*9.76 FS
24	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
25	1		*HEADLIGHT - LH	Cracked	1,825.00 FS	*1,460.00 FS
26	1		*LIFT CYLINDER - LH	Damaged	181.00 FS	*144.80 FS
27	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	22.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	11.00 FS	*- FS
29	1		*SUNDRIES	Necessary	300.00 FS	*23.36 FS
30	1		*FRONT LOCK CARRIER	Broken	547.60 FS	*547.60 FS
31	1		*MIX COOLANT	Not Necessary	84.00 FS	*- FS
32	1		*NO PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,233.60 4,264.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
5	TO REMOVE AND REINSTALL AIRCOND CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
6	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION	New	2,800.00	1,250.00
Gross Labour Cost (\$\$)			9,002.00	5,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >