



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCL 89X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOTTOM ENGINE COVER	TORN	1,200.00	1,200.00
1	BOTTOM ENGINE COVER LH	CRACKED	980.00	980.00
1	BOTTOM ENGINE COVER RH	CRACKED	980.00	980.00
1	BOTTOM COVER LH	DENTED	85.00	85.00
1	BOTTOM COVER RH	DENTED	85.00	85.00
1	FRONT SUB FRAME	BENT	11,550.00	11,550.00
1	FRONT BOTTOM REINFORCEMENT	DENTED	1,200.00	1,200.00
1	REINFORCEMENT FOR CROSS MEMBER	BENT	1,800.00	1,800.00
1	REINFORCEMENT PLATE	BENT	1,350.00	1,350.00
1	HEAT SHIELD SUB FRAME	DENTED	120.00	120.00
1	TRACK CONTROL LOWER ARM LH	DISTORTED	3,280.00	3,280.00
1	TRACK CONTROL LOWER ARM RH	DISTORTED	3,280.00	3,280.00
1	TRACK CONTROL ARM SPOILER LH	SERVICEABLE	220.00	-
1	TRACK CONTROL ARM SPOILER RH	SERVICEABLE	220.00	-
1	TRACK CONTROL ARM UPPER	BENT	2,350.00	2,350.00
8	BOLT WITH SHOULDER	NECESSARY	120.00	120.00
8	12-PT SOCKET SHOULDERED NUT SELF-LOCKING	NECESSARY	200.00	200.00
2	SELF LEVELING SENSOR	SERVICEABLE	2,400.00	-
2	HYDRO MOUNTING	CRACKED	2,400.00	2,400.00
2	SUSPENSION STRUT BEARING	NECESSARY	380.00	380.00
2	STOP WASHER	SERVICEABLE	140.00	-
2	WHEEL SPORT RIM (FRONT) / SIZE 19"	DENTED	16,000.00	5,200.00
2	WHEEL SPORT RIM (REAR) / SIZE 19"	DENTED	16,800.00	5,200.00
8	BOLT	NECESSARY	80.00	80.00
2	ENGINE MOUNT	CRACKED	2,300.00	2,300.00
1	GEAR BOX MOUNT LH	CRACKED	350.00	350.00
1	GEAR BOX MOUNT RH	CRACKED	350.00	350.00
1	ENGINE MOUNTING SUPPORT LH	CRACKED	420.00	420.00
1	ENGINE MOUNTING SUPPORT RH	CRACKED	420.00	420.00

Report Ref No. CS/AWA19021905/Kvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-7,106.00	-4,568.00
			63,954.00	41,112.00
	<u>SPECIAL NETT ITEMS</u>			
2	PIRELLI ZERO TYRES x 19" (REAR) (SN)	SERVICEABLE	960.00	-
			960.00	-
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS.		2,500.00	2,000.00
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)		250.00	200.00
	TO CHECK, REMOVE & REFIT CROSS MEMBER. }		350.00	-
	TO REMOVE, RENEW & REFIT UNDER CARRIAGE X 04. }		1,000.00	900.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	120.00
	TO REMOVE & REFIT ENGINE FOR NECESSARY WORKS. (ADDITIONAL)	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT TYRES X 02. (ADDITIONAL)	NOT NECESSARY	40.00	-
			4,410.00	3,220.00
	GRAND TOTAL		69,324.00	44,332.00
	RECOMMENDED COST OF REPAIRS			44,332.00
	LESS EXCESS			-2,500.00
	NETT LIABILITY			41,832.00

Report Ref No. CS/AWA19021905/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.