

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021916/QRS3Q2

Date: 18/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900120841

Claimant
Vehicle No : SLB4487A **Insured Vehicle No :** SDU40B

Date of Loss: 12/12/2019 Nature of Claim: TP Claim No: 5861796335SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4487A		
Make & Model:	TOYOTA AXIO, 1.5 (A)	Engine No:	2NR8532025
Reg. Date:	07/04/2016 (Man. Year: 2015)	Chassis No:	NRE1610011710
Colour:	Silver	Odometer:	592401 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,482.88	2,692.57	1,790.31	39.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,500.00	700.00	31.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,682.88	4,192.57	2,490.31	37.26
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	6,682.88	3,350.00	3,332.88	49.87
+ GST 7.00/7.00% (S\$)	467.80	234.50	233.30	49.87
Nett Amount (S\$)	7,150.68	3,584.50	3,566.18	49.87
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,886.50		

INSPECTION

Date of Assignment: 12/12/2019

Date Inspected: 12/12/2019 Inspected At:

Lion City Rentals Pte Ltd
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,059.84 FL	*900.00 FL
2	1		*REAR BOOT COROLLA EMBLEM	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BOOT AXIO EMBLEM	Necessary	30.00 FL	*30.00 FL
4	1		*REAR BOOT WEATHERSTRIP	Cut	226.00 FL	*187.00 FL
5	1		*REAR BOOT LOCK	Jammed	418.00 FL	*174.00 FL
6	1		*REAR BOOT LOCK CATCH	Bent	60.00 FL	*60.00 FL
7	1		*R/L TAILLAMP	Cracked	850.00 FL	*548.00 FL
8	1		*R/R TAILLAMP	Serviceable	850.00 FL	*- FL
9	1		*REAR END PANEL	Dented	850.00 FL	*602.40 FL
10	1		*REAR END PANEL TOP COVER	Dented	320.00 FL	*218.20 FL
11	1		*REAR BUMPER	Dented	780.00 FL	*598.50 FL
12	1		*REAR BUMPER RH RETAINER	Broken	180.00 FL	*96.00 FL
13	1		*REAR BUMPER LH RETAINER	Broken	180.00 FL	*96.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,943.84	3,580.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,460.96	887.53
Total Parts (\$\$)	4,482.88	2,692.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING OUT REAR BOOT ,REAR END PANEL,AND REAR BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS,ALSO TO STRAIGHTEN REAR SPARE TYRE PANEL	New	1,200.00	900.00
2	TO RESPRAY REAR BUMPER ,R/L FENDER ,REAR BOOT ,END PANEL AND SPARE TYRE PANEL (PEARL PAINT)	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,200.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >