

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021918/UEA3Q2

**Date:** 23/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900152468

**Claimant**  
**Vehicle No :** SLF9893G **Insured Vehicle No :** SDU7789D

Date of Loss: 08/12/2019 Nature of Claim: TP Claim No: 2007083664SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLF9893G</b>		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	1NZE712819
Reg. Date:	21/11/2014 (Man. Year: 2014)	Chassis No:	NCP815216230
Colour:	Silver	Odometer:	128276 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,910.45	0.00	4,910.45	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	800.00	1,430.00	64.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,140.45</b>	<b>800.00</b>	<b>6,340.45</b>	<b>88.80</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	499.83	56.00	443.83	88.80
<b>Nett Amount (\$\$)</b>	<b>7,640.28</b>	<b>856.00</b>	<b>6,784.28</b>	<b>88.80</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (\$\$)</b>		240.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,098.00</b>		

### INSPECTION

Date of Assignment: 12/12/2019

Date Inspected: 12/12/2019 Inspected At:

Abwin Service Pte Ltd (HQ)  
No. 8 Kaki Bukit Avenue 4, #07-48  
Premier@Kaki Bukit Gate 2  
Singapore 415875

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Repair	622.74 F	*- F
2	1		*FRONT BUMPER	Repair	1,337.80 F	*- F
3	1		*SPORTS RIM	Not Necessary	1,201.11 F	*- F
4	1		*HEAD LAMP LH	Not Necessary	1,339.70 F	*- F
5	1		*FRONT LH SIDE RETAINER	Not Necessary	67.30 F	*- F
6	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	291.80 F	*- F
7	10		*BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>4,910.45</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	800.00	200.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	600.00
3	TO DISMANTLE ,REPLACE AND /OR REPAIR SPORTS RIM AND TYRE COMPONENTS & BALANCING	New	200.00	0.00
4	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	180.00	0.00
5	TO APPLY TUFF COAT ON AFFECTED AREAS	New	150.00	0.00
6	TO CHECK WIRING	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,230.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >