

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021919/DBA3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900155767

Claimant
Vehicle No : SH8121P **Insured Vehicle No :** SMN8352D

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 1122954252SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8121P		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU132631
Reg. Date:	11/12/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU122069
Colour:	Blue	Odometer:	81184 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,563.92	11,628.88	4,935.04	29.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,600.00	1,390.00	46.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,553.92	13,228.88	6,325.04	32.35
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	19,553.92	10,000.00	9,553.92	48.86
+ GST 7.00/7.00% (S\$)	1,368.77	700.00	668.77	48.86
Nett Amount (S\$)	20,922.69	10,700.00	10,222.69	48.86
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Car Rental (9.0 x S\$125.19/day) (S\$)		1,126.71		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,278.71		
Global Sum Settlement (S\$)		12,250.00		

INSPECTION

Date of Assignment: 11/12/2019

Date Inspected: 12/12/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A,
#03-19 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,409.10 FL	*1,409.10 FL
2	1		*FRONT BUMPER COVER	Torn	418.30 FL	*418.30 FL
3	1		*FRONT BUMPER SPONGE	Torn	86.90 FL	*86.90 FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	1,075.10 FL	*1,075.10 FL
5	1		*FRONT BUMPER ABSORBER	Not Necessary	86.90 FL	*- FL
6	1		*FRONT BUMPER GRILLE (LH)	Dislodged / Broken	186.90 FL	*186.90 FL
7	1		*FRONT BUMPER CENTRE MOULDING	Not Necessary	188.00 FL	*- FL
8	1		*FRONT BUMPER MOULDING (LH)	No such part	93.60 FL	*- FL
9	1		*FRONT BUMPER LOWER STIFFNER	Bent	85.10 FL	*85.10 FL
10	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
11	1		*FRONT BUMPER BRACKET TOP (LH)	Broken	35.00 FL	*35.00 FL
12	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	28.00 FL	*- FL
13	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
14	1		*FRONT BUMPER CENTRE GRILLE	No such part	318.80 FL	*- FL
15	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	398.00 FL	*- FL
16	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
17	1		*HEADLAMP (LH)	Cut	1,198.80 FL	*1,198.80 FL
18	1		*DAY LIGHT ,LH	Mtg Broken	642.50 FL	*642.50 FL
19	1		*DAY LIGHT WIRE ,LH	Not Necessary	585.50 FL	*- FL
20	1		*EMBLEM -BLUE DRIVE (LH)	Necessary	26.60 FL	*26.60 FL
21	1		*RADIATOR	Bent	510.50 FL	*510.50 FL
22	1		*RADIATOR SHROUD	Not Necessary	275.50 FL	*- FL
23	1		*FRONT FENDER (LH)	Repair	490.70 FL	*- FL
24	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
25	1		*FRONT WHEEL RIM (LH)	Distorted	1,124.20 FL	*1,124.20 FL
26	1		*FRONT WHEEL HUB CAP (LH)	Cut	346.40 FL	*346.40 FL
27	1		*FRONT WHEEL BEARING	Damaged	454.00 FL	*454.00 FL
28	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	372.50 FL	*372.50 FL
29	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	206.90 FL	*- FL
30	1		*FRONT SHOCK ABSORBER FORK (LH)	Not Necessary	206.90 FL	*- FL
31	1		*FRONT SUSPENSION UPPER ARM (LH)	Not Necessary	244.30 FL	*- FL
32	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	936.70 FL	*- FL
33	1		*RACK & PINION ASSY	Damaged	887.40 FL	*887.40 FL
34	1		*STG TIE END	Bent	91.50 FL	*91.50 FL
35	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	296.80 FL	*296.80 FL
36	1		*KNUCKLE ARM (LH)	Distorted	363.60 FL	*363.60 FL
37	1		*ENGINE CROSSMEMBER	Not Necessary	1,803.90 FL	*- FL
38	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
39	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS
40	1		*HEADLAMP (RH)	Cracked	1,198.80 FL	*1,198.80 FL
41	1		*FRONT FENDER SHIELD (LH)	Deformed	114.70 FL	*114.70 FL
42	1		*ENGINE UNDER COVER	Torn / Cracked	469.40 FL	*469.40 FL
43	1		*FRONT BUMPER REINFORCEMENT ABSORBER ,LH	Dented	180.00 FL	*180.00 FL
44	1		*FRONT BUMPER LOWER GRILLE	Dislodged / Broken	223.70 FL	*223.70 FL
45	1		*FRONT BUMPER LOWER GRILLE MOULDING	Dislodged / Broken	93.60 FL	*93.60 FL
46	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,625.90 14,511.10
- List Item Discount on L Items 20.00/20.00% (\$\$) 4,061.98 2,882.22

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	16,563.92 11,628.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	50.00	30.00
4	TOWING CHARGE	New	90.00	0.00
5	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
6	FRONT WHEEL ALIGNMENT	New	120.00	60.00
7	REMOVE /REFIX AIRCON & REFILL GAS	New	150.00	80.00
8	RE-SET FRT ABS SYSTEM }	New	200.00	280.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (\$\$)			2,990.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >