

REPAIR ESTIMATE*

AIG

[illegible]

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8121P (Supplementary)


DATE : 12.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) <i>crack</i>			\$ 1,198.80
	Front Fender Shield (LH) <i>detuner</i>			\$ 114.70
	Engine Under Cover <i>turn / crack</i>			\$ 469.40
	Front Bumper Reinforcement Absorber, LH <i>Dent</i>			\$ 180.00
	Front Bumper Lower Grille <i>dislodged / broken</i>			\$ 223.70
	Front Bumper Lower Grille Moulding <i>dislodged / broken</i>			\$ 93.60
	Radiator Inverter <i>By</i>			\$ 884.80
SUB TOTAL				\$ 3,165.00
LESS 20%				\$ 633.00
DISCOUNTED TOTAL				\$ 2,532.00
<i>Ryan</i> <i>LKK Auto</i> 				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

71111111

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 8121 P

Technician:

Mileage: 81184

Time Printed 12.12.19 3:21 PM

HYUNDAI IONIQ

Front : Left

Actual	BEFORE	Specified Range
-0°34'		-3°00' 3°00'
4°05'		-0°19' 5°41'
3°17'		-1°30' 1°30'
14°13'		
13°39'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°16'		-3°00' 3°00'
4°05'		-0°19' 5°41'
0°02'		-1°30' 1°30'
16°07'		
15°51'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	-0°19'		-3°00' 3°00'
Cross Caster	0°00'		-3°00' 3°00'
Cross SAI	-1°54'		-3°00' 3°00'
Total Toe	3°19'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
0°04'		-3°30' 2°30'
0°10'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°05'		-3°30' 2°30'
-0°34'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	0°09'		-3°00' 3°00'
Total Toe	-0°25'		-3°00' 3°00'
Thrust Angle	0°22'		-3°00' 3°00'