

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III19021920/UGA3Q2

**Date:** 28/05/2020

### REFERENCE

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D19MPC0006405   |
| <b>Claimant Vehicle No :</b> | SJR3639A                              | <b>Insured Vehicle No :</b> | SLU3179X        |
| Date of Loss:                | 11/12/2019                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MPC2019D0001625 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SJR3639A                          | Engine No:  | G4FC9H258953      |
| Make & Model:               | KIA CERATO FORTE, 1.6 EX (A)      | Chassis No: | KNAFH221395080401 |
| Reg. Date:                  | 22/06/2009 (Man. Year: 2009)      | Odometer:   | 177012 km         |
| Colour:                     | Brown                             |             |                   |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195/65 R15       | Rear Tyre Size:  | 195/65 R15       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 38,737.90         | 15,544.19         | 23,193.71         | 59.87         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 8,260.00          | 5,120.00          | 3,140.00          | 38.01         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>46,997.90</b>  | <b>20,664.19</b>  | <b>26,333.71</b>  | <b>56.03</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>14,000.00</b>  |                   |               |
| <b>Nett Amount (S\$)</b>                         | <b>46,997.90</b>  | <b>14,000.00</b>  | <b>32,997.90</b>  | <b>70.21</b>  |
| <b>+ Loss of Use (10.0 x S\$60.00/day) (S\$)</b> |                   | 600.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 2.00              |                   |               |
| <b>+ Other Costs (S\$)</b>                       |                   | 180.00            |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>14,782.00</b>  |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>14,500.00</b>  |                   |               |

### INSPECTION

|                             |                          |                                                                                                            |
|-----------------------------|--------------------------|------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 12/12/2019               |                                                                                                            |
| Date Inspected:             | 12/12/2019 Inspected At: | Choo Motor Spray Painter (HQ)<br>1 Kaki Bukit Avenue 6, #01-39<br>AutoBay @ Kaki Bukit<br>Singapore 417883 |
| Estimated Period of Repair: | 15.0 days                |                                                                                                            |

---

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                               |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 02 Apr 2020)                 |
| <b>Parts:</b>        | 143                                                                                                                                                                          | KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJR3639A)                                                                                                                                    |                                                               |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition              | Repairer's | Amount       |
|-----|-----|----------|------------------------------------|------------------------|------------|--------------|
| 1   | 1   |          | *BOOTLID                           | Buckled                | 919.20 F   | *732.00 FL   |
| 2   | 1   |          | *BOOTLID REAR LOGO                 | Necessary              | 65.50 F    | *32.50 FL    |
| 3   | 1   |          | *BOOTLID C&C LOGO                  | Necessary              | 45.00 F    | *45.00 FL    |
| 4   | 1   |          | *BOOTLID CERATO EMBLEM             | Necessary              | 42.00 F    | *32.50 FL    |
| 5   | 1   |          | *BOOTLID FORTE EMBLEM              | Necessary              | 45.00 F    | *30.00 FL    |
| 6   | 2   |          | *BOOTLID REFLECTORS                | Cracked                | 840.20 F   | *370.00 FL   |
| 7   | 1   |          | *BOOTLID INNERLOCK                 | Twisted                | 115.00 F   | *115.00 FL   |
| 8   | 1   |          | *BOOTLID WEATHERSTRIP              | Twisted                | 245.00 F   | *145.00 FL   |
| 9   | 1   |          | *BOOTLID INNER TRIM                | Not Necessary          | 265.00 F   | *- FL        |
| 10  | 1   |          | *BOOTLID HINGES                    | Repair                 | 376.00 F   | *- FL        |
| 11  | 1   |          | *REAR BUMPER                       | Distorted              | 845.00 F   | *587.00 FL   |
| 12  | 1   |          | *REAR BUMPER LOWER GARNISH         | Distorted              | 216.00 F   | *184.00 FL   |
| 13  | 1   |          | *REAR BUMPER SPONGE                | Torn                   | 288.00 F   | *165.00 FL   |
| 14  | 1   |          | *REAR BUMPER REINFORCEMENT         | Cracked                | 399.00 F   | *379.30 FL   |
| 15  | 5   |          | *REAR BUMPER REINFORCEMENT BRACETS | Cracked (2 PCS ONLY)   | 100.00 F   | *40.00 FL    |
| 16  | 1   |          | *REAR BUMPER BRACKETS              | O/S Bent               | 322.00 F   | *161.00 FL   |
| 17  | 1   |          | *REAR END PANEL                    | Badly Dented           | 655.00 F   | *530.50 FL   |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH        | Twisted                | 299.00 F   | *80.60 FL    |
| 19  | 2   |          | *TAILLAMP                          | Cracked                | 960.00 F   | *500.00 FL   |
| 20  | 1   |          | *TAILLAMP HOUSING PANELS           | O/S Bent               | 810.00 F   | *165.00 FL   |
| 21  | 1   |          | *REAR FENDER O/S                   | Badly Dented / Buckled | 1,299.00 F | *1,029.10 FL |
| 22  | 1   |          | *REAR FENDER INNER TRIM O/S        | Not Necessary          | 385.00 F   | *- FL        |
| 23  | 1   |          | *REAR FENDER INNER COVER O/S       | Not Necessary          | 165.00 F   | *- FL        |
| 24  | 1   |          | *REAR AIR VENT                     | Not Necessary          | 80.00 F    | *- FL        |
| 25  | 1   |          | *REAR FLOOR PANEL                  | Crumpled / Buckled     | 1,480.00 F | *919.00 FL   |
| 26  | 1   |          | *REAR FLOOR PANEL TOP BOARD        | Warped                 | 392.00 F   | *316.00 FL   |
| 27  | 1   |          | *REAR EXHAUST                      | Repair                 | 792.00 F   | *- FL        |
| 28  | 1   |          | *REAR EXHAUST HEAT SHIELD          | Distorted              | 185.00 F   | *112.00 FL   |
| 29  | 2   |          | *REAR EXHAUST MOUNTINGS            | Not Necessary          | 120.00 F   | *- FL        |
| 30  | 1   |          | *REAR CHASSIS MEMBER O/S           | Repair                 | 655.00 F   | *- FL        |
| 31  | 1   |          | *REAR WINDSCREEN MOULDING          | Necessary              | 121.00 F   | *66.80 FL    |
| 32  | 1   |          | *BONNET                            | Buckled                | 909.00 F   | *685.00 FL   |
| 33  | 2   |          | *BONNET HINGES                     | Serviceable            | 310.00 F   | *- FL        |
| 34  | 1   |          | *BONNET INSULATOR                  | Not fitted             | 288.00 F   | *- FL        |
| 35  | 1   |          | *SET BONNET INSULATOR CLIPS        | Not fitted             | 50.00 F    | *- FL        |
| 36  | 1   |          | *BONNET RUBBER                     | Necessary              | 62.00 F    | *60.80 FL    |
| 37  | 1   |          | *BONNET LOCK                       | Twisted                | 95.00 F    | *95.00 FL    |
| 38  | 1   |          | *FRONT GRILLE                      | Cracked                | 315.00 F   | *235.00 FL   |
| 39  | 1   |          | *FRONT GRILLE LOGO                 | Necessary              | 80.00 F    | *45.00 FL    |
| 40  | 1   |          | *FRONT BUMPER                      | Distorted              | 701.00 F   | *535.00 FL   |
| 41  | 1   |          | *FRONT BUMPER CENTRE GRILLE        | Not Necessary          | 232.00 F   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                             | Condition      | Repairer's | Amount       |
|-----|-----|----------|-----------------------------------------|----------------|------------|--------------|
| 42  | 1   |          | *FRONT BUMPER FOG LAMPS                 | O/S Broken     | 970.00 F   | *185.00 FL   |
| 43  | 1   |          | *FRONT BUMPER FOG LAMP COVERS           | O/S Torn       | 130.00 F   | *65.00 FL    |
| 44  | 1   |          | *FRONT BUMPER SPONGE                    | Torn           | 312.00 F   | *165.00 FL   |
| 45  | 1   |          | *FRONT BUMPER REINFORCEMENT             | Bent           | 492.00 F   | *385.00 FL   |
| 46  | 1   |          | *FRONT BUMPER SIDE RETAINERS            | O/S Cracked    | 90.00 F    | *45.00 FL    |
| 47  | 1   |          | *SET FRONT BUMPER CLIPS                 | Necessary      | 50.00 F    | *50.00 FL    |
| 48  | 2   |          | *HEADLAMPS                              | Cracked        | 2,300.00 F | *1,184.00 FL |
| 49  | 1   |          | *FRONT SUPPORT PANEL                    | Bent / Cracked | 1,015.00 F | *742.00 FL   |
| 50  | 1   |          | *AIR DUCT                               | Cracked        | 305.00 F   | *105.00 FL   |
| 51  | 1   |          | *AIR DUCT CONDENSER                     | Not Necessary  | 1,280.00 F | *- FL        |
| 52  | 1   |          | *RADIATOR                               | Not Necessary  | 1,660.00 F | *- FL        |
| 53  | 1   |          | *RADIATOR FAN ASSY                      | Not Necessary  | 915.00 F   | *- FL        |
| 54  | 1   |          | *WASHER TANK                            | Not Necessary  | 302.00 F   | *- FL        |
| 55  | 1   |          | *FRONT FENDER O/S                       | Buckled        | 711.00 F   | *391.00 FL   |
| 56  | 1   |          | *FRONT FENDER INNERSHIELD O/S           | Torn           | 188.00 F   | *145.00 FL   |
| 57  | 1   |          | *SET FRONT FENDER INNERSHIELD CLIPS O/S | Necessary      | 50.00 F    | *50.00 FL    |
| 58  | 1   |          | *FRONT WHEEL HOUSING PANEL O/S          | Repair         | 619.00 F   | *- FL        |
| 59  | 1   |          | *FRONT DOOR O/S                         | Repair         | 845.00 F   | *- FL        |
| 60  | 1   |          | *FRONT DOOR PILLAR O/S                  | Repair         | 699.00 F   | *- FL        |
| 61  | 1   |          | *FRONT SHOCK ABSORBER O/S               | Bent / Twisted | 455.00 F   | *322.00 FL   |
| 62  | 1   |          | *FRONT LOWER ARM O/S                    | Bent           | 428.00 F   | *365.00 FL   |
| 63  | 1   |          | *FRONT KNUCKLE ARM O/S                  | Bent           | 545.00 F   | *352.00 FL   |
| 64  | 1   |          | *FRONT KNUCKLE ARM BEARING O/S          | Necessary      | 250.00 F   | *185.00 FL   |
| 65  | 1   |          | *FRONT DRIVESHAFT O/S                   | Twisted        | 1,319.00 F | *1,215.00 FL |
| 66  | 1   |          | *FRONT STEERING RACK ASSY               | Bent / Jammed  | 2,200.00 F | *1,850.00 FL |
| 67  | 1   |          | *FRONT ENGINE CROSS MEMBER              | Serviceable    | 1,815.00 F | *- FL        |
| 68  | 1   |          | *POWER STEERING TANK                    | Cracked        | 292.00 F   | *155.00 FL   |
| 69  | 1   |          | *AIR CON DISCHARGE HOSE                 | Serviceable    | 285.00 F   | *- FL        |
| 70  | 1   |          | *AIR CON SUCTION HOSE                   | Serviceable    | 288.00 F   | *- FL        |
| 71  | 1   |          | *SET REAR BUMPER REVERSE SENSOR         | Shorted        | 280.00 FS  | *200.00 FS   |
| 72  | 1   |          | *REAR END PANEL SEALANT                 | Necessary      | 50.00 FS   | *50.00 FS    |
| 73  | 1   |          | *REAR WINDSCREEN SEALANT                | Necessary      | 50.00 FS   | *40.00 FS    |
| 74  | 1   |          | *SET REAR FLOOR PANEL INSULATOR         | Necessary      | 200.00 FS  | *100.00 FS   |
| 75  | 1   |          | *FRONT LICENCE PLATE W/HOLDER           | Bent           | 50.00 FS   | *40.00 FS    |
| 76  | 1   |          | *FRONT SPORT RIM O/S                    | Dented         | 480.00 FS  | *300.00 FS   |
| 77  | 1   |          | *FRONT TYRE O/S (50%)                   | Punctured      | 200.00 FS  | *100.00 FS   |
| 78  | 1   |          | *BOT RADIATOR COOLANT                   | Not Necessary  | 50.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 38,737.90 17,179.10  
**- List Item Discount on L Items 0.00/10.00% (\$\$)** 0.00 1,634.91

**Total Parts (\$\$)** 38,737.90 15,544.19

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                               |          |                 |                 |
| 1                              | TO CHECK WIRING                               | New      | 30.00           | 30.00           |
| 2                              | TO DISMANTLE & REPLACING REVERSE SENSOR       | New      | 80.00           | 50.00           |
| 3                              | TO DISMANTLE & REPLACING REAR EXHAUST         | New      | 80.00           | 60.00           |
| 4                              | TO DISMANTLE & REFIX PETROL TANK              | New      | 80.00           | 60.00           |
| 5                              | TO DISMANTLE & REFIX REAR WINDSCREEN          | New      | 150.00          | 120.00          |
| 6                              | TO DISMANTLE & REFIX BOOTLID MECHANISM        | New      | 120.00          | 60.00           |
| 7                              | TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY | New      | 120.00          | 80.00           |
| 8                              | TO REFILL AIR CON GAS                         | New      | 120.00          | 100.00          |
| 9                              | TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE  | New      | 1,480.00        | 300.00          |
| 10                             | TO CONDUCT WHEEL ALIGMMENT                    | New      | 120.00          | 60.00           |
| 11                             | TO MOUNT VEHICLE ON CAR-OLINER                | New      | 380.00          | 0.00            |
| 12                             | LABOUR FOR PANEL BEATING & REPLACING PARTS    | New      | 3,000.00        | 2,400.00        |
| 13                             | TO PUTTY & SPRAY PAINTING                     | New      | 2,500.00        | 1,800.00        |
| <b>Gross Labour Cost (S\$)</b> |                                               |          | <b>8,260.00</b> | <b>5,120.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >