



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI19021923/Uba3s2 Date: 30/12/2020 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 228A	Veh. Inspected	SML 8661Y
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D19007750MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA SAN SAN	Assign Date	12/12/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP72001026	Colour	BLUE
Odometer	061673 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/12/2019	Inspection Date	12/12/2019
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	