



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005592  
INV Date 14/08/2020  
Reference CC4/FCI19021926/Hka3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SGU 8385T  
Insured Veh. SHD 4207D  
Claim No. D19007792MFSH/1  
Policy No. D-18088936MFSH  
Accident Date 05/12/2019  
Inspection Date 11/12/2019

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 359.00        |
| Resurvey Inspection |               |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>359.00</b> |
| <b>GST (7%)</b>     | <b>25.13</b>  |
| <b>Grand Total</b>  | <b>384.13</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |                              |   |
|---|---|------------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD                                    |   | Ref : CC4/FCI19021926/Hka3q2 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877             |   | Date : 14-08-2020            |  |
|   |   | Code : FCI2                  |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |   |                              |   |
|   | Insured Veh.  | SHD 4207D                    | Veh. Inspected  |
|   |   |                              | SGU 8385T   |
|   | Policy No.  | D-18088936MFSH               | Coverage (\$)   |
|   |   |                              | 0.00  |
|   | Claim No.   | D19007792MFSH/1              | Excess (\$)   |
|   |   |                              | 0.00  |
|   | Assign From   | JOANNE YONG                  | Assign Date   |
|   |   |                              | 10/12/2019  |
| 2. Vehicle Particulars & Condition                                |   |                              |   |
|   | Make & Model  | TOYOTA VIOS E                | c.c   |
|   |   |                              | 1497  |
|   | Engine No.  | HIDDEN                       | Year of Reg.  |
|   |   |                              | 2007  |
|   | Chassis No.   | MR053HY9305000539            | Colour  |
|   |   |                              | SILVER  |
|   | Odometer  | 224897                       | Steering  |
|   |   |                              | IN ORDER  |
|   | Brakes  | IN ORDER                     | Modification  |
|   |   |                              | SPORTS RIM  |
|   | General   | GOOD                         |   |
|   |   |                              |   |
| 3. Conditions of Tyres  |   |                              |   |
|   |   | Size                         | Make  |
|   |   |                              | Balance   |
|   | R/H Front Tyre  | 185/60 R15                   | MICHELIN  |
|   |   |                              | 5 mm  |
|   | L/H Front Tyre  | 185/60 R15                   | MICHELIN  |
|   |   |                              | 5 mm  |
|   | R/H Rear Tyre   | 185/60 R15                   | NEUTON  |
|   |   |                              | 5 mm  |
|   | L/H Rear Tyre   | 185/60 R15                   | NEUTON  |
|   |   |                              | 5 mm  |
| 4. Description of Damages   |   |                              |   |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.                        |                              |   |
|   | DAMAGES SEE DETAILS.  |                              |   |
| 5. General Information  |   |                              |   |
|   | Accident Date   | 05/12/2019                   | Inspection Date   |
|   |   |                              | 11/12/2019  |
|   | Survey held at  | BIFROST AUTO PTE LTD         |   |
|   |   | 8 KAKI BUKIT AVENUE 4        |   |
|   |   | #01-49 PREMIER @ KAKI BUKIT  |   |
|   |   | SINGAPORE 415875             |   |
| 5a. Remarks   |   |                              |   |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.         |                              |   |
|   | B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                              |   |
| 5b. Estimate Days of Repair                                       |   |                              |   |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:                                   |                              | <b>4 Working Days</b>   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 8385T

| Qty                                | Description of Parts                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |               |                           |                   |
| 1                                  | FRONT BUMPER  | CRACKED       | 558.40                    | 490.80            |
| 1                                  | FRONT BUMPER RETAINER RH                            | CRUMPLED      | 95.60                     | 95.60             |
| 1                                  | FRONT BUMPER RETAINER LH                            | SERVICEABLE   | 95.60                     | -                 |
| 1                                  | FOG LAMP GARNISH RH                                 | SERVICEABLE   | 128.30                    | -                 |
| 1                                  | FOG LAMP RH   | SERVICEABLE   | 298.20                    | -                 |
| 1                                  | HEAD LAMP RH  | SCRATCHED     | 674.20                    | 525.30            |
| 1                                  | FRONT FENDER RH                                     | BENT          | 558.30                    | 440.80            |
| 1                                  | FRONT FENDER INNER SHIELD RH                        | CRACKED       | 158.40                    | 158.40            |
| 1                                  | FRONT FENDER EMBLEM -VVTI                           | NECESSARY     | 75.50                     | 75.50             |
| 1                                  | FRONT ABSORBER RH                                   | SERVICEABLE   | 431.50                    | -                 |
| 1                                  | FRONT KNUCKLE ARM RH                                | SERVICEABLE   | 521.40                    | -                 |
| 1                                  | FRONT KNUCKLE BEARING RH                            | CRUMPLED      | 224.20                    | 110.70            |
| 1                                  | FRONT LOWER ARM RH                                  | SERVICEABLE   | 425.30                    | -                 |
|                                    | LESS 25% DISCOUNT                                   |               | -                         | -474.28           |
|                                    |   |               | 4,244.90                  | 1,422.82          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |               |                           |                   |
| 1                                  | SET FRONT BUMPER CLIP (SN)                          | NECESSARY     | 50.00                     | 20.00             |
| 1                                  | SET FRONT FENDER INNER SHIELD CLIP (SN)             | NECESSARY     | 50.00                     | 20.00             |
| 1                                  | FRONT WHEEL RIM RH (SN)                             | SCRATCHED     | 600.00                    | 300.00            |
| 1                                  | FRONT WHEEL TYRE RH (SN)                            | SERVICEABLE   | 200.00                    | -                 |
| 1                                  | SUNDRIES (SN)                                       | NOT NECESSARY | 50.00                     | -                 |
|                                    |   |               | 950.00                    | 340.00            |
| <b><u>LABOUR</u></b>               |   |               |                           |                   |
|                                    | TO CHECK WIRING AND LIGHTING SYSTEM.                |               | 80.00                     | 30.00             |
|                                    | TO CONDUCT HEAD LAMP FOCUS .                        |               | 100.00                    | 30.00             |
|                                    | TO SUPPLY UNDER-COATING /PUTTY ON PARTS REPLACED. } |               | 80.00                     | 40.00             |
|                                    | TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS .} |               | 60.00                     | -                 |
|                                    | TO CONDUCT WHEEL ALIGNMENT BEFORE AND AFTER.        |               | 180.00                    | 60.00             |
|                                    | TO R&R FRONT RH WHEEL RIM ,TYRE AND BALANCING .     |               | 50.00                     | 20.00             |

Report Ref No. CC4/FCI19021926/Hka3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-----------|---------------------------|-------------------|
|     | TO R&R FRONT RH UNDER-CARRIAGE DAMAGED PARTS.}                              |           | 350.00                    | 100.00            |
|     | TO PRESS FRONT RH KNUCKLE BEARING ASSY .}                                   |           | 100.00                    | -                 |
|     | TO REPAIR ,REPLACE AND REALIGN DAMAGRED AREAS.                              |           | 900.00                    | 400.00            |
|     | TO SPRAY PAINTING ON AFFECTED AREAS.  |           | 900.00                    | 400.00            |
|     |   |           | 2,800.00                  | 1,080.00          |
|     | <b>GRAND TOTAL</b>  |           | <b>7,994.90</b>           | <b>2,842.82</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |           |                           | <b>2,250.00</b>   |

Report Ref No. CC4/FCI19021926/Hka3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 8385T

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 8385T

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 8385T

RE-INSPECTION





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

