

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021935/EEA3Q2
Date: 06/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100477266-03
Claimant Vehicle No : SLS49T **Insured Vehicle No :** SLE7098D
 Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 7371194110SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS49T**
 Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CZC243971
 Reg. Date: 07/05/2015 (Man. Year: 2015) Chassis No: WAUZZZ8V9FA133535
 Colour: Black Odometer: 112254 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
 Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,438.32	5,370.38	6,067.94	53.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	2,050.00	3,610.00	63.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	17,098.32	7,420.38	9,677.94	56.60
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/12/2019
 Date Inspected: 13/12/2019 Inspected At: Revol Carz Garage Pte Ltd (HQ)
 Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point
 Singapore 568047
 Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DRIVER SIDE FRONT DOOR	Dented	1,500.75 F	*1,500.75 FL
2	1		*DRIVER SIDE FRONT DOOR LOCK	Bent	600.54 F	*458.00 FL
3	1		*DRIVER SIDE FRONT DOOR WINDOW REGULATOR	Bent	433.21 F	*433.21 FL
4	1		*DRIVER SIDE FRONT DOOR WINDOW MOTOR	Jammed	600.75 F	*428.00 FL
5	1		*DRIVER SIDE FRONT DOOR OUTER HANDLE	Broken	300.21 F	*300.21 FL
6	1		*DRIVER SIDE FRONT DOOR OUTER HANDLE COVER	Broken	130.21 F	*36.00 FL
7	1		*DRIVER SIDE FRONT DOOR HINGE	Bent	147.20 F	*84.00 FL
8	1		*DRIVER SIDE REAR DOOR	Dented	1,500.75 F	*1,500.75 FL
9	1		*DRIVER SIDE REAR DOOR WINDOW REGULATOR	Not Necessary	455.60 F	*- FL
10	1		*DRIVER SIDE REAR DOOR WINDOW MOTOR	Not Necessary	400.21 F	*- FL
11	1		*DRIVER SIDE FRONT DOOR HINGE UPPER	Bent	100.21 F	*84.00 FL
12	1		*DRIVER SIDE FRONT DOOR HINGE -LOWER	Not Necessary	100.21 F	*- FL
13	1		*DRIVER SIDE FRONT DOOR INNER RUBBER	Necessary	188.86 F	*188.86 FL
14	1		*DRIVER SIDE REAR DOOR INNER RUBBER	Necessary	188.86 F	*188.86 FL
15	1		*DRIVE SIDE FRONT DOOR INNER BOARD	Not Necessary	1,670.21 F	*- FL
16	1		*DRIVE SIDE REAR DOOR INNER BOARD	Not Necessary	1,600.54 F	*- FL
17	1		*DRIVE SIDE FRONT DOOR CHROME STRIPS	Necessary	160.00 F	*160.00 FL
18	1		*DRIVE SIDE REAR DOOR CHROME STRIPS	Necessary	160.00 F	*160.00 FL
19	1		*PAINT PROTECTION (ZE TOUGH PROTECTION)	Necessary	1,200.00 FS	*400.00 FS
					Sub Total (\$)	11,438.32 5,922.64
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 552.26
					Total Parts (\$)	11,438.32 5,370.38

F=Franchise part. S=SpcNett. L=ListItemDisc.

LKK Auto Consultants Pte Ltd/SLS49T/06/05/2020 17:04

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING AND TEST FOR PROPER FUNCTIONING	New	40.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS ,INNER GARNISHES ,TO FACILITATE THE REPAIR	New	80.00	50.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	2,800.00	900.00
4	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	2,500.00	900.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	60.00	50.00
6	COMPUTERISED 4 WHEEL ALIGNMENT	New	120.00	60.00
7	TO RESET COMPUTERIZE FAULT CODE	New	60.00	60.00
Gross Labour Cost (\$\$)			5,660.00	2,050.00

LKK Auto Consultants Pte Ltd/SLS49T/06/05/2020 17:04

< END OF ESTIMATES >