

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021935/EEA3Q2

Date: 06/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100477266-03

Claimant
Vehicle No : SLS49T **Insured Vehicle No :** SLE7098D

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 7371194110SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLS49T | | |
| Make & Model: | AUDI A3, 1.4 TFSI (A) | Engine No: | CZC243971 |
| Reg. Date: | 07/05/2015 (Man. Year: 2015) | Chassis No: | WAUZZZ8V9FA133535 |
| Colour: | Black | Odometer: | 112254 km |
| Engine Capacity: | 1395 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/45 R17 | Rear Tyre Size: | 225/45 R17 |
| Front Left Side: | Continental 5 mm | Rear Left Side: | Continental 5 mm |
| Front Right Side: | Continental 5 mm | Rear Right Side: | Continental 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 11,438.32 | 5,370.38 | 6,067.94 | 53.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,660.00 | 2,050.00 | 3,610.00 | 63.78 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (\$\$) | 17,098.32 | 7,420.38 | 9,677.94 | 56.60 |
| Global Sum Settlement (\$\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 13/12/2019 Inspected At:

Revol Carz Garage Pte Ltd (HQ)
Block 10, Ang Mo Kio Ind Park 2A,
#02-18, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *DRIVER SIDE FRONT DOOR | Dented | 1,500.75 F | *1,500.75 FL |
| 2 | 1 | | *DRIVER SIDE FRONT DOOR LOCK | Bent | 600.54 F | *458.00 FL |
| 3 | 1 | | *DRIVER SIDE FRONT DOOR WINDOW REGULATOR | Bent | 433.21 F | *433.21 FL |
| 4 | 1 | | *DRIVER SIDE FRONT DOOR WINDOW MOTOR | Jammed | 600.75 F | *428.00 FL |
| 5 | 1 | | *DRIVER SIDE FRONT DOOR OUTER HANDLE | Broken | 300.21 F | *300.21 FL |
| 6 | 1 | | *DRIVER SIDE FRONT DOOR OUTER HANDLE COVER | Broken | 130.21 F | *36.00 FL |
| 7 | 1 | | *DRIVER SIDE FRONT DOOR HINGE | Bent | 147.20 F | *84.00 FL |
| 8 | 1 | | *DRIVER SIDE REAR DOOR | Dented | 1,500.75 F | *1,500.75 FL |
| 9 | 1 | | *DRIVER SIDE REAR DOOR WINDOW REGULATOR | Not Necessary | 455.60 F | *- FL |
| 10 | 1 | | *DRIVER SIDE REAR DOOR WINDOW MOTOR | Not Necessary | 400.21 F | *- FL |
| 11 | 1 | | *DRIVER SIDE FRONT DOOR HINGE UPPER | Bent | 100.21 F | *84.00 FL |
| 12 | 1 | | *DRIVER SIDE FRONT DOOR HINGE -LOWER | Not Necessary | 100.21 F | *- FL |
| 13 | 1 | | *DRIVER SIDE FRONT DOOR INNER RUBBER | Necessary | 188.86 F | *188.86 FL |
| 14 | 1 | | *DRIVER SIDE REAR DOOR INNER RUBBER | Necessary | 188.86 F | *188.86 FL |
| 15 | 1 | | *DRIVE SIDE FRONT DOOR INNER BOARD | Not Necessary | 1,670.21 F | *- FL |
| 16 | 1 | | *DRIVE SIDE REAR DOOR INNER BOARD | Not Necessary | 1,600.54 F | *- FL |
| 17 | 1 | | *DRIVE SIDE FRONT DOOR CHROME STRIPS | Necessary | 160.00 F | *160.00 FL |
| 18 | 1 | | *DRIVE SIDE REAR DOOR CHROME STRIPS | Necessary | 160.00 F | *160.00 FL |
| 19 | 1 | | *PAINT PROTECTION (ZE TOUGH PROTECTION) | Necessary | 1,200.00 FS | *400.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,438.32 5,922.64
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 552.26

Total Parts (\$\$) 11,438.32 5,370.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND REFIT REAR ELECTRICAL WIRING AND TEST FOR PROPER FUNCTIONING | New | 40.00 | 30.00 |
| 2 | TO REMOVE AND REFIT INNER TRIMS ,INNER GARNISHES ,TO FACILITATE THE REPAIR | New | 80.00 | 50.00 |
| 3 | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS | New | 2,800.00 | 900.00 |
| 4 | TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE | New | 2,500.00 | 900.00 |
| 5 | TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION | New | 60.00 | 50.00 |
| 6 | COMPUTERISED 4 WHEEL ALIGNMENT | New | 120.00 | 60.00 |
| 7 | TO RESET COMPUTERIZE FAULT CODE | New | 60.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 5,660.00 | 2,050.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >