

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19021944/R1GA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJQ4940C	Insured Vehicle No :	SHC8775J
Date of Loss: 10/12/2019	Nature of Claim: TP	Claim No: MCT19120230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ4940C		
Make & Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Engine No:	1AZH331120
Reg. Date:	14/05/2009 (Man. Year: 2009)	Chassis No:	JTEGH23B700026543
Colour:	Blue	Odometer:	151263 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,511.99	1,991.75	5,520.24	73.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,490.00	1,970.00	56.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,971.99	3,481.75	7,490.24	68.27
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	10,971.99	2,800.00	8,171.99	74.48
+ GST 7.00/7.00% (\$\$)	768.04	196.00	572.04	74.48
Nett Amount (\$\$)	11,740.03	2,996.00	8,744.03	74.48
+ Car Rental (5.0 x S\$120.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		36.49		
Nett Liability (\$\$)		3,632.49		
Global Sum Settlement (\$\$)		3,600.00		

INSPECTION

Date of Assignment:	12/12/2019	
Date Inspected:	12/12/2019 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2020)
Parts:	M1-MPV	TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ4940C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	673.00 FL	*586.00 FL
2	1		*REAR BUMPER RETAINER	O/S Necessary	150.00 FL	*55.00 FL
3	1		*REAR BUMPER REFLECTOR	O/S Scratched	183.30 FL	*87.00 FL
4	1		*REAR BUMPER TOW COVER	Cut	83.20 FL	*55.00 FL
5	1		*REAR BUMPER SIDE BRACKET	Serviceable	144.50 FL	*- FL
6	1		*REAR END PANEL	Bent	691.56 FL	*571.00 FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	327.55 FL	*- FL
8	1		*TAILGATE	Not Necessary	1,507.00 FL	*- FL
9	1		*TAILGATE EMBLEM LOGO	Not Necessary	75.00 FL	*- FL
10	1		*TAILGATE EMBLEM TOYOTA	Not Necessary	52.80 FL	*- FL
11	1		*TAILGATE EMBLEM PICNIC	Not Necessary	66.70 FL	*- FL
12	1		*TAILGATE GLASS MOULDING	Not Necessary	172.30 FL	*- FL
13	1		*TAILGATE LAMP	Not Necessary	599.60 FL	*- FL
14	1		*TAILGATE LOCK	Not Necessary	428.90 FL	*- FL
15	1		*TAILGATE LOCK STRIKER	Not Necessary	43.50 FL	*- FL
16	1		*TAILGATE WEATHERSTRIP	Not Necessary	316.80 FL	*- FL
17	1		*TAILGATE ABSORBER	Not Necessary	563.00 FL	*- FL
18	1		*REAR COMPARTMENT TRIM	Not Necessary	561.55 FL	*- FL
19	1		*SET REAR REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
22	1		*SET END PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS
23	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
24	1		*REAR EXHAUST	Bent	879.60 FL	*833.00 FL
25	1		*REAR EXHAUST MOUNTING	Necessary	161.50 FL	*122.00 FL
26	1		*FLOOR PANEL COMPARTMENT	Repair	1,201.30 FL	*- FL
27	1		*REAR BUMPER STICKER	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,732.66	2,569.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,220.67	577.25
Total Parts (\$\$)	7,511.99	1,991.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	60.00
3	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	0.00
4	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	600.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	750.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
9	REMOVE AND REFIT REAR EXHAUST	New	150.00	80.00
Gross Labour Cost (\$\$)			3,460.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >