



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004438  
INV Date 23/06/2020  
Reference CC4/FCI19021946/Gka3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SLA 3606K  
Insured Veh. SHB 3969E  
Claim No. D19007777MFSH/1  
Policy No. D-19092579MFSH  
Accident Date 06/12/2019  
Inspection Date 18/12/2019

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19021946/Gka3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-06-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHB 3969E	<b>Veh. Inspected</b>	SLA 3606K
<b>Policy No.</b>	D-19092579MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D19007777MFSH/1	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	RACHEL WU	<b>Assign Date</b>	12/12/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	VOLKSWAGEN PASSAT	<b>c.c</b>	1984
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	WVWZZZ3CZGE071562	<b>Colour</b>	BLUE
<b>Odometer</b>	37888	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	235/45 R18	CONTINENTAL	6 mm
<b>L/H Front Tyre</b>	235/45 R18	CONTINENTAL	6 mm
<b>R/H Rear Tyre</b>	235/45 R18	CONTINENTAL	6 mm
<b>L/H Rear Tyre</b>	235/45 R18	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	06/12/2019	<b>Inspection Date</b>	18/12/2019
<b>Survey held at</b>	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 3606K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	SET SENSOR BRACKETS (SN)	NECESSARY	39.84	39.84
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	74.29	74.29
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	56.90	56.90
1	SPOILER PRIMED (SN)	DEFORMED	240.11	240.11
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	476.93	-
1	ATTACHMENT STRIP RR CTR BRACKET (SN)	NOT NECESSARY	54.40	-
1	GUIDE LHR TAILLIGHT BRACKET (SN)	NOT NECESSARY	20.09	-
1	GUIDE RHR TAILLIGHT BRACKET (SN)	NOT NECESSARY	20.09	-
1	DECORATIVE MOULDING BRIGH RR CTR CHROME (SN)	CUT	195.49	195.49
1	DECORATIVE MOULDING BRIGH LHR CHROME (SN)	NOT NECESSARY	150.53	-
1	DECORATIVE MOULDING BRIGH RHR CHROME (SN)	NOT NECESSARY	150.53	-
1	REFLECTOR LHR INNER (SN)	NOT NECESSARY	63.86	-
1	REFLECTOR LHR OUTER (SN)	NOT NECESSARY	63.86	-
1	COVER PRIMED REAR BUMPER (SN)	DEFORMED	1,530.46	1,530.46
1	NO PLATE (SN)	CUT	80.00	80.00
20	RIVET (SN)	NECESSARY	22.80	22.80
			3,240.18	2,239.89
	<b>LABOUR</b>			
	LABOUR.		2,520.00	840.00
	SPRAY PAINTING.		2,400.00	1,200.00
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	CHECK SHORT CIRCUIT/HARNESS REPAIR.		280.00	280.00
			5,680.00	2,800.00
	<b>GRAND TOTAL</b>		<b>8,920.18</b>	<b>5,039.89</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>5,039.89</b>

Report Ref No. CC4/FC119021946/Gka3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 3606K

INSPECTION





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 3606K

RE-INSPECTION

