

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

SGR 5079M

1PC	FRONT DOOR O/S	
1PC	REAR DOOR O/S	1287.50
1PC	REAR DOOR INNER RUBBER O/S	295.30
2PCS	REAR DOOR HINGES @\$105.00	
1PC	REAR DOOR INNER LOCK O/S	
1PC	REAR DOOR GLASS REGULATOR O/S	
1PC	REAR DOOR GLASS REGULATOR MOTOR O/S	
1PC	REAR DOOR INNER TRIM BOARD O/S	
1SET	REAR DOOR INNER TRIM BOARD CLIPS O/S	
1PC	REAR DOOR OUTER HANDLE O/S	
1PC	REAR DOOR FRAME BLACK STICKER O/S	
1PC	REAR FENDER O/S	871.10
1PC	REAR FENDER GLASS O/S	
1PC	REAR BUMPER	521.10
1PC	REAR BUMPER SIDE RETAINER O/S	
1SET	REAR BUMPER CLIPS	
1PC	REAR SHOCK ABSORBER O/S	
1PC	REAR AXLE BEAM	
1PC	TAILLAMP O/S	408.20
1PC	REAR WHEEL HUB BEARING O/S	485.00
1PC	REAR FENDER GLASS SEALANT O/S	
1PC	REAR SPORT RIM O/S	

body	117	\$1,420.10	X
body	117	\$1,399.10	—
ner		\$366.50	—
117		\$210.00	X
should		\$439.10	—
bul		\$315.20	—
for		\$485.50	—
reform		\$681.10	—
ner		\$50.00	—
su		\$245.50	X
or		\$80.00	X
body	117	\$1,420.10	—
117		\$680.00	X
cut		\$681.00	—
117		\$66.50	X
ner		\$50.00	—
117		\$399.10	X
117		\$1,845.10	X
scr		\$482.50	—
page		\$650.00	—
ner		\$50.00	—
or		\$680.00	400 S.N
		\$12,696.50	

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REFIX REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR FENDER GLASS O/S	\$150.00	100
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$100.00	80
TO DISMANTLE & REPLACING REAR UNDER CARRIAGE	\$380.00	120
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
TO TRANSFER REAR DOOR COMPONENTS	\$100.00	60
TO SPRAY RUST PROOFING	\$100.00	30
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,200.00	700
TO PUTTY & SPRAY PAINTING	\$1,500.00	800
TOTAL		\$16,506.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6033-1
5076
P-3016-55
S.N 400-00
L-2020
5436-55