

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North, #01-18,**  
**628457**

**Insurer Reference:**  
**Repairer Reference: GBH1712G-OD CHINA**  
**Date calculated: 12/12/2019 4:35 PM**

**Full Report**  
**Registration: GBH1712G**  
**Printed: 12/12/2019 4:40 PM**

### Summary Information

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SNG AH TEE	Currency:	SGD
Claim Reference:		Date of Incident:	09/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

#### Vehicle

Manufacturer: TOYOTA  
Model: DYNA  
Sub Model: BASE MODEL  
Model Sheet Number: 70 1C 01  
Registration: GBH1712G  
VIN number:  
Odometer:

#### Model Specs

AIR CONDITIONING	PLATFORM	WHEELBASE 2525MM	STANDARD CAB
TWO COAT METALLIC	PREPARE OFF VEHICLE		


### Vehicle Condition

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All ☐  
Underbody ☐



### Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
520011	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS	10.0	42.00
751011	R + R RADIATOR GRILLE	3.0	12.60
810051)	R + R R/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.20
810151A	ADJUST HEADLAMPS	3.0	12.60
670051	RENEW R/F DOOR INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, ADJUST DOOR	14.0	58.80
752051	R + R R/DOOR MIRROR CPL INCLUDES: R/END MOULDING REMOVE AND REFIT.	5.0	21.00
670201)	R + R R/F DOOR HINGE/S	1.0	4.20
NN	R/F STEP R&R / NEW PARTS	90.0*	378.00
0413	ENGINE FIREWALL REPAIR	15.0*	63.00
0912	R/OUTER A-PILLAR REPAIR	20.0*	84.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>16.20</b>	<b>162.0</b>
<b>Total of Labour</b>			<b>680.40</b>

### Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
LE 0281	FRONT BUMPER NEW PART PAINT ST 1	12.0	50.40
LE 0888	R/END MOULDING NEW PART PAINT ST 1	6.0	25.20
LE 1482	RIGHT FRONT DOOR NEW PART PAINT ST 1	16.0	67.20
LE 2206	R/F STEP NEW PART PAINT ST 1	6.0	25.20
LS 0413	ENGINE FIREWALL REPAIR PAINT ST IV	23.0	96.60
LS 0912	R/OUTER A-PILLAR REPAIR PAINT ST IV	15.0	63.00
L 0418	OUTER ENG FIREWALL SURFACE PAINT ST 2	5.0	21.00
NO NUMBER	PREPARE FOR PAINTING	21.0	88.20
NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	5.0	21.00
<b>Total Paint</b>		<b>Hrs</b> <b>10.90</b>	<b>WU</b> <b>109.0</b>
			<b>Price SGD</b> <b>457.80</b>

### Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	52111 37301	da ✓	230.00
0410	GRILLE	53111 37891	sla ✓	200.00
0562	RIGHT HEADLAMP ASSY	81110 37120	bro ✓ (ex-stock \$320 x 80%)	320.00 - 256
0608	R/HEADLAMP TRIM	81193 37050	? x svc	30.00
0678	R/F INDICATOR CPL	81610 37200	bro x svc	120.00
0888	R/END MOULDING	53813 37100A0	3 ? cut ✓	85.00

Code	Description	Part Number	Supplier	Price SGD
1482	RIGHT FRONT DOOR	67001 37292	bt ✓	560.00
1488	R/F UPPER DOOR HINGE	68710 37020	? X SVC	35.00
1496	R/F LOWER DOOR HINGE	68730 37010	? X SVC	35.00
1510	R/DOOR SEAL	67861 37021	ne ✓	25.00
1578	R/INN DOOR LOCK	69310 37070	X SVC	120.00
2206	R/F STEP	51771 37211	? X SVC	90.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,850.00
u: Used parts				Fixed Sundry Parts Price 100.00
<b>Total</b>				<b>1,950.00</b>

### Extras

Code	Description	Price SGD
1000	TO CHECK WIRING ne ✓	30.00* ✓
1001	FRT DOOR ROC STICKER ne ✓	20.00* ✓
1002	FRT CORNER PANEL BRACKET RH bt ✓	40.00* ✓
<b>Total Extras</b>		<b>90.00</b>

### Final Calculation

	SGD	SGD
<b>Parts</b>		
Fixed Sundry Parts Price	1,850.00	
<b>Total Parts</b>	100.00	1,950.00
<b>Labour Time Base 10 WU/h</b>		
Total 162.0 WU X 42.00 SGD/h		
<b>Total of Labour</b>		680.40
<b>Total Of Extras</b>		90.00
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 109.0 WU X 42.00 SGD/h		
<b>Total Paint Including Material</b>		457.80
<b>Repair Cost Excludes GST</b>		3,178.20
GST (+7.0%)		222.47
<b>Repair Cost Included GST</b>		3,400.67

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

Audatex System Using Manufacturer Times

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 3 of 4  
 Approved by Repairer  
 Signature:  
 Date:

PRINT DATE 12/12/2019