Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road, #16-00 Springleaf Tower

Date: 11/05/2020 Singapore 079909

REFERENCE

GREENLITE ELECTRIC Insured/Claimant:

PTE. LTD.

Policy No: DMCVSN3014311900

Our File No:

CS/CTI19021963/R1QF3E2

Nature of Claim SNM19D205861/GBH1712G/CBS Date of Loss: 08/12/2019 OD Claim: No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBH1712G** 

TOYOTA DYNA 150, 3.0 D (M) Make & Model: Engine No: 1KD2774594

Reg. Date: 06/03/2018 (Man. Year: 2017) Chassis No: JTFAT35Y80K209803

Colour: Odometer: 68547 km White

**Engine Capacity:** 2982 cc Market Value/New Car Price: S\$58,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable): No

**CONDITION OF TYRES** 

Front Tyre Size: 195/75 R15 155 R12C (D) Rear Tyre Size: Yokohama 5/5 mm Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 5/5 mm Front Right Side: Yokohama 7 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,950.00	1,456.00	494.00	25.33
Miscellaneous Items	90.00	88.00	2.00	2.22
Labour	680.40	239.40	441.00	64.81
Paintwork Labour	457.80	390.60	67.20	14.68
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,178.20	2,174.00	1,004.20	31.60
- Excess (S\$)	0.00	450.00	-450.00	
(S\$)	3,178.20	1,724.00	1,454.20	45.76
+ GST 7.00/7.00% (S\$)	222.47	120.68	101.79	45.75
Nett Amount (S\$)	3,400.67	1,844.68	1,555.99	45.76

INSPECTION

Date of Assignment: 13/12/2019 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

Date Inspected: 13/12/2019 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair: 5.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference				
Part Source:		(Last Synchronised: 11 May 2020)		
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	: (Unsubmitted, no print-code for GBH1712G)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

# Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*TOTAL SPARE PART		1,950.00 F	*1,456.00 F
F=Fra	anchise part.		Total Parts (S\$)	1,950.00	1,456.00
		Report was unsubr	mitted during this print-out.		

Adjuster Report Page 4 of 4

### Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	FRT CORNER PANEL BRACKET RH (BENT)		40.00	38.00
2	1	FRT DOOR ROC STICKER (NECESSARY)		20.00	20.00
3	1	TO CHECK WIRING		30.00	30.00
			Sub Total (S\$)	90.00	88.00

### Recommended Labour

Particulars	Lab.Type	Repairer's	Amount		
Paintwork Labour					
TOTAL PAINTWORK LABOUR	New	457.80	390.60		
<u>Labour Items</u>					
TOTAL OF LABOUR	New	680.40	239.40		
	Gross Labour Cost (S\$)	1,138.20	630.00		
	ntwork Labour  TOTAL PAINTWORK LABOUR  our Items	ntwork Labour  TOTAL PAINTWORK LABOUR  Our Items	TOTAL PAINTWORK LABOUR OUR Items TOTAL OF LABOUR New 680.40		

Report was unsubmitted during this print-out.

< END OF ESTIMATES >