

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021984/ABA3Q2

Date: 22/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SJP9871R **Insured Vehicle No :** SMN2455E

Date of Loss: 11/12/2019 **Nature of Claim:** TP **Claim No:** 1983089459SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP9871R	Engine No:	1NZX890578
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305108393
Reg. Date:	21/04/2009 (Man. Year: 2009)	Odometer:	194106 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45R16	Rear Tyre Size:	205/45R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,196.22	2,040.40	7,155.82	77.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,530.00	1,760.00	53.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,486.22	3,570.40	8,915.82	71.41
Approved Total (Overridden) (\$\$)		2,800.00		
Nett Amount (\$\$)	12,486.22	2,800.00	9,686.22	77.58
+ Car Rental (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		3,336.45		

INSPECTION

Date of Assignment: 12/12/2019

Date Inspected: 12/12/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30
Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	1,239.10 FL	*- FL
2	1		*REAR BOOTLID LOGO	Necessary	75.00 FL	*45.00 FL
3	1		*REAR BOOTLID LOCK	Not Necessary	125.60 FL	*- FL
4	1		*REAR BOOTLID LOCK CHECKER	Not Necessary	48.00 FL	*- FL
5	1		*REAR BOOTLID RUBBER	Not Necessary	230.80 FL	*- FL
6	2		*REAR BOOTLID HINGE LH & RH	Not Necessary	432.00 FL	*- FL
7	2		*REAR BOOTLID RUBBER STOPPER LH & RH	Not Necessary	107.80 FL	*- FL
8	2		*REAR BOOTLID LAMP LH & RH	Not Necessary	881.40 FL	*- FL
9	1		*REAR BOOTLID NUMBER PLATE LAMP GARNISH	Not Necessary	223.20 FL	*- FL
10	1		*REAR BOOTLID NUMBER PLATE LAMP	Not Necessary	165.20 FL	*- FL
11	1		*REAR BUMPER	Deformed	757.50 FL	*545.00 FL
12	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	428.20 FL	*110.00 FL
13	2		*REAR BUMPER SIDE BRACKET LH & RH	Not Necessary	294.40 FL	*- FL
14	1		*REAR BUMPER KEYLESS ANTENNA	Not Necessary	285.00 FL	*- FL
15	1		*REAR END PANEL	Dented	867.50 FL	*596.00 FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	211.10 FL	*- FL
17	2		*REAR TAILLAMP LH & RH	Not Necessary	1,886.40 FL	*- FL
18	2		*REAR TAILLAMP PANEL LH & RH	Not Necessary	243.00 FL	*- FL
19	1		*REAR FENDER LH	Not Necessary	981.30 FL	*- FL
20	2		*REAR FENDER COWLING LH & RH	Not Necessary	238.60 FL	*- FL
21	2		*REAR FENDER AIR VENT LH & RH	Not Necessary	116.00 FL	*- FL
22	2		*REAR END PANEL BRACKET	Bent	171.20 FL	*171.20 FL
23	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
24	1		*REAR WINDSCREEN SEAL	Not Necessary	100.00 FS	*- FS
25	1		*REAR WINDSCREEN SPONGE TAPE	Not Necessary	40.00 FS	*- FS
26	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
28	1		*SET REAR CAR PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
30	1		*REAR BUMPER LOWER COVER	Deformed	800.00 FS	*650.00 FS
31	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
					Sub Total (\$\$)	11,698.30 2,407.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,502.08 366.80
					Total Parts (\$\$)	9,196.22 2,040.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	800.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	120.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	60.00
5	TO REMOVE AND REFIX REAR BOOTLID WINDSCREEN	New	150.00	0.00
6	TO REMOVE REAR BOOT MECHANISM	New	150.00	0.00
7	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
8	TO REMOVE AND REFIX CUSHION AND INNER TRIM	New	150.00	40.00
Gross Labour Cost (\$\$)			3,290.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >