

## ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29 Singapore 417807 Tel:6702 4282 Fax:6702 4202

Vehicle No.

SJP9871R TOYOTA VIOS

TPALG Jasper.

Page No. 1

QTY	SJF98/IR TOTOTA VIOS		REPAIRER'S	SURVEYOR
QII	DESCRIPTION	CONDITION	ESTIMATE(S\$)	ADJUSTMENT
	PARTS (LIST ITEMS)		2011111112(04)	Abjostiticiti
1	REAR BOOTLID Page		1239.10	7
1	REAR BOOTLID LOGO NOC		75,00	
1	REAR BOOTLID LOCK Nel mu		125.60	1
1	REAR BOOTLID LOCK CHECKER Not Neu		48.00	
1	REAR BOOTLID RUBBER AND ME		230.80	
2	REAR BOOTLID HINGE LH & RH @\$216.00 >	1 m	432.00	I
2	REAR BOOTLID RUBBER STOPPER LH & RH @\$	53.90 NH M	107.80	U
2	REAR BOOTLID LAMP LH & RH @\$440.70 🕒	en	881.40	l
1	REAR BOOTLID NUMBER PLATE LAMP GARNIS	H MI ME	223.20	
1	REAR BOOTLID NUMPER PLATE LAMP	New	165.20	+
1	REAR BUMPER Deformed		757.50	1/ (11)
2	REAR BUMPER SIDE RETAINER LH & RH @\$214		428.20	
2	REAR BUMPER SIDE BRACKET LH & RH @\$147	.20 M/m	294.40	
1	REAR BUMPER KEYLESS ANTENNA At Me		285.00	X
1	REAR END PANEL Dented.		867.50	- 94
1	REAR END PANEL TOP GARNISH AND MAKE		1467.20 211.10	×
2	REAR TAILLAMP LH & RH @\$943.20	160 60	1886.40	1
2	REAR TAILLAMP PANEL LH & RH @\$121.50	NIT PEL	1100.40 243.00	X.
1	REAR FENDER LH	2	981.30	
2	REAR FENDER COWLING LH & RH @\$119.30	T ART	238.60	X.
2	REAR FENDER AIR VENT LH & RH @\$58.00	J MW	116.00	1
2	Peer End Panel Bradeet @ 85.60 171.20		9837.10	
	Bent.	less	25% 2459.28	25%
			7377.83	
	SPECIAL NETT ITEMS			,
1	REAR WINDSCREEN GLASS SEALANT		100.00	X
	REAR WINDSCREEN SEAL		100.00	X
1	MEAN WINDSCREEN SPONGE TAPE		40.00	*
	REAR BUMPER CLIPS		100.00	30
	REAR END PANEL TOP GARNISH CLIPS	Service and the service of the servi	940 100.00	X
	REAR CAR PLATE WITH HOLDER	1.1	70.00	X,
	REAR END PANEL SEALANT		80.00	
1 0 01	REAR BUMPER LOWER COVER		800	620
1 Set		Total Parts	8347.83	
Dayed 200				
	U	t a		



## ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29 Singapore 417807 Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SIP9871R TOYOTA VIOS

venic	Vehicle No. SJP98/1R TOYOTA VIOS REPAIRER'S OUR				
S/N	DESCRIPTION	ESTIMATE (S\$)	ASSESSMENT (S\$)		
1	LABOUR To remove the affected parts & fittings to commence repairs and replace damaged parts	1400,00	600		
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	<b>&amp;</b> )		
3	To remove and refix wiring at damaged areas	120.00	30		
4	To perform anti rust treatment on affected areas	200.00	60		
5	To remove and refix rear bootlid windscreen	150.00	X		
6	To remove rear boot mechanism	150.00	X		
7	To conduct water seepage test	120.00	X		
8	To remove and refix cushion and inner trim	150.00	40.		
	Labour Total :	3290.00			
TOTAL (PARTS & LABOUR):		10667.83			

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

total: 357040 4/s: 2.8k. 04 Days.

