

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021986/KEA3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLJ3084T

Insured Vehicle No : SMK2206Z

Date of Loss: 02/12/2019

Nature of Claim: TP

Claim No: 4457129398SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ3084T**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRR969293

Reg. Date: 05/12/2016 (Man. Year: 2016)

Chassis No: JTDKB3FU803538717

Colour: Metallic Silver

Odometer: 229792 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Yokohama 8 mm

Rear Left Side:

Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side:

Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	579.84	178.95	400.89	69.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	849.51	608.47	241.04	28.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,429.35	787.42	641.93	44.91
+ GST 7.00/7.00% (S\$)	100.05	55.12	44.93	44.91
Nett Amount (S\$)	1,529.40	842.54	686.86	44.91
+ Car Rental (4.0 x S\$69.95/day) (S\$)		279.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,129.79		

INSPECTION

Date of Assignment: 12/12/2019

Date Inspected: 23/12/2019 Inspected At:

385 SIN MING DRIVE

Repairer: Esteem Performance Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/R BUMPER BRACKET	Serviceable	112.70 FL	*- FL
2	1		*RHR HUB CAB	Dented	195.64 FL	*195.64 FL
3	1		*ART WORK	Not Necessary	400.00 FL	*- FL
4	1		*WHEEL ALIGNMENT	Necessary	120.00 FL	*60.00 FL
					Sub Total (\$\$)	828.34
					- List Item Discount on L Items 30.00/30.00% (\$\$)	248.50
					Total Parts (\$\$)	579.84

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	73.0 WU X 50.00 SGD/H	New	365.00	130.00
2	LABOUR COST 66.0 WU X 50.00 SGD/H	New	360.00	360.00
3	MATERIAL COST	New	124.51	118.47
Gross Labour Cost (\$\$)			849.51	608.47

Report was unsubmitted during this print-out.

< END OF ESTIMATES >