

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119021988/EYF3E2

Date: 25/06/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30597919022

Claimant Vehicle No : SJN9777R

Insured Vehicle No : GBD2608P

Date of Loss: 10/12/2019

Nature of Claim: TP

Claim No: SNM19D205921C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN9777R**

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A)

Engine No: 1AZE121988

Reg. Date: 29/12/2008 (Man. Year: 2008)

Chassis No: MR053BK4107038092

Colour: Silver

Odometer: 134480 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,710.00	1,485.00	2,225.00	59.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,221.87	869.47	352.40	28.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,931.87	2,354.47	2,577.40	52.26
+ GST 7.00/7.00% (S\$)	345.23	164.81	180.42	52.26
Nett Amount (S\$)	5,277.10	2,519.28	2,757.82	52.26

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 13/12/2019 Inspected At:

Car City Auto Centre Pte Ltd (HQ)
Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2020)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN9777R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	230.00 F	*230.00 F
2	1		*R/F UPP BUMPER BRKT	Broken	30.00 F	*30.00 F
3	1		*BUMPER SUPPORT	Not Necessary	120.00 F	*- F
4	1		*FRT BUMPER ABSORBER	Not Necessary	40.00 F	*- F
5	1		*CTR BUMPER GRILLE	Not Necessary	55.00 F	*- F
6	1		*BONNET	Dented	380.00 F	*380.00 F
7	1		*L/BONNET HINGE	Not Necessary	30.00 F	*- F
8	1		*R/BONNET HINGE	Not Necessary	30.00 F	*- F
9	1		*LOWER BONNET LOCK	Not Necessary	40.00 F	*- F
10	1		*L/BONNET DAMPER	Not Necessary	65.00 F	*- F
11	1		*R/BONNET DAMPER	Not Necessary	65.00 F	*- F
12	1		*RIGHT HEADLAMP ASSY	Broken	320.00 F	*320.00 F
13	1		*L/F BUMPER MOULDING	Necessary	35.00 F	*35.00 F
14	1		*R/F BUMPER MOULDING	Cut	35.00 F	*35.00 F
15	1		*R/F WING	Dented	175.00 F	*175.00 F
16	1		*R/WING MOULDING	Not Necessary	45.00 F	*- F
17	1		*R/WHEELHOUSE SHELL	Torn	65.00 F	*65.00 F
18	1		*LOCK CARRIER STRUT	Not Necessary	35.00 F	*- F
19	1		*FRONT PANEL	Repair	350.00 F	*- F
20	1		*R/RADIATOR AIR GUIDE	Not Necessary	40.00 F	*- F
21	1		*R/SIDE MEMBER EXT	Not Necessary	65.00 F	*- F
22	1		*WASHER CONTAINER	Not Necessary	60.00 F	*- F
23	1		*BADGE VVT-I R	Necessary	15.00 F	*15.00 F
24	1		*CONDENSER	Not Necessary	400.00 F	*- F
25	1		*RADIATOR	Not Necessary	480.00 F	*- F
26	1		*RH FOG LAMP	Not Necessary	80.00 F	*- F
27	1		*RH FOG LAMP COVER	Not Necessary	55.00 F	*- F
28	1		*SUNDRY PARTS	Necessary	100.00 FS	*30.00 FS
29	1		*SUNDRY PARTS	Not Necessary	100.00 FS	*- FS
30	1		*GRILLE	Broken	140.00 F	*140.00 F
31	1		*BONNET EMBLEM	Necessary	30.00 F	*30.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,710.00** **1,485.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	25.00	25.00
2	ANTI FREEZE	New	20.00	0.00
3	AIR -CON GAS	New	50.00	0.00
4	CHECK WIRING	New	25.00	0.00
5	TOTAL 109.0 WU X 42.00 SGD/H	New	457.80	260.40
6	ALIGNMENT FIXED RATE	New	60.00	0.00
7	LABOUR COST 95.0 WU X 42.00 SGD/H	New	399.00	399.00
8	MATERIAL COST	New	185.07	185.07
Gross Labour Cost (S\$)			1,221.87	869.47

Report was unsubmitted during this print-out.

< END OF ESTIMATES >