

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021989/R1DS3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GBB2689R

Insured Vehicle No : GBG5726X

Date of Loss: 09/12/2019

Nature of Claim: TP

Claim No: 8756441331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB2689R**

Make & Model: TOYOTA HIACE, 2.0 (M)

Engine No: 1KD1747606

Reg. Date: 08/10/2008 (Man. Year: 2007)

Chassis No: KDH2010012227

Colour: Grey

Odometer: 0 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C

Rear Tyre Size: 195R15C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,251.00	3,390.50	2,860.50	45.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,170.00	1,880.00	46.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,301.00	5,560.50	4,740.50	46.02
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	10,301.00	4,450.00	5,851.00	56.80
+ GST 7.00/7.00% (S\$)	721.07	311.50	409.57	56.80
Nett Amount (S\$)	11,022.07	4,761.50	6,260.57	56.80
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		5,361.50		
Global Sum Settlement (S\$)		5,360.00		

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 23/12/2019 Inspected At:

Automobile Integrated Management

Pte Ltd (HQ)

23 Kaki Bukit Ave 4 #04-01, Kaki Bukit

(South Wing)

Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,062.00 FL	*1,600.00 FL
2	1		*TAILGATE LOGO	Necessary	135.00 FL	*75.00 FL
3	1		*TAIL LAMP ASSY LH	Broken	786.00 FL	*450.00 FL
4	1		*REAR FENDER PANEL LH	Buckled	1,988.00 FL	*1,620.00 FL
5	1		*REAR BUMPER	Deformed	982.00 FL	*365.00 FL
6	1		*REAR BUMPER SIDE RETAINER	N/S Necessary	243.00 FL	*40.00 FL
7	1		*REAR END PANEL OUTER	Repair	1,288.00 FL	*- FL
8	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	90.00 FS	*60.00 FS
9	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	135.00 FS	*100.00 FS
10	1		*REAR SIDE PANEL GLASS SEALANT	Necessary	90.00 FS	*60.00 FS
11	1		*70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
12	8		*TAIL GATE TRIM BOARD CLIP	Necessary	48.00 FS	*48.00 FS
13	1		*REVERSE SENSOR	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,122.00	4,428.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,871.00	1,037.50
Total Parts (\$\$)	6,251.00	3,390.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,200.00	750.00
3	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY ATTACHMENTS	New	250.00	80.00
4	TO REMOVE,REFIX REAR WINDSCREEN GLASS AND WATER TEST	New	250.00	120.00
5	TO REMOVE,REFIX SIDE PANEL GLASS AND WATER TEST LH	New	250.00	120.00
6	TO REMOVE,REFIX REAR INTERIOR GARNISHES UPHOLSTERY	New	200.00	100.00
7	TO INSTALL REVERSE SENSOR AND TEST FUNCTION	New	100.00	0.00
Gross Labour Cost (\$\$)			4,050.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >