

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021990/NBA3Q2
Date: 05/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900250204	
Claimant Vehicle No : SHA1161L	Insured Vehicle No : SMQ7159L	
Date of Loss: 07/12/2019	Nature of Claim: TP	Claim No: 9485128175SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA1161L		
Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No: D4DFDU540146	
Reg. Date: 26/05/2016 (Man. Year: 2016)	Chassis No: KMHLB41UMGU089934	
Colour: Blue	Odometer: 352476 km	
Engine Capacity: 1685 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16	Rear Tyre Size: 205/60 R16	
Front Left Side: Hankook 5 mm	Rear Left Side: Hankook 6 mm	
Front Right Side: Hankook 5 mm	Rear Right Side: Hankook 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,908.08	470.88	2,437.20	83.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,200.00	640.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,748.08	1,670.88	3,077.20	64.81
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	4,748.08	1,350.00	3,398.08	71.57
+ GST 7.00/7.00% (S\$)	332.37	94.50	237.87	71.57
Nett Amount (S\$)	5,080.45	1,444.50	3,635.95	71.57
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$116.95/day) (S\$)		701.70		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,453.69		
Global Sum Settlement (S\$)		2,450.00		

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 13/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

4/5/2021

Adjuster Report

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY-RR BUMPER	Deformed	553.00 FL	*553.00 FL
2	1		*BEAM -RR BUMPER	Serviceable	428.40 FL	*- FL
3	1		*STAY -RR BUMPER RH	Serviceable	80.30 FL	*- FL
4	10		*HYUNDAI BUMPER COVER CLIP	Serviceable	22.00 FL	*- FL
5	1		*PANEL ASSY -QUARTER	Repair	2,171.40 FL	*- FL
6	1		*MOULDING -RR WDO GLA	Not Necessary	28.30 FL	*- FL
7	2		*(ALL) WINDSCREEN AHESIVE -3	Not Necessary	46.00 FS	*- FS
8	1		*COVER -RR BUMPER LWR	Serviceable	228.00 FL	*- FL
9	1		*REFLECTOR /REFLEX AS	Serviceable	30.60 FL	*- FL
10	1		*REAR BUMPER SIDE BRACKET	Deformed	35.60 FL	*35.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,623.60	588.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	715.52	117.72
Total Parts (\$\$)	2,908.08	470.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	560.00
2	SPRAY PAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	50.00	0.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	40.00
5	REMOVE/REFIX UPHOLSTERY ASSY REPAIR	New	120.00	0.00
6	REMOVE/REFIX RR WINDSCREEN GLASS	New	120.00	0.00
7	RENEW ADVERTISEMENT STICKER	New	200.00	200.00
Gross Labour Cost (S\$)			1,840.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >