



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7707Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	CRACKED	1,576.80	1,500.80
1	REAR BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	147.60	-
1	REAR BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	147.60	-
1	REAR BUMPER CENTER BRACKET (CONSISTENT)	SERVICEABLE	248.90	-
1	REAR BUMPER BRACKET RH (CONSISTENT)	SERVICEABLE	195.80	-
1	REAR BUMPER BRACKET LH (CONSISTENT)	CRACKED	195.80	98.80
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	SCRATCHED	485.60	280.70
1	REAR BUMPER CHROME PIECE (LH)	SCRATCHED	245.70	220.80
1	REAR BUMPER CHROME DIFFUSER LH (CONSISTENT)	SCRATCHED	382.50	382.50
3	REVERSE SENSOR (L/H) (CONSISTENT)	SHORTED (1 PCS ONLY)	420.00	192.00
1	SET REVERSE SENSOR WIRE HARNESS (CONSISTENT)	SERVICEABLE	685.00	-
6	REAR BUMPER REVERSE SENSOR HOLDER (CONSISTENT)	NECESSARY (4 PCS ONLY)	180.00	180.00
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	128.60	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	698.70	-
1	TAIL LAMP LH (CONSISTENT)	SCRATCHED	1,150.80	827.20
	LESS 10% DISCOUNT		-	-368.28
			6,889.40	3,314.52
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	60.00	25.00
1	SET TAIL LAMP CLIP (SN) (CONSISTENT)	NECESSARY	30.00	10.00
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			140.00	35.00
<b><u>LABOUR</u></b>				
	TO R&R REAR BUMPER REVERSE SENSOR .		100.00	20.00
	TO CHECK WIRING AND LIGHTING SYSTEM.		80.00	20.00
	TO SUPPLY UNDER-COATING/PUTTY ON PARTS REPLACED.}		80.00	20.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.}		60.00	-

Report Ref No. CC4/ASM19021995/Hps3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DIAGNOSTIC ERASE FAULT CODE MEMORIES.		180.00	100.00
	TO REPAIR ,REPLACE AND REALIGN DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		600.00	250.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		600.00	250.00
			1,700.00	660.00
<b>GRAND TOTAL</b>			<b>8,729.40</b>	<b>4,009.52</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,200.00</b>
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CC4/ASM19021995/Hps3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.