



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6573T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER, LH	BROKEN	450.00	450.00
1	BUMPER BRACKET, LH	BROKEN	70.00	70.00
1	HEADLAMP, LH	CRACKED	700.00	700.00
1	STEP PANEL, LH	TO REPAIR SEE LABOUR	787.50	-
1	SIDE SIGNAL LAMP, LH	BROKEN	37.50	37.50
	LESS 20% DISCOUNT		-409.00	-251.50
			1,636.00	1,006.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS, CHECK LAMP WIRING ETC. INCLUSIVE OF THE REPAIR OF STEP PANEL, LH.		1,400.00	875.00
			1,400.00	875.00
	GRAND TOTAL		3,036.00	1,881.00
RECOMMENDED COST OF REPAIRS				1,881.00

Report Ref No. CC4/FCI19021998/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.