



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003398
INV Date 23/04/2020
Reference CS/SMO19022017/Atd3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SMG 8870L
Insured Veh. YN 9893K
Claim No. CMTD1905755/MYE
Policy No.
Accident Date 09/12/2019
Inspection Date 16/12/2019

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO19022017/Atd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 23-04-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 9893K	Veh. Inspected	SMG 8870L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905755/MYE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	13/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800347181	Colour	WHITE
Odometer	36884	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	GOODYEAR	6 mm
L/H Front Tyre	195/55 R15	GOODYEAR	6 mm
R/H Rear Tyre	195/55 R15	GOODYEAR	6 mm
L/H Rear Tyre	195/55 R15	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/12/2019	Inspection Date	16/12/2019
Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 8870L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	TO REPAIR SEE LABOUR	1,860.00	-
1	TAIL GATE EMBLEM	NECESSARY	75.40	75.40
1	TAIL GATE OUTER CHROME MOULDING	NOT NECESSARY	781.00	-
1	TAIL GATE EMBLEM "HYBRID SYNERGY DRIVE"	NECESSARY	69.70	69.70
1	TAIL GATE INNER GARNISH RH	NOT NECESSARY	245.00	-
1	TAIL LAMP RH	CRACKED	789.40	789.40
1	REAR WINDSCREEN GLASS }	SHATTERED	2,002.95	1,650.00
1	REAR WINDSCREEN MOULDING }	NECESSARY	-	-
	LESS 25% DISCOUNT		-	-646.13
			5,823.45	1,938.37
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN PRIMER & CLEANER (SN)	NECESSARY	50.00	50.00
1	TAIL GATE SEALANT (SN)	NOT NECESSARY	50.00	-
10	TAIL GATE INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
			250.00	150.00
	<u>LABOUR</u>			
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF TAIL GATE.		600.00	200.00
	TO SPRAY PAINT ON AFFECTED AREAS.		600.00	400.00
	TO CHECK WIRING.		120.00	30.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.	NOT NECESSARY	150.00	-
	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS.		180.00	120.00
	TO DISMANTLE,REPLACE AND/OR REPAIR TAIL GATE COMPONENTS.	NOT NECESSARY	180.00	-
			1,830.00	750.00
	GRAND TOTAL		7,903.45	2,838.37



RECOMMENDED COST OF REPAIRS			2,838.37
------------------------------------	--	--	-----------------

Report Ref No. CS/SMO19022017/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 8870L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

