

OWNER:

MERINA CHIA

CC4/FCI19022018/Uda3

LKK:

IDAC:

ASSIGNMENT

MARCUS

DOI: 13/12/2019

Date / Time: 13/12/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: SHA 8572M

Name of Insured: CITYCAB PTE LTD

Insured Tel No.: HP:

Excess Sec II :SS

D.O.A: 09/12/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHIA SEAH

Driver Tel No.: +65-91294633

(V/L: YES / NO)

Claim No.: D19007804MFSH

Policy No.: D-19092579MFSH

Make / Model: HYUNDAI I40-1.7 D CRDI (A)

Place of Accident: ALONG JURONG GATEWAY ROAD
TOWARDS TOH GUAN ROAD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GBB 938K

INSRS:
WSP: LIU'S BROTHER
Tel: AUTO
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	GBB 938K - X	Non-Reporting ltr (1st):	
	SHA 8572M - CS/FCI13009010/T1y1d1; DOA: 13.5.13	Non-Reporting ltr (2nd):	
	- CC4/AXA16012326/H1ua3q2; DOA: 30.6.16	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Susan

Email ☒Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 37

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 5550.00

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

40.00

(S

80

x

8

days)

Loss of Income (LOI):

S\$

-

(S

-

x

days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format: P

3) Survey fee: \$500

Total:

S\$ 6197.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

6197.45

Name 1:

Liu's Brother Auto Engineering Workshop

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 47883

LOB No: 532917931, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liusbros@gmail.com

Invoice/Ref No: GBB938K191209

Estimate

Customer

Name: MS First Capital Insurance Limited

Date: 12-12-19

Address: Motor Claims Department

Vehicle No: GBB938K

36 Robinson Road #16-01

Model/Make: Toyota Hiace

City House

Singapore 068877

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>1815.10</i>	\$ 1,850.00	
2	Tailgate Rubber	\$ 387.90	
3	Tailgate Lock	\$ 359.00	
4	Number Plate Outer Garnish		X
5	Tailgate Inner Trim Board	\$ 165.30	X
6	Tailgate Inner Trim Board Clips 1 set	\$ 50.00	X
7	Tailgate "Toyota Logo" Motif	\$ 70.50	
8	Tailgate "70 KM/H" Sticker	\$ 15.00	SN 10 S.W
9	Tailgate "8 Pax" Sticker	\$ 15.00	SN 10 S.W
10	Number Plate (Metal Plate)	\$ 35.00	SN X
11	Tail Lamp Rh	\$ 365.10	
12	Tailgate Corner Panel Rh	\$ 165.80	
13	Corner Panel Garnish Bracket	\$ 31.50	X
14	Tailgate Windscreen Moulding	\$ 285.90	X
15	Tailgate Windscreen Sealant	\$ 45.00	405.00
16	Bumper	\$ 496.50	
17	Bumper Clips 1 set	\$ 48.00	
18	Bumper Side Bracket 4 pcs (@ \$51.00) <i>@ 28.00/pc</i>	\$ 404.00	112
19	Bumper Reverse Sensor	\$ 220.00	SN 2005.00
20	End Panel Inner	\$ 936.20	
21	End Panel Outer	\$ 566.10	
22	End Panel Sealant <i>252</i>	\$ 50.00	SN 5.00
23	Wooden Board (Plywood)	\$ 250.00	SN X
24	Spare Tyre Carrier	\$ 250.60	
25	Exhaust Pipe	\$ 971.10	
26	Exhaust Pipe Mounting 02 pcs (@ \$542.50)	\$ 85.00	X
27	"Company Advertisement" Sticker	\$ 300.00	SN X
	Remove and refix rear Bumper distance sensor	\$ 90.00	50
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	To check all wiring & electrical component for proper function	\$ 80.00	20
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 200.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	780
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	600
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	60
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	100

Total Parts & Labour of estimate for damaged vehicle

\$ 10,888.50

Total amount in Lump Sum Basis for repaired vehicle

Note: Repairs

- To resurvey damaged parts during resurvey
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledgement



M/s Liu's Brother Auto Engrg Wks

P- 6543.90

252

P- 4907.92

S.W- 310.00

L- 1730.00

6947.92

not Allowed

2/5 \$ 5550

6 day

13/12/19 take up the bill



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19007804MFSH
Our ref: CC4/FCI19022018/Uda3

Date: 27.12.2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBB 938K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13-12-2019 at the premises of M/s Liu's Brother Auto Engineering Workshop have the following to report:-

Workshop Estimate Amount	: S\$	10,888.50
Revised Estimate Amount	: S\$	5,800.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	5,800.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 day

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 12 Dec 2019 / 11:18:50

Receipt Date/Time : 12 Dec 2019 / 11:18:37

Tax Invoice/Receipt

Receipt No. : ITNET-00000-191212-001150

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA8572M				
As at 09 Dec 2019/09:20:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
1	Insurance Enquiry - SHA8572M			
	Enquiry Fee	7.00	0.49	7.49
	20191212111657185351			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx8946		Credit Card: Visa /MasterCard	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

2.12

FLASH SALE
EXTRA 12% OFF
CODE: 12FLASH

CALVIN KLEIN
SHOP NOW

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

X'Mas Offer! Free 1 Year Insurance And 1 Year Road Tax!



2 Years Extended Warranty For
Engine And Gearbox!
AutoPrestige Gallery - StarAd

Lake View
Credit Pte Ltd

[view our cars](#)

> Low prices guaranteed

> Specialist in Japanese cars

> Easy loan approval

> All terms are negotiable

Browse by Category ▼

[« Back](#) ([1](#) [2](#) [3](#)) [Next »](#)

Sort by Date Posted ▼ 20 results/page ▼

49 vehicles

HIACE

Advanced Search [Submit](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	HIACE		Any	Any	> 10 year(s) old	Any	Any	Any	Available



Toyota Hiace 3.0M (COE till 08/2024)

Fuel Type: Diesel

New Paint. New Suspension. Aluminum Protected Loan 90% Of The Car Price. Monthly \$600 Plus.

Posted: 12-Dec-2019 Tags: 2009 Toyota Hiace, 2009 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

27,800

\$5,960 /yr

12-Aug-2009

2,982 cc

170,000 km

Van

Available

[Contact Dealer](#)



Toyota Hiace 3.0M (COE till 07/2022)

Fuel Type: Diesel

Car Search

Posted: 12-Dec-2019 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

19,800

\$7,580 /yr

24-Jul-2007

2,982 cc

-

Van

Available

[View More](#)



Toyota Hiace 3.0M (COE till 04/2023)

Fuel Type: Diesel

One Of The Most Durable And Reliable Workhorse For Sales! 5 Doors Catering Van For Your Business Needs, Very Fuel Efficient, Trade-I...

Posted: 12-Dec-2019 Tags: 2008 Toyota Hiace, 2008 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

22,388

\$6,670 /yr

23-Apr-2008

2,982 cc

-

Van

Available



Toyota Hiace 3.0M (COE till 07/2022)

Fuel Type: Diesel

We Provide Door Steps Viewing, 5 Doors, Well Kept Condition, Powerful Aircon, Easy In House Finance, High Trade In, Call Us Now For...

Posted: 12-Dec-2019 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

20,800

\$7,900 /yr

30-Aug-2007

2,982 cc

-

Van

Available



Is your COE expiring? Let us help you renew it!
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Hiace 3.0A (COE till 11/2024)

Fuel Type: Diesel

New 5-Years CDE Toyota Hiace, 1 Previous Owner, Wear And Tear Replaced. Trade In And High Loan Available. Doorstep Viewing Car B...

ABWIN (1994) Pte Ltd

Posted: 10-Dec-2019 Tags: 2009 Toyota Hiace, 2009 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

32,800

\$6,700 /yr

03-Nov-2009

2,982 cc

-

Van

Available



Toyota Hiace Commuter 3.0M (COE till 09/2024)

Fuel Type: Diesel

Very Nice Carplate 8816 Lucky Buyer Welcome! After Sales Service Guaranteed. Low Average Mileage Done. Accident Free & Welcome F...

ABWIN (1994) Pte Ltd

32,800

\$6,830 /yr

01-Oct-2009

2,982 cc

251,228 km

Bus

Available

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	196N

Vehicle Details

Vehicle No.:	GBB938K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1KD1814318
Chassis No.:	JTFHT02P100023184
Maximum Power Output:	-
Open Market Value:	\$24,647.00
Original Registration Date:	21 Jul 2008
First Registration Date:	21 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$1,233.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,100.00
COE Rebate Amount:	\$11,598.00
Total Rebate Amount:	\$11,598.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 13 Dec 2019

OK

MOTOR SURVEY ASSIGNMENT

Date 10-12-2019 Our Ref No. D19007804MFSH
 Accident Date 09-12-2019 Claim Type. Third Party
 Insured Vehicle SHA8572M Third Party Vehicle. GBB938K
 Survey Location 1 KAKI BUKIT AVENUE 8 #01-01 AUTOBAY @ KAKI BUKIT
 Contact Person. SUSAN LOW
 Contact No. 67411730/ 0 Fax No. 67445746
 Survey Type WITHOUT PREJUDICE:
 Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
 Contact Person NA Fax No. 68416315
 Contact Number. NA

11.51am ② 13/12/19
 P: SUSAN
 V: IN
 S: MERINA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop LIU'S BROTHER AUTO ENGINEERING WORKSHOP Attention. NIL
 Cc : TP Solicitor NA TP Solicitor Fax No. NA
 Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19022018/Uda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 11-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8572M	Veh. Inspected	GBB 938K
Policy No.	D-19092579MFSH	Coverage (\$)	0.00
Claim No.	D19007804MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	13/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JTFHT02P100023184	Colour	WHITE
Odometer	423691	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	AUSTONE	6 mm
L/H Front Tyre	195 R15	AUSTONE	6 mm
R/H Rear Tyre	195 R15	AUSTONE	6 mm
L/H Rear Tyre	195 R15	AUSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/12/2019	Inspection Date	13/12/2019
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 938K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BADLY DENTED	1,850.00	1,815.10
1	REAR TAILGATE RUBBER	TWISTED	387.90	387.90
1	REAR TAILGATE LOCK	DENTED / JAMMED	359.00	359.00
1	REAR NUMBER PLATE OUTER GARNISH (NPA)	NOT NECESSARY	-	-
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	165.30	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR TAILGATE "TOYOTA LOGO" MOTIF	NECESSARY	70.50	70.50
1	REAR TAIL LAMP RH	CRACKED	365.10	365.10
1	REAR TAIL LAMP PANEL RH	DENTED	165.80	165.80
1	REAR CORNER PANEL GARNISH BRACKET	NOT NECESSARY	31.50	-
1	REAR TAILGATE WINDSCREEN MOULDING	NO SUCH PARTS	285.90	-
1	REAR BUMPER	DISTORTED	496.50	496.50
1	SET REAR BUMPER CLIPS	NECESSARY	48.00	48.00
4	REAR BUMPER SIDE BRACKET @\$101.00	BENT	404.00	112.00
1	REAR END PANEL INNER	BADLY DENTED	936.20	936.20
1	REAR END PANEL OUTER	BADLY DENTED	566.10	566.10
1	REAR SPARE TYRE CARRIER	BENT	250.60	250.60
1	REAR EXHAUST PIPE	BENT/TWISTED	971.10	971.10
2	REAR EXHAUST PIPE MOUNTING @\$42.50	NOT NECESSARY	85.00	-
	LESS 25% DISCOUNT		-	-1,635.98
			7,488.50	4,907.92
SPECIAL NETT ITEMS				
1	REAR TAILGATE "70 KM/H" STICKER (SN)	NECESSARY	15.00	10.00
1	REAR TAILGATE "8 PAX" STICKER(SN)	NECESSARY	15.00	10.00
1	REAR NUMBER PLATE (METAL PLATE) (SN)	NOT NECESSARY	35.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	45.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WOODEN BOARD (PLYWOOD)(SN)	NOT NECESSARY	250.00	-

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR "COMPANY ADVERTISEMENT" STICKER(SN)	NOT FITTED	300.00	-
			930.00	310.00
	LABOUR			
	REMOVE AND REFIX REAR BUMPER DISTANCE SENSOR.		90.00	50.00
	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM.		80.00	60.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	20.00
	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILTATE REPAIRS.		200.00	60.00
	LABOR FOR PANEL BEATING , CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		1,000.00	780.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECT .		800.00	600.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS.		120.00	100.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	60.00
			2,470.00	1,730.00
GRAND TOTAL			10,888.50	6,947.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,550.00

Report Ref No. CC4/FC119022018/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.