

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBB938K191209

Estimate**Customer**

Name: MS First Capital Insurance Limited

Address: Motor Claims Department

36 Robinson Road #16-01

City House

Singapore 068877

Date: 12-12-19

Vehicle No: GBB938K

Model/Make: Toyota Hiace
Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>1815.10</i>	\$ 1,850.00	
2	Tailgate Rubber <i>1m</i>	\$ 387.90	
3	Tailgate Lock <i>11</i>	\$ 359.00	
4	Number Plate Outer Garnish <i>11</i>	\$ 165.30	
5	Tailgate Inner Trim Board <i>11</i>	\$ 50.00	
6	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 70.50	
7	Tailgate "Toyota Logo" Motif <i>11</i>	\$ 15.00	SN 10 S.W
8	Tailgate "70 KM/H" Sticker <i>11</i>	\$ 15.00	SN 10 S.W
9	Tailgate "8 Pax" Sticker <i>11</i>	\$ 35.00	SN X
10	Number Plate (Metal Plate) <i>11</i>	\$ 365.10	
11	Tail Lamp Rh <i>11</i>	\$ 165.80	
12	Tailgate Corner Panel Rh <i>11</i>	\$ 31.50	
13	Corner Panel Garnish Bracket <i>11</i>	\$ 285.90	
14	Tailgate Windscreen Moulding <i>11</i>	\$ 45.00	405.00
15	Tailgate Windscreen Sealant <i>11</i>	\$ 496.50	
16	Bumper <i>11</i>	\$ 48.00	
17	Bumper Clips 1 set <i>11</i>	\$ 404.00	112
18	Bumper Side Bracket 4 pcs (@ \$41) <i>28.00</i>	\$ 220.00	SN 2005.00
19	Bumper Reverse Sensor <i>11</i>	\$ 936.20	
20	End Panel Inner <i>11</i>	\$ 566.10	
21	End Panel Outer <i>11</i>	\$ 50.00	SN 5.00
22	End Panel Sealant <i>252</i>	\$ 250.00	SN X
23	Wooden Board (Plywood) <i>11</i>	\$ 250.60	
24	Spare Tyre Carrier <i>11</i>	\$ 971.10	
25	Exhaust Pipe <i>11</i>	\$ 85.00	
26	Exhaust Pipe Mounting 02 pcs (@ \$42.50) <i>11</i>	\$ 300.00	SN X
27	"Company Advertisement" Sticker <i>11</i>		
	Remove and refix rear Bumper distance sensor	\$ 90.00	50
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	To check all wiring & electrical component for proper function	\$ 80.00	20
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 200.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	780
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	600
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	60
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	100

Total Parts & Labour of estimate for damaged vehicle

\$ 10,888.50

LKK Auto Consultants hence notify

the Repairs on the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Partner

Signature

Date



M/s Liu's Brother Auto Engrg Wks

p. 6543.90

252

p. 4907.92

S.W. - 310.00

L - 2000.00

7257.92

2/5 \$ 5800

6 day

13/12/19

The Repairs on the following: