

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022029/EDA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBJ5838R **Insured Vehicle No :** SMJ5347K

Date of Loss: 03/12/2019 **Nature of Claim:** TP **Claim No:** 3738452941SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5838R	Engine No:	K9KE628D660162
Make & Model:	NISSAN NV200, 1.5 (M)	Chassis No:	VSKYBAM20Z0176742
Reg. Date:	31/05/2019 (Man. Year: 2018)	Odometer:	20069 km
Colour:	Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,668.72	4,770.98	3,897.74	44.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,350.00	1,470.00	38.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,488.72	7,120.98	5,367.74	42.98
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	12,488.72	5,700.00	6,788.72	54.36
+ GST 7.00/7.00% (S\$)	874.21	399.00	475.21	54.36
Nett Amount (S\$)	13,362.93	6,099.00	7,263.93	54.36
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		45.00		
Nett Liability (S\$)		6,786.00		
Global Sum Settlement (S\$)		6,750.00		

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 13/12/2019 Inspected At:

Efficient Motor & Engineering Works
Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang

Enterprise Building
Singapore 508775

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Dented	1,651.80 FL	*1,219.70 FL
2	1		*RH SLIDING DOOR	Dented	1,281.70 FL	*1,281.70 FL
3	1		*FUEL FLAP	Dented	119.60 FL	*119.60 FL
4	1		*RH REAR FENDER	Repair	504.70 FL	*- FL
5	1		*RH REAR FENDER INNER SEAL	Not Necessary	138.90 FL	*- FL
6	10		*RH REAR FENDER INNER SEAL CLIPS	Not Necessary	44.00 FL	*- FL
7	1		*RH REAR WHEEL CAP	Cut	136.80 FL	*136.80 FL
8	1		*RH FRONT LOWER ARM	Not Necessary	200.50 FL	*- FL
9	1		*RH FRONT KNUCKLER ARM	Not Necessary	357.20 FL	*- FL
10	1		*RH FRONT KNUCKLER ARM BEARING	Not Necessary	329.70 FL	*- FL
11	1		*RH FRONT WHEEL CAP	Broken	136.80 FL	*136.80 FL
12	1		*LH FRONT WHEEL CAP	Missing	136.80 FL	*136.80 FL
13	1		*RHR FRONT DOOR BLACK STICKER	Not Necessary	26.60 FL	*- FL
14	1		*RHR FRONT DOOR HING TOP	Dented	56.10 FL	*56.10 FL
15	1		*RHR FRONT DOOR HING BOTTOM	Dented	56.10 FL	*56.10 FL
16	1		*RHR FRONT DOOR CHECKER	Not Necessary	39.50 FL	*- FL
17	1		*RHR FRONT DOOR PILLAR	Repair	726.40 FL	*- FL
18	1		*CENTRE PILLAR RH	Dented	708.40 FL	*708.40 FL
19	1		*ABSORBER LH ,FRONT	Bent	252.80 FL	*252.80 FL
20	1		*LOWER ARM LH ,FRONT	Bent	200.50 FL	*200.50 FL
21	1		*KNUCKLE ARM LH FRONT	Bent	357.20 FL	*357.20 FL
22	1		*KNUCKLE ARM BEARING LH,FRT	Necessary	329.70 FL	*329.70 FL
23	1		*RH REAR RIM	Not Necessary	199.20 FS	*- FS
24	1		*RH FRONT SHOCK ABSORBER	Not Necessary	252.80 FS	*- FS
25	1		*FRONT CROSS MEMBER	Not Necessary	325.70 FS	*- FS
26	1		*RH FRONT RIM	Not Necessary	199.20 FS	*- FS
27	1		*LH FRONT RIM	Bent	199.20 FS	*150.00 FS
28	1		*LH FRONT TYRE (80%) (\$160.00)	Cut	160.00 FS	*128.00 FS
29	1		*RH FRONT TYRE	Not Necessary	160.00 FS	*- FS
30	1		*RH REAR TYRE	Not Necessary	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,447.90	5,270.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	779.18	499.22
Total Parts (\$\$)	8,668.72	4,770.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	1,400.00	1,000.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	900.00
3	WIRING	New	80.00	30.00
4	TOWING	New	120.00	60.00
5	LABOUR FOR REMOVE & REFIX LH FRONT UNDERCARRIAGE	New	400.00	200.00
6	FRONT WHEEL ALIGNMENT CHECK	New	120.00	60.00
7	LABOUR FOR REPAIR & STRAIGHTEN BOTH FRONT CHASSIS FRAME	New	300.00	0.00
8	LABOUR FOR TRANSFER ALL RH SLIDING DOOR FITTING	New	200.00	50.00
9	LABOUR FOR TRANSFER ALL RH FRONT DOOR FITTING	New	200.00	50.00
Gross Labour Cost (S\$)			3,820.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >