



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 8320D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR LH	DENTED	1,231.70	1,200.00
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,179.30	-
1	LOCKER PANEL LH	DENTED	494.75	494.75
1	FRONT DOOR WEATHER STRIP LH	TORN	169.79	169.79
1	FRONT DOOR LOCK LH	JAMMED	421.76	421.76
1	FRONT DOOR CHECKER	BENT	195.40	139.10
1	FRONT DOOR REGULATOR	JAMMED	188.91	188.91
1	FRONT DOOR REGULATOR MOTOR	JAMMED	511.65	499.10
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	858.64	-
1	FRONT DOOR OUTER CHROME MOULDING	BENT	158.47	130.70
1	FRONT DOOR INNER TRIM	CRACKED	799.60	799.60
1	SIDE MIRROR LH	NOT NECESSARY	901.60	-
1	FRONT DOOR OUTER HANDLE	DISLODGE	167.41	167.41
	LESS 25% DISCOUNT		-	-1,052.78
			7,278.98	3,158.34
<u>SPECIAL NETT ITEMS</u>				
10	FRONT DOOR INNER TRIM CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT DOOR LH SEALANT (SN)	NECESSARY	50.00	30.00
1	REAR DOOR LH SEALANT (SN)	NECESSARY	50.00	30.00
	FRONT DOOR BODY WEATHER STRIP LH (ADDITIONAL) (SN)	TORN	323.70	323.70
			473.70	413.70
<u>LABOUR</u>				
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR LH AND FRONT FENDER LH .		1,000.00	800.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,000.00	800.00
	TO DISMANTLE REPLACE AND /OR REPAIR FRONT LH DOOR COMPONENTS.		180.00	80.00
	TO DISMANTLE ,REPLACE AND /OR REPAIR REAR LH DO	NOT NECESSARY	180.00	-

Report Ref No. CC4/FCI19022030/Bha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING FOR RUST PROOFING .		200.00	120.00
	TO CHECK WIRING .		150.00	80.00
			2,710.00	1,880.00
	GRAND TOTAL		10,462.68	5,452.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,350.00

Report Ref No. CC4/FCI19022030/Bha3q2

LIM TEOW GUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.