

© 2005 Blackwell Publishing Ltd

ASS. MED. BY:

Europe: Rasu

REF:

REF: C9/CT119027068/R14f3

Special Instructions:

ASSIGNMENT (Office)

FELIX (PERSON)

Week 7

of

CTI

Date/Time:

11/12/15

Estimated Cost:

Bill 666

$$OD(TP)/WS/TPRES/ODRES/EVA/INV/MV/CS$$

To Inspect Vehicle No:

GBE 4175

Ingeniería

62042

1st Workshop m/s

Siā Shung

Teh

6863 9595



No 8 Tuas Ave 18

Policy No:

Claim No:

SNM19D 205941

Sum Insured:

Excentric

Make of Veh:

D.O.A.

11/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

6/17/19 @ 11:54 AM

Person Contacted:

Suzanne

Vehicle IN/OUT

[illegible]

The UIC / Chassis frame / Body Structure affected due to collision.

230

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003023

Date : 13/12/2019
Vehicle Num. : GBE417G
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : JTFHT02P900174967/1KD2546989
Accident Date : 11/12/2019
Claim No. :
Reference : GBH6204Z
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR DOOR <i>bt</i>		2,150.20
2.	1	REAR DOOR LOCK <i>bt</i>		275.10
3.	1	REAR DOOR GARNISH <i>new</i>		365.90
4.	1	TOYOTA EMBLEM <i>new</i>		53.50
5.	1	REAR BODY WEATHERSTRIP <i>X new</i>		312.10
6.	<i>21 pc</i>	REAR LAMP (LH) <i>new</i>	365.90	731.80
7.	<i>21 pc</i>	REAR LAMP GARNISH <i>de (LH)</i>	165.20	330.40
8.	1	REAR BUMPER <i>de (LH)</i>		677.50
9.	2	BUMPER SIDE BRACKET <i>X new</i>	123.50	247.00
10.	6	BUMPER CLIP <i>new</i>	5.00	30.00
11.	1	REAR END PANEL <i>repair</i>		585.90
List Total S\$:				5,759.40
25.00% Discount S\$:				1,439.85
				4,319.55

NETT ITEMS :				
1.	1	REVERSE SENSOR <i>new shorter</i>		250.00 <i>200?</i>
2.	1	70km/h Sticker <i>new</i>		20.00/0
3.	1	8 PAX STICKER <i>new</i>		20.00/0
4.	1	SEALANT <i>new</i>		40.00/
5.	1	NUMBER PLATE <i>X new</i>		20.00 X

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Estimate : ES003023

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Date : 13/12/2019
Vehicle Num. : GBE417G
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : JTFHT02P900174967/1KD2546989
Accident Date : 11/12/2019
Claim No. :
Reference : GBH6204Z
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
6.	1	LOGO		400 250 650.00
		Nett Total S\$:		1,000.00
		10.00% Discount S\$:		100.00
				900.00
		LABOUR :		
		TO DISMANTLE/REPLACE REAR WINDSCREEN		120.00
		TO PANEL BEAT/REPAIR REAR BODY		1,100.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		700.00
		TO SPRAY PAINTING		850.00
		TO APPLY TUFF-KOTE		80.00
		TO CHECK WIRING		50.00
		LOSS OF USE : 8 DAYS @ \$120/DAY		
		Labour Total S\$:		2,200.00
Total S\$:				7,419.55

SIN SHENG ENGINEERING SERVICES

Yuanne

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003023

Date : 13/12/2019
Vehicle Num. : GBE417G
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : JTFHT02P900174967/1KD2546989
Accident Date : 11/12/2019
Claim No. :
Reference : GBH6204Z
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR DOOR <i>bt</i>		2,150.20
2.	1	REAR DOOR LOCK <i>bt</i>		275.10
3.	1	REAR DOOR GARNISH <i>ne</i>		365.90 X
4.	1	TOYOTA EMBLEM <i>ne</i>		53.50
5.	1	REAR BODY WEATHERSTRIP X		312.10 X
6.	<i>2/pk</i>	REAR LAMP (LH) <i>ca</i>		731.80 X
7.	<i>2/pk</i>	REAR LAMP GARNISH <i>de</i> (LH)		330.40 X
8.	1	REAR BUMPER <i>de</i>		677.50
9.	2	BUMPER SIDE BRACKET X	123.50	247.00 X
10.	6	BUMPER CLIP <i>ne</i>	5.00	30.00
11.	1	REAR END PANEL <i>repair</i>		585.90 R X
List TotalSS :				5,759.40
25.00% Discount SS :				1,439.85
				4,319.55
NETT ITEMS :				
1.	1	REVERSE SENSOR <i>7AW</i>		258.00 <i>200?</i>
2.	1	70km/h Sticker <i>ne</i>		20.00/0
3.	1	8 PAX STICKER <i>ne</i>		20.00/0
4.	1	SEALANT <i>ne</i>		40.00
5.	1	NUMBER PLATE X		20.00 X

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003023

Date : 13/12/2019
Vehicle Num. : GBE417C
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : JTFHT02P900174967/1KD2546989
Accident Date : 11/12/2019
Claim No. :
Reference : GBH6204Z
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
6.	1	LOGO		
		Nett Total S\$:		
		10.00% Discount S\$:		
		LABOUR :		
		TO DISMANTLE/REPLACE REAR WINDSCREEN		
		TO PANEL BEAT/REPAIR REAR BODY		
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		TO SPRAY PAINTING		
		TO APPLY TUFF-KOTE		
		TO CHECK WIRING		
		LOSS OF USE : 8 DAYS @ \$120/DAY		
		Labour Total S\$:		

400
2500 650.00 660
1,000.00 102
100.00
900.00 594
5 days
4/8
16/12/19 @ 1600
Resy after repair 1570
120.00
1,100.00 600
700 500
850.00 600
80.00 60
50.00 30

2,200.00

Total S\$: 7,419.55

SIN SHENG ENGINEERING SERVICES

2788.05

594.00

1510.00

4892.05

202

3913.64

4/5 - 3,900

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2019		16 Dec 2019 11:39 Edit Adj Rpt	S\$3,900.00 Edit Estimates	S\$3,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ID: -									
Main Claimant: GOLDBELL LEASING PTE LTD									
Vehicle Reg. No.: GBE417G		Date of Loss: 11/12/2019 17:00 - :59 [31 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D205941C02		Policy/Cover Note No.: DMCVSN19146419000							
Vehicle Reg. No. (Insured): GBH6204Z		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/12/2019]									
Adj Asp. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE417G (SNM19D205941C02)
[GBH6204Z]
TP
GOLDBELL LEASING PTE LTD
Dec 11 2019 5:00PM
[-]
Sin Sheng Engineering Services

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/01/20 10:59	Accident Photo		Load JPG	☒
2	09/01/20 10:59	Accident Photo		Load JPG	☒
3	09/01/20 10:59	Accident Photo		Load JPG	☒
4	09/01/20 10:59	Accident Photo		Load JPG	☒
5	09/01/20 10:59	Accident Photo		Load JPG	☒
6	09/01/20 10:59	Accident Photo		Load JPG	☒
7	09/01/20 10:59	Accident Photo		Load JPG	☒
8	09/01/20 10:59	Accident Photo		Load JPG	☒
9	09/01/20 10:59	Accident Photo		Load JPG	☒
10	09/01/20 10:59	Accident Photo		Load JPG	☒
11	09/01/20 10:59	Accident Photo		Load JPG	☒
12	09/01/20 10:59	Accident Photo		Load JPG	☒
13	09/01/20 10:59	Accident Photo		Load JPG	☒
14	09/01/20 10:59	Accident Photo		Load JPG	☒
15	09/01/20 10:59	Accident Photo		Load JPG	☒
16	09/01/20 10:59	Accident Photo		Load JPG	☒
17	09/01/20 10:59	Accident Photo		Load JPG	☒
18	09/01/20 10:59	Accident Photo		Load JPG	☒
19	09/01/20 10:59	Accident Photo		Load JPG	☒
20	09/01/20 10:59	Accident Photo		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19022068/R1YF3Q2

Date: 10/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19146419000

Claimant
Vehicle No : GBE417GInsured
Vehicle No : GBH6204Z

Date of Loss: 11/12/2019

Nature of Claim: TP

Claim
No: SNM19D205941C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE417G

Make & Model: TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT
2WD LGV (M)

Engine No: 1KD2546989

Reg. Date: 17/08/2015 (Man. Year: 2015)

Chassis No: JTFHT02P900174967

Colour: White

Odometer: 167497 km

Engine Capacity: 2982 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Austone 6 mm

Rear Left Side:

Austone 6 mm

Front Right Side: Austone 6 mm

Rear Right Side:

Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,219.55	3,382.05	1,837.50	35.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,510.00	690.00	31.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,419.55	4,892.05	2,527.50	34.07
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	7,419.55	3,900.00	3,519.55	47.44
+ GST 7.00/7.00% (S\$)	519.37	273.00	246.37	47.44
Nett Amount (S\$)	7,938.92	4,173.00	3,765.92	47.44

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 16/12/2019 Inspected At:

Sin Sheng Engineering Services (HQ)
3 Tech Park Crescent, Tuas Tech
Park
Singapore 638129

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Jan 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX DIESEL TURBO MT 2WD LGV (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE417G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR	Bent	2,150.20 FL	*2,150.20 FL
2	1		*REAR DOOR LOCK	Bent	275.10 FL	*275.10 FL
3	1		*REAR DOOR GARNISH	Not Necessary	365.90 FL	*- FL
4	1		*TOYOTA EMBLEM	Necessary	53.50 FL	*53.50 FL
5	1		*REAR BODY WEATHERSTRIP	Not Necessary	312.10 FL	*- FL
6	1		*REAR LAMP	N/S Damaged	731.80 FL	*365.90 FL
7	1		*REAR LAMP GARNISH	N/S Deformed	330.40 FL	*165.20 FL
8	1		*REAR BUMPER	Deformed	677.50 FL	*677.50 FL
9	2		*BUMPER SIDE BRACKET	Not Necessary	247.00 FL	*- FL
10	6		*BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
11	1		*REAR END PANEL	Repair	585.90 FL	*- FL
12	1		*REVERSE SENSOR	Shorted	250.00 FN	*200.00 FN
13	1		*70KM/H STICKER	Necessary	20.00 FN	*10.00 FN
14	1		*8 PAX STICKER	Necessary	20.00 FN	*10.00 FN
15	1		*SEALANT	Necessary	40.00 FN	*40.00 FN
16	1		*NUMBER PLATE	Not Necessary	20.00 FN	*- FN
17	1		*LOGO	Necessary	650.00 FN	*400.00 FN

F=Franchise part. L=ListItemDisc. N=NetItemDisc.

Sub Total (S\$)	6,759.40	4,377.40
- List Item Discount on L Items 25.00/25.00% (S\$)	1,439.85	929.35
- Nett Item Discount on N Items 10.00/10.00% (S\$)	100.00	66.00
Total Parts (S\$)	5,219.55	3,382.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REPLACE REAR WINDSCREEN	New	120.00	120.00
2	TO PANEL BEAT /REPAIR REAR BODY TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS	New	1,100.00	700.00
3	TO SPRAY PAINTING	New	850.00	600.00
4	TO APPLY TUFF-KOTE	New	80.00	60.00
5	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			2,200.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >