

ASS. REC. BY:

REF: CS /MSG19022070/Kuf3 n2

Special Instruction:

Surveyor: Merimen

ASSIGNMENT (Office)

From (Person): Paulin Thomof MS1GDate/Time: 16.12.2019 10.00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 3568RInsured: SK R 5356Rat Workshop m/s Chung Hop MotorTel: 67556142of Bik 1019 # 01-3741382 YunnanPolicy No: 2906465A12

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.12.19 10.30amPerson Contacted: EfudaVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SMG 3568R - X
	SK R 5356R - X
17/12/19	Send preli revised via merimen

ASS. REC. BY:

REF: *MSG /*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SMQ 3568R*Yr Regn: *04, 07*Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: *Honda Fit*c.c. *1390*Colour: *M. Silver*A/C: ☒

Insured / Std / NI / NA

Sp. Reading: *63855*T/Radio: ☒

Insured / Std / NI / NA

Eng/No: _____

C/No: *GD 1**2382501*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ NII / ☐ S/Rim / ☐ STD A/Rim orTyre Size: *F: 195/55R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *GO*

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *12/12/19*D.O.A. *16/12/19*

Survey held at _____

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*1**File pass to**4/3**LLDy 824501 Confirm (Red 213.76, 469)*

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

*4/3 - typist*Days Of Repair: *5*Resurvey No. of Trip: *1*Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

F. & S.

Others

TOTAL

Report Format: *Merimen*Lump Sum / I.B.I. (\$) *2450/-**150**11**161*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 17 Dec 2019

Preliminary Advice

Insured Vehicle No	: SKR5356R	Accident Date	: 12/12/2019
TP Vehicle No	: SMQ3568R	Assignment Date	: 16/12/2019
Make	: HONDA FIT	Est. Duration of Repair	: 5
Date of Inspection	: 16/12/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,563.76
Revised Amount	:S\$	2,722.00
Check Items (Estimated)	:S\$	1,398.00
Total	:S\$	4,120.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2019 17:50		16 Dec 2019 10:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAN SIEW CHOO, ID: S1240516B, Tel: +6596215255								
Main Claimant:	SUN MASTER TRADING COMPANY, Co. Reg. No.: 31340600J								
Vehicle Reg. No.:	SMQ3568R	Date of Loss:	12/12/2019 20:00 - :59 [151 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29064665AT2 (Comprehensive) Coverage: 13/02/2019 - 12/02/2020						
Vehicle Reg. No. (Insured):	SKR5356R	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/12/2019]								
Driver/Custodian (Insured):	ONG ENG ANN (60 / Male), NRIC: S1348709Z, Tel: +6596215255 Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 13/12/19. (Manual Assign). Liab: unclear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: June Phua @ 6755 6142.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(In)
 efaxda
 16/12/19 @ 10.38am
 ✓ EST.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	600J
Vehicle Details	
Vehicle No.:	SMQ3568R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3 A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	L13A2304025
Chassis No.:	GD12382501
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$11,808.00
Original Registration Date:	23 Apr 2007
First Registration Date:	23 Apr 2007
Transfer Count:	3
Actual ARF Paid:	\$12,090.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,115.00
COE Rebate Amount:	\$11,845.00
Total Rebate Amount:	\$11,845.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Dec 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMQ3568R

TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 12/12/2019

TP Veh Reg No: SKR5356R

FAX: 62257402

Estimate No: ES1992387/YISHUN

Date: 13 Dec 2019

Policy No: 8-V0013077-MVA-R003

Veh Reg No: SMQ3568R

Make/Model: HONDA FIT 1.3 A

Chassis No: GD12382501

Engine No: L13A2304025

Reg. Date: 23/04/2007

Estimate Repair Cost to Vehicle No :SMQ3568R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT RH FENDER	375.60	1 PC	375.60	✓
2 FRONT RH FENDER LAMP	34.00	1 PC	34.00	✓
3 FRONT BUMPER	530.50	1 PC	530.50	✓
4 FRONT BUMPER RH SIDE RETAINER	13.70	1 PC	13.70	✓
5 FRONT RH DOOR	1,064.40	1 PC	1,064.40	✓
6 FRONT RH DOOR FRAME STICKER	39.80	1 SET	39.80	✓
7 FRONT RH SPORT RIM	717.20	1 PC	717.20	2800
8 FRONT RH SHOCK ABSORBER	254.40	1 PC	254.40	✓
9 FRONT RH KNUCKLE ARM	228.70	1 PC	228.70	✓
10 FRONT RH WHEEL BEARING	101.40	1 PC	101.40	✓
			3,359.70	
			Less 20%	671.94
				2,687.76
Labour				
11 REMOVE & REFIX FRT BUMPER ASSY,FRT RH FENDER,FRT RH DOOR,TRANSFER DOOR ATTACHEMENT & REALIGN THE SAME	500.00	1 LA	500.00	450/
12 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER,FRT RH DOOR,SIDE MIRROR	750.00	1 LA	750.00	650/
13 REMOVE & REFIX FRT RH UNDER CARRIAGE	150.00	1 LA	150.00	✓
14 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
15 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,520.00	1,520.00

4563.76

Total S\$ 4,207.76

Add GST @ 7% 294.54

Total Amount Payable S\$ 4,502.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMQ3568R

TP/MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 12/12/2019

TP Veh Reg No: SKR5356R

Estimate No: ES1992387/YISHUN

Date: 13 Dec 2019

Policy No: 8-V0013077-MVA-R003

Veh Reg No: SMQ3568R

Make/Model: HONDA FIT 1.3 A

Chassis No: GD12382501

Engine No: L13A2304025

Reg. Date: 23/04/2007

Estimate Repair Cost to Vehicle No :SMQ3568R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT RH FENDER	375.60	1 PC	375.60	✓
2 FRONT RH FENDER LAMP	34.00	1 PC	34.00	✓
3 FRONT BUMPER	530.50	1 PC	530.50	XX
4 FRONT BUMPER RH SIDE RETAINER	13.70	1 PC	13.70	✓
5 FRONT RH DOOR	1,064.40	1 PC	1,064.40	✓
6 FRONT RH DOOR FRAME STICKER	39.80	1 SET	39.80	✓
7 FRONT RH SPORT RIM	717.20	1 PC	717.20	2800
8 FRONT RH SHOCK ABSORBER	254.40	1 PC	254.40	XX
9 FRONT RH KNUCKLE ARM	228.70	1 PC	228.70	XX
10 FRONT RH WHEEL BEARING	101.40	1 PC	101.40	XX
2/4 head lamp	8445.00			✓
			3,359.70	
		Less 20%	671.94	2,687.76
Labour				
11 REMOVE & REFIX FRT BUMPER ASSY,FRT RH FENDER,FRT RH DOOR,TRANSFER DOOR ATTACHEMENT & REALIGN THE SAME	500.00	1 LA	500.00	450/
12 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER,FRT RH DOOR,SIDE MIRROR	750.00	1 LA	750.00	650/
13 REMOVE & REFIX FRT RH UNDER CARRIAGE	150.00	1 LA	150.00	XX
14 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
15 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,520.00	1,520.00

Parts \$1972.50
Less 20% 394.50

\$1578
280 SN

1220

\$3078

\$42450/

Total SS 4,207.76

Add GST @ 7% 294.54

Total Amount Payable SS 4,502.30

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19022070/KVF3N2
Date: 05/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29064665

Claimant Vehicle No : SMQ3568R

Insured Vehicle No : SKR5356R

Date of Loss: 12/12/2019

Nature of Claim: TP Claim No: 614525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMQ3568R
Make & Model: HONDA FIT, 1.3 (A)
Reg. Date: 23/04/2007 (Man. Year: 2007)
Colour: Metallic Silver
Engine Capacity: 1390 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

Engine No: L13A2304025
Chassis No: GD12382501
Odometer: 63855 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,043.76	1,858.00	1,185.76	38.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	1,220.00	300.00	19.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,563.76	3,078.00	1,485.76	32.56
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	4,563.76	2,450.00	2,113.76	46.32
+ GST 7.00/7.00% (S\$)	319.46	171.50	147.96	46.32
Nett Amount (S\$)	4,883.22	2,621.50	2,261.72	46.32

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 16/12/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2020)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ3568R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Bent	375.60 FL	*375.60 FL
2	1		*FRONT RH FENDER LAMP	Cracked	34.00 FL	*34.00 FL
3	1		*FRONT BUMPER	Repair	530.50 FL	*- FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	13.70 FL	*13.70 FL
5	1		*FRONT RH DOOR	Bent	1,064.40 FL	*1,064.40 FL
6	1		*SET FRONT RH DOOR FRAME STICKER	Necessary	39.80 FL	*39.80 FL
7	1		*FRONT RH SHOCK ABSORBER	Serviceable	254.40 FL	*- FL
8	1		*FRONT RH KNUCKLE ARM	Serviceable	228.70 FL	*- FL
9	1		*FRONT RH WHEEL BEARING	Serviceable	101.40 FL	*- FL
10	1		*R/H HEAD LAMP	Mtg Cracked	445.00 FL	*445.00 FL
11	1		*FRONT RH SPORT RIM	Dented	573.76 FS	*280.00 FS
					Sub Total (\$\$)	3,661.26 2,252.50
					- List Item Discount on L Items 20.00/20.00% (\$\$)	617.50 394.50
					Total Parts (\$\$)	3,043.76 1,858.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,FRT RH FENDER,FRT RH DOOR,TRANSFER DOOR ATTACHMENT & REALIGN THE SAME	New	500.00	450.00
2	PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER,FRT RH DOOR,SIDE MIRROR	New	750.00	650.00
3	REMOVE & REFIX FRT RH UNDER CARRIAGE	New	150.00	0.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,520.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >